



**DTB** Date: June 4, 2009

Order No.: S-B-83.30/74p

Supersedes: S-B-83.30/740 dated April 29, 2009

Group: 83

Revision I	Revision History					
Revision	Date	Purpose				
р	6/4/09	Warranty Information Updated				
0	4/29/09	Applicable Models (216 added) / Local Purchase and Warranty Info. Updated				
n	4/15/09	Local Purchase Information Included for Wynns Part Number				
m	3/20/09	Wynns Part Numbers Revised				
1	2/27/09	Technical Content Updated				
k	9/25/08	Applicable Models Updated (addition of 204) / Figure 1a Added				
j	10/24/07	Warranty Information Updated for Op Code 61 1072				
i	10/8/07	Model Indicators Updated for Op Code 83-1415				
h	5/30/07	Model 203 Added / Technical Content, Parts and Warranty Information Updated				
g	5/8/07	"Caution" and "Warning" Notes on Page 1 and Figure 1 Added				
f	3/5/07	Warranty Information Update				
е	2/28/07	Applicable Models, Technical Content, Parts and Warranty Information Updated				
d	3/27/06	Technical Content Updated				
С	10/26/05	Warranty Information Updated				
b	6/2/05	Technical Content Updated				
а	2/4/05	Warranty Information Updated				
-	1/31/05	Initial issue				

SUBJECT: All Model 164, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230 and 251 Vehicles
Air Conditioning Musty/Moldy Odor Complaints

Under certain environmental conditions, typically in a hot and humid climate, the vehicle may emit a musty/moldy odor from the air conditioning system. This may be more noticeable when starting the vehicle due to residual condensation on the evaporator and on the interior surface of the heater box.

If you receive customer reports in the above model vehicles regarding a musty/moldy odor from the air conditioning system, the evaporator should be cleaned using Mercedes-Benz Contra Sept and the interior using the "ultrasonic atomizer", refer to WIS document AR83.30-P-5556A. For the best lasting results, follow the instructions provided below.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.


www.startekinfo.com

- 1. Remove all filters installed in the air conditioning system. The following filter may be fitted: Pollen filter, dust filer, combination filter or active charcoal filter.
- 2. Clean evaporator with Mercedes—Benz Contra Sept as per WIS document AR83.30-P-5555T. Contra Sept is applied using a spray gun attached to a long probe. It is imperative to have as much of the evaporator sprayed with the cleaner by moving the probe in / out and up / down inside the case. It may be necessary to bend the probe in order to gain access. The cleaner is applied and allowed to dry. Refer to Figure 1a for spraying angle recommendation.

**Note:** After cleaning the evaporator, a second treatment has to be conducted. After completion of section A (ContraSept), refer to section B (Wynns).

# A. ContraSept Cleaning Procedure:

Caution! Wear safety glasses and respiratory protection when spraying cleaner.



- Spray the evaporator in a 90° angle.
- Move up and down, left and right to reach all areas of the evaporator
- Do not rotate the probe to reach other areas of the evaporator. This will change the spraying angle and the cleaning effect will diminish.

Figure 1a P-B-83.30/74k

Warning! Do not exceed the manufacturer's recommended maximum air pressure as stated on the label affixed to the pressure cup (Figure 1b). Excessive air pressure could cause the canister to explode and potentially cause personal injury. The recommended pressure to clean the evaporator effectively is 120psi.




Figure 1b P-B-83.30/74g

To reduce the possibility for this condition to reoccur, advise the owner to operate the blower at a higher speed, especially during humid conditions. For vehicles with a REST function, it also helps to use this feature during humid conditions when parking the car.

# Additional Procedures - Model 203 / 209

2

1. Equipped with ACC climate system Option Code 580 - It is necessary to drill a 15mm hole in the S-B-83.30/74p (June 4, 2009)

- climate housing to access the evaporator with the spray probe. The location for drilling the hole is described in WIS document AR83.30-P-5555-01A and Figure 1, A1 and B1.
- 2. A white foam block may be mounted to the housing between the blower motor and the main section of the case, see (Figure 2). On these housings, there is an alternate location of the hole as shown in Figure 1, A2 and B2.




Figure 1 P-B-83.30/74h Without foam block as in WIS AR83.30-P-5555-01A



Figure 2 P-B-83.30/74h

Dimension A1 = 30 mm Dimension B1 = 25 mm

With foam block

Dimension A2 = 10 mm

Dimension B2 = 15 mm

- 3. Bend the shorter of the two probes (Figure 3). Move the probe up and down as well as side to side to ensure the entire evaporator is sprayed with the cleaner. Plug hole after cleaning with seal plug A110 987 10 44 64.
- 4. Using the instructions below check the 'REHEAT' setting. It should be set to 'Anti-icing'. Control Units → Body → EIS → Control unit adaptations → Read coding and change if necessary → Climate control → Standard setting: Climate control → REHEAT mode → Change From: "Standard" to: "Anti-icing protection"
- 5. In case of customer reports that the air conditioning system is emitting a musty/moldy odor from the vents within three months after using the Mercedes-Benz Contra Sept product as described above, a Biocide coated evaporator entered production as of VIN A731368 and F634900 (203) and F144091 and T042954 (209). In this case, this part can be installed in earlier vehicles. Be sure to thoroughly clean the inside of the heater box and make sure the drain tubes are not clogged before reassembling the system.



#### Additional Procedures - Model 211

- Using the instructions below check the 'REHEAT' setting. It should be set to 'Fixed value'.
   Control Units → Air Conditioning → C-AAC, AAC → Control unit adaptations → Read coding
   and change if necessary → Workshop coding → Evaporator-Control (REHEAT mode) → Change
   From "Humidity-dependent (SERIES)" To: "Fixed value
- 2. In case of customer reports that the air conditioning system is emitting a musty/moldy odor from the vents within three months after using the Mercedes-Benz Contra Sept product as described above, a new slanted heater box bottom which allows the condensation to drain better and a coated evaporator entered production as of VIN A675828 and X171590. In this case, these parts can be installed in earlier vehicles. Be sure to thoroughly clean the inside of the heater box and make sure the drain tubes are not clogged before reassembling the system.

Note: Replacement of the heater box bottom and evaporator on the 211 and replacement of the evaporator on the 203 and 209 can only be claimed if the Mercedes-Benz Contra Sept treatment has already been performed. Dealers must claim which option was performed in the text of the claim.

### Procedure for 164 and 251

Caution! Wear safety glasses and respiratory protection when drilling hole and spraying cleaner.

- 1. Clean the evaporator with Mercedes–Benz Contra Sept as per WIS document AR83.30-P-5555T and the additional information in this document.
- 2. To clean the driver side of the evaporator, the spray probe is inserted into the hole for the evaporator temperature sensor as described in WIS document AR83.30-P-5555T, Step 4.1.
- 3. To clean the passenger side of the evaporator, the spray probe is inserted into a 15 mm hole that needs to be drilled in the climate housing as described in Steps 4 through 6.
- 4. Remove the cover below the instrument panel on the passenger side and fold carpet down. Refer to WIS document AR68.10-P-1520GZ (164) or AR68.10-P-1520RT (251).
- 5. Location of hole is shown in Figures 4 and 5. The hole should be centered in the triangular shaped section of the climate housing as shown in Figure 5.
- 6. Drill a 15mm hole in small increments using a mechanical drill stop to limit how far the drill bit penetrates the climate housing. A collar type drill stop, a piece of rubber hose or tape can be used as the drill stop.

Warning! The drill bit cannot be allowed to penetrate the housing more than 13mm or damage to the evaporator could occur. When the drill bit breaks through the housing it has a tendency to pull inward.

This is why a drill stop is necessary.





Figure 4 S-B-83.30/74k Figure 5 S-B-83.30/74k

Bending of the probe may be required to be able to spray all parts of the evaporator. Move the probe up and down as well as side to side to ensure the entire evaporator is sprayed with the

cleaner.

8 Follow the remainder of instructions in WIS document AR83.30-P-5555T. Reassemble vehicle in reverse order. Do not replace any filter back into the system!

Warning! Do not exceed the manufacturer's recommended maximum air pressure as stated on the label affixed to the pressure cup (Figure 3). Excessive air pressure could cause the canister to explode and potentially cause personal injury.

## **B.** Wynns Treatment

1. Warm up vehicle with air conditioning switched off for a minimum of 30 minutes in order to dry out the climate housing and ducts. Set the climate control to the following settings:

Blower speed 2-3

Heat to maximum

Recirculation activated

Air distribution to the footwell

All doors, windows and sliding roof closed

Note: AC compressor does not turn off immediately when the AC Off is selected at the control module. In order to ensure the compressor is off, use the following instructions:

Select AC Off

Select Climate System Off

Select Climate System On. The AC compressor will now be off.

- 2. Remove all filters installed in the climate system. This could include dust, activated charcoal or combination filters.
- 3. Close the recirculation flap for cleaning using SDS.

For 171, 204, 211, 219, 216, 221, 164 and 251 models follow path: Control Units → Air Conditioning → C-AAC, AAC → Actuations → Closing air recirculation flap for cleaning → Select recirculation.

For 203 and 209 models, follow path: Functions performed by more than one control unit  $\rightarrow$  Body  $\rightarrow$  Climate control  $\rightarrow$  Climate control  $\rightarrow$  C-AAC  $\rightarrow$  Actuations

The system will come out of recirculation when SDS is disconnected from the vehicle.

Note: This menu item is not available in SDS for all vehicles. On these vehicles, recirculation must be manually selected on the control module.

- 4. Place the Wynn's® AIRCOMATIC™ Ultrasonic Cleaning System in the passenger footwell. Insert the hose in the luggage net and orient the end of the hose to insure the output from the device is sucked into the footwell vents.
- 5. Start engine, **AC off**, press recirculation button, select lowest blower speed and set the temperature(s) to minimum.

# Note: The compressor must not be running.

- 6. Install one container of Wynn's® AIRCO-CLEAN™ in the Wynn's system.
- 7. Plug in the Wynn's system and check that it is running.
- 8. Close all doors and windows.
- 9. When the fog stops coming out of the Wynn's® system (after approximately 20 minutes), the dispersion process has been completed.
- 10. When the cleaning procedure is finished, switch engine off, turn off the Wynn's® system and leave windows and doors closed for approximately 1 hour.
- 11. Open doors and trunk lid/tailgate.
- 12. Open the air recirculation flap again if the automatic recirculation function has been deactivated by coding, and set the recirculated air function to "unimited" again.

- 13. Restart engine, switch on A/C, select the highest blower speed and set the temperature(s) to minimum.
- 14. Allow system to run for about 10 minutes. The cleaning process is now complete.
- 15. After cleaning, install new filters.
- 16. If cleaning the inteior does not remedy the complaint, please refer to the following documents: SI83.00-P-0004A and SI83.30-P-0008A.

To reduce the possibility for this condition to reoccur, advise the owner to operate the blower at a higher speed, especially during humid conditions. For vehicles with a REST function, it also helps to use this feature during humid conditions when parking the car.

#### **Parts Information**

Qty.	Part Name	Part Number
	ContraSept treatment	
1	Spray gun and probes	A000 581 00 04
1	Mercedes-Benz Contra Sept (1 liter bottle per vehicle)	A009 989 61 71
1	Spray probe , short	A000 581 00 05 *
1	Spray probe , long	A000 581 01 05 *
1	Mixer insert	A000 997 15 03 *
1	Coupling	A005 997 47 89 *
1	Flat sealing ring	A016 997 91 45 *
1	Coated evaporator (211)	A211 830 07 58
1	Heater box bottom	A211 830 22 03
1	Biocide coated evaporator (203 and 209)	A209 830 03 58
1	Seal plug for drilled hole	A110 987 10 44 64
	Wynns treatment – order through SSEP Cata	log, Section E3
1	Ultrasonic atomizer	211 – 03000
1	Interior cleaner	211 – 30208 <sup>1</sup>

<sup>\*</sup> Replacement parts for Spray gun, order only when needed

Note: The following allowable labor operations should be used when submitting a warranty claim for this repair. This information has been generated on June 4, 2009. Please refer to Netstar → Star TekInfo → Star Time for the most current labor time allowance.

### In Case of Warranty

**Operation:** Combination filter – heating / AC system, replace (83-3080)

Charcoal filter, R&R / replace if required (83-3097)

Evaporator temperature sensor – automatic A/C system, R&R/replace (after test) (83-8084)

Ventilation dust filter, R&R / replace, if required (83-3095)

A/C system Ultrasonic, cleaning (83-1415) A/C system, Contrasept, cleaning (83-0000)

Star Diagnosis system (SDS), connect & disconnect (02 4762)

Damage Code	Operation	n Number	Time (hrs.)	Mod	lel Indica	ator (s)

<sup>&</sup>lt;sup>1</sup> Part number is quantity of 12. Submit as local purchase WYNN03354, quantity of 1.

83432 65	83 3080	0.2 hrs.	T1, T2, T3, T4, T5, T6, T7, T8, T9, TA, TB, TC, U1, U2, U3, U4, U5, U6, U7, U8, Y1, Y2, Y3, Y4
		0.3 hrs.	AA, AB, AC, AD, AE, CA, CB, CC, CD, DA, DB, DC, DD, S1, S2, S3, S4, S5, S6, S7, S8, S9, SA, SB, SC, X1, X2, X3, X4, XA
If vehicle has code 581	83 3097	0.3 hrs.	P1, P2, P3, P4, P5, P6, P7, P8, P9, Q1, Q2, Q3, Q4, Q5, Q6, Q7, Q8, Q9, QA T1, T2, T3, T4, T5, T6, T7, T8, T9, TA, TB, TC, U1, U2, U3, U4, U5, U6, U7, U8
		0.7 hrs.	J1, J2, J3, M1, M2, M3, M4, M5, M6, M7, M8, M9, N1, N2, N3, N4, N5, N6
If vehicle has code 580	83 3095	0.2 hrs.	P1, P2, P3, P4, P5, P6, P7, P8, P9, Q1, Q2, Q3, Q4, Q5, Q6, Q7, Q8, Q9, QA, S1, S2, S3, S4, S5, S6, S7, S8, S9, SA, SB, T1, T2, T3, T4, T5, T6, T7, T8, T9, TA, TB, TC, U1, U2, U3, U4, U5, U6, U7, U8
		0.3 hrs.	J1, J2, J3, M1, M2, M4, M5, M6, M7, M8, M9, N1, N2, N3, N4, N5, N6, X1, X2, X3, X4
		0.4 hrs.	EA, EB, EC, ED, R1, R2, R3, R4, R5, R6, R7, Z1, Z2, Z3, Z4, Z5, Z6
		0.5 hrs.	BA, BB, BC, BD, BE, BF
	83 8084	0.2 hrs.	J1, J2, J3, M1, M2, M3, M4, M5, M6, M7, M8, M9, N1, N2, N3, N4, N5, N6, R1, R2, R3, R4, R5, R6, R7, R8, X1, X2, X3, X4
		0.3 hrs.	BA, BB, BC, BD, BE, BF, CA, CB, CC, CD, EA, EB, EC, ED, Q1, Q2, Q3, Q4, Q5, Q6, Q7, Q8, Q9, QA, T1, T2, T3, T4, T5, T6, T7, T8, T9, TA, TB, TC, U1, U2, U3, U4, U5, U6, U7, U8,XA, XB, Y1, Y2, Y3, Y4, Z1, Z2, Z3, Z4, Z5, Z6

Continued on Page 8

In Case of Warranty Damage Code	<b>Operation Number</b>	Time (hrs.)	Model Indicator (s)
	83 1415	0.4 hrs.	AA, AB, AC, AD, AE, BA, BB, BC, BD, BE,
			BF, CA, CB, CC, CD, DA, DB, DC, DD,
			EA, EB, EC, ED,J1 J2, J3, M1, M2, ,M3,
			M4, M5 M6, M7, M8, M9, N1, N2, N3, N4,
			N5, N6, P1, P2, P3, P4, P5, P6, P7, P8,
			P9, Q1, Q2, Q3, Q4, Q5, Q6, Q7, Q8, Q9,
			QA, R1, R2, R3, R4, R5, R6, R7 R8, S1,
			S2, S3, S4, S5, S6, S7, S8, S9, SA, SB,
			SC, T1 T2, T3, T4, T5, T6, T7, T8, T9, TA,
			TB, TC, U1, U2, U3, U4, U5, U6, U7,
			U8,XA X1, X2, X3 X4, XA, XB, Y1, Y2, Y3,
			Y4, Z1, Z2, Z3, Z4, Z5, Z6
	02 4762	0.2 hrs.	AA, AB, AC, AD, AE BA, BB, BC, BD, BE,
			BF, CA, CB, CC, CD, DA, DB, DC, DD,
			EA, EB, EC, ED, J1, J2, J3, M1, M2, M3,
			M4, M5, M6, M7, M8, M9, N1, N2, N3, N4,
			N5, N6, P1, P2, P3, P4, P5, P6, P7, P8,
			P9, Q1, Q2, Q3, Q4, Q5, Q6, Q7, Q8, Q9,
			QA, R1, R2, R3, R4, R5, R6, R7, R8, S1,
			S2, S3, S4, S5, S6, S7, S8, S9, SA, SB,
			SC, T1, T2, T3, T4, T5, T6, T7, T8, T9, TA,
			TB, TC, U1, U2, U3, U4, U5, U6, U7, U8,
			X1, X2, X3, X4, XA, XB, Y1, Y2, Y3, Y4,
			Z1, Z2, Z3, Z4, Z5, Z6
	83 0000	0.5 hrs. *	AA, AB, AC, AD, AE BA, BB, BC, BD, BE,
			BF, CA, CB, CC, CD, DA, DB, DC, DD,
			EA, EB, EC, ED, J1, J2, J3, M1, M2, M3,
			M4, M5, M6, M7, M8, M9, N1, N2, N3, N4,
			N5, N6, P1, P2, P3, P4, P5, P6, P7, P8,
			P9, Q1, Q2, Q3, Q4, Q5, Q6, Q7, Q8, Q9,
			QA, R1, R2, R3, R4, R5, R6, R7, R8, S1,
			S2, S3, S4, S5, S6, S7, S8, S9, SA, SB,
			SC, T1, T2, T3, T4, T5, T6, T7, T8, T9, TA,
			TB, TC, U1, U2, U3, U4, U5, U6, U7, U8,
			X1, X2, X3, X4 XA, XB, Y1, Y2, Y3, Y4,
			Z1, Z2, Z3, Z4, Z5, Z6

<sup>\*</sup> Maximum time allowed with a separate time punch. Ensure that punches are labeled as NON time.

Note: Only claim filters that are applicable to the system. Claims that are submitted with incorrect op codes will be debited.