

Model 205, 207, 212, 213, 218, 231, 238, 253 (except 253.99), 257, 290

Shown on model 253.925


- 1 Flexible coupling
- 2 Propeller shaft flange



P41.10-2439-06




1 Flexible couplings



P41.10-2312-06

Illustration shows model 213

1 Flexible couplings



P41.10-2422-06

| ⚠ Warning | Risk of injury . Moving parts can pinch, crush or, in extreme cases even sever extremities. | No parts of the body or limbs should be within the operating area of mechanical components when moving components. | AS00.00-Z-0009-01A |
|-----------|--|--|--------------------|
| | Risk of death caused by vehicle slipping or toppling off of the lifting platform. | Align vehicle between vehicle lift columns and position the four support plates at the vehicle lift support points specified by the vehicle manufacturer. | AS00.00-Z-0010-01A |
| | Preparatory activity | | |
| 1 | Lift vehicle with lifting platform. | | |
| AR | | | AR00.60-P-1006A |
| ⊴ | Check | | |
| 2 | Check flex disks (1) for crack formation, wear, damage and deformation. | If problems occur, | |
| | | ↓ | |
| | | rectify problems. | |
| | | i After obtaining special order. | |
| 3 | Check propeller shaft flange (2) for crack | Model 253 (except 253.99) | |
| | formation, wear, damage and deformation. | Model 290 with code M005 (4MATIC) | |
| | | If problems occur, | |
| | | | |
| | | v rectify problems. | |
| | | i After obtaining special order. | |
| | Finishing activity | | |
| 4 | Lower vehicle with vehicle lift. | | |
| ₩AR | | | AR00.60-P-1006A |