

---

## Switch for seat belt extender inoperative

---

Topic number	LI91.45-P-056629
Version	1
Design group	91.45 Seat belt extenders
Date	07-10-2013
Validity	Model series 207
Reason for change	

---

### Complaint:

Switch for seat belt extender inoperative.

### Cause:

Coding problem in rear control unit (N22/6).

### Remedy:

With add-on 2816 for DVD 0313 or add-on 2817 for DVD 0513 change the coding of the seat belt extenders in Xentry via menu "Adaptations --> Configuration --> Manual settings".

Please see attached pdf for details on how to determine whether to set the coding to active or inactive.

Attachments	
File	Designation
Active or Inactive.pdf	How to determine if the coding should be set to active or inactive

### Symptoms

Body / Safety system / Seat belt / Seat belt extender / Nonfunctional

Body / Safety system / Seat belt / Seat belt extender / Does not move in/out