





DTB Date: September 25, 2008

Order No.: P-B-91.10/80a

Supersedes: P-B-91.10/80 dated October 1, 2004

Group: 9'

**Revision History** 

Revision Date Purpose

a 9/25/08 Applicable Models Updated

- 10/1/04 Initial issue

SUBJECT: All Model 211 Vehicles, As of VIN A554000 or March 19, 2004 Production Date

Seat Common Structure (SCS) Memory Function or Fore/Aft Adjustment Faults

If you receive customer reports in the above model vehicles that the Seat Common Structure (SCS) front seats have either a memory function fault or moves fore/aft in short steps, the plug in the seat fore/aft adjustment motor (Figure 1) may have been connected incorrectly. This leads to a fault in the Hall sensor and may cause the normalization settings of the seat fore/aft adjustment to be lost. To correct, raise the seat completely upwards, remove plug and insert correctly (Figure 2).

## **Possible Complaints on the Driver Side:**

- Memory function of electric seat fore/aft adjustment not functioning
- Seat fore/aft adjustment with easy entry/exit feature not functioning
- Head restraint presetting (head restraint is set automatically in relation to the position of the fore/aft adjustment) not functioning
- Seat fore/aft adjustment can only be adjusted for 2 seconds with the seat adjustment switch (seat can only be adjusted in longitudinal direction with a start and stop motion)

## Possible Complaints on the Passenger Side:

- Memory function of electric seat fore/aft adjustment not functioning
- Function "Collision avoidance when folding down the rear seat backrest" not functioning (seat fails to move forward when the rear seat backrest is folded down)
- Head restraint presetting (head restraint is set automatically in relation to the position of the fore/aft adjustment) not functioning
- Seat fore/aft adjustment can only be adjusted for 2 seconds with the seat adjustment switch (seat can only be adjusted in longitudinal direction with a start and stop motion)

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

www.startekinfo.com






Figure 1 P-B-91.10/80 Figure 2 P-B-91.10/80

| Control unit  | Fault code | Fault text   |  |
|---|------------|--|--|
| ESA driver-Electric seat<br>adjustment driver (with<br>memory) (ESVF2)                | 9200 (001) | Hall sensor of component M27m1 (Forward/back motor) is faulty. FN1 |  |
| ESA passenger-Electric<br>seat adjustment front<br>passenger (with memory)<br>(ESVB2) | 9060       | No normalizing of forward/back adjustment.                         |  |
| ESA passenger-Electric<br>seat adjustment front<br>passenger (with memory)<br>(ESVB1) | 9060       | No normalizing of forward/back adjustment.                         |  |
| ESA driver-Electric seat<br>adjustment driver (with<br>memory) (ESVF2)                | 9060       | No normalizing of forward/back adjustment.                         |  |
| ESA driver-Electric seat<br>adjustment driver (with<br>memory) (ESVF1)                | 9006       | No normalizing of forward/back adjustment.                         |  |
| ESA passenger-Electric<br>seat adjustment front<br>passenger (with memory)<br>(ESVB2) | 9200       | Hall sensor of component M28m1 (Forward/back motor) is faulty.     |  |
| ESA passenger-Electric<br>seat adjustment front<br>passenger (with memory)<br>(ESVB1) | 9200       | Hall sensor of component M28m1 (Forward/back motor) is faulty.     |  |
| ESA driver-Electric seat<br>adjustment driver (with<br>memory) (ESVF1)                | 9200       | Hall sensor of component M27m1 (Forward/back motor) is faulty.     |  |
| ESA driver-Electric seat<br>adjustment driver (with<br>memory) (ESVF2)                | 9200 (002) | Hall sensor of component M27m1 (Forward/back motor) is faulty. FN2 |  |

Note: The following allowable labor operations should be used when submitting a warranty claim for this repair. This information has been generated on September 25, 2008. Please refer to Netstar → Star TekInfo → Star Time for the most current labor time allowance.

## In Case of Warranty

Short test, perform (54-1011) (can only be claimed once per RO) If necessary: Electrical line for .....(specify), repair (54-9204) Operation:

| Damage Code  | Operation Number | Time (hrs.) | Model Indicator (s)         |
|--------------|------------------|-------------|-----------------------------|
| 59317 74     | 54 1011          | 0.3 hrs.    | T1, T2, T3, T4, T5, T6, T7, |
|              |                  |             | T8, T9, TB, TC, U1, U3,     |
|              |                  |             | U4, U5, U6, U7              |
| If necessary | 54 9204          | 0.1 hrs. *  | T1, T2, T3, T4, T5, T6, T7, |
|              |                  |             | T8, T9, TB, TC, U1, U3,     |
|              |                  |             | U4, U5, U6, U7              |

<sup>\*</sup> Maximum time allowed with a separate time punch. Ensure that punches are labeled as NON time.