

# Shimming Trailing Arm

The pulling right symptom has occurred on some Gwagens in the past. After checking the basics of the system (tire pressure, alignment, and switching tires right to left \*directional tires must be dismounted off of the rim to maintain direction), the following is the next step to perform. **NOTE:** If the vehicle has a drastic pull to the right, the Right Rear trailing arm may need to be shimmed too.

1. With vehicle on a lift, support the Front axle on the right side.
2. Remove the trailing arm.
3. Install a shim (460 352 02 76) as shown in picture below.
4. Reinstall the trailing arm adhering to the torque specifications as supplied on following page.
5. Test drive vehicle for pull. If a pull to the right is still present, shim the RR trailing arm and check the pull for resolution.
6. Check and correct Toe adjustment if necessary.

