
ENGINES 642 in MODEL 164, 251

- 1 Bolts
- 2 Oil pan bottom section
- 3 Electrical connector

B1 Oil temperature sensor



P01.45-2206-06

Modification notes

| 4.8.10 | Method to install engine hoist changed | | AR33.10-P-0100-01RT |
|--------|--|--|---------------------|
|--------|--|--|---------------------|

| XX | Remove/install | | |
|-----|---|--|--|
| | Risk of death caused by vehicle slipping or toppling off of the lifting platform. | Align vehicle between columns of vehicle lift and position four support plates at vehicle lift support points specified by vehicle manufacturer. | AS00.00-Z-0010-01A |
| | Risk of injury caused by fingers being pinched or crushed when removing, installing or aligning hoods, doors, trunk lids, liftgates or sliding roof | Keep body parts and limbs well clear of moving parts. | AS00.00-Z-0011-01A |
| (1) | Notes on self-locking nuts and bolts | | AH00.00-N-0001-01A |
| 1.1 | Removes strut tower brace | Model 164.8 only Remove strut tower brace from strut tower mounts. | AR62.30-P-2500GY |
| 1.2 | Remove partition wall between wheel wells | Model 251 only | AR62.30-P-2400RT |
| 2 | Remove engine trim panel | Model 164 Model 251 | AR01.10-P-2405GZB AR01.10-P-2405RTB |
| 3 | Mount engine lifting device and attach engine | Model 164 Model 251 i Observe manufacturer's assembly specifications and safety information. Mm Model 251 gray Engine hoist | AR33.10-P-0100-01GZ AR33.10-P-0100-01RT *BA62.30-P-1008-01E *240589006100 |
| 4 | Remove oil dipstick guide tube | | AR18.40-P-3510GZB |
| 5 | Remove bottom sections of soundproofing | i Installation: Only install lower sections of soundproofing after checking for leaks. Model 164 Model 251 | AR94.30-P-5300GZ AR94.30-P-5300RT |
| 6 | Drain engine oil, collect if necessary | Nm | *BA01.45-P-1006-01Q |
| 7 | Loosen bolts on the engine mount at the front axle carrier | Mm Model 164 Nm Model 251 | *BA22.10-P-1001-03G *BA22.10-P-1001-03F |
| 8 | Disconnect electrical connector (3) from oil temperature sensor (B1) | | |
| 9 | Raise engine | | |

| 10 | Unscrew bolts (1) and take off oil pan bottom section (2) | Warm sealing surface on oil pan in order to ease detachment of the seal. Do not damage sealing surfaces while removing! Observe application of sealant to oil pan bottom section (2). | |
|----|--|---|---------------------|
| i | Notes on sealant path for oil pan | | AH01.45-P-0001-01OM |
| | | Nm | *BA01.45-P-1003-01Q |
| | | Loctite 5970 sealant | *BR00.45-Z-1013-01A |
| ₽Ž | Clean | | |
| 11 | Clean sealing surfaces | Do not use any sharp-edged tools or abrasive paper as this will damage the sealing surfaces. | AR01.00-P-0050-01A |
| | | Loctite 7200 | *BR00.45-Z-1038-04A |
| | | Loctite 7063 cleaning spray (150 ml) | *BR00.45-Z-1046-04A |
| 12 | Install in the reverse order | | |
| 13 | Check engine oil level | In order to avoid measurement errors, vehicle must be parked on an even surface. | AR18.00-P-3035-01PI |
| | | Shut off engine once it has reached operating temperature and wait approx. 5 minutes before checking engine oil level. | |
| | | With code 474 Particulate filter | *BF18.00-P-1001-01S |
| | | Without particulate filter | *BF18.00-P-1001-01A |
| | Risk of accident caused by vehicle starting off by itself when engine is running. Risk of injury caused by contusions and burns during starting procedure or when working near the engine as it is running | Secure vehicle to prevent it from moving by itself. | AS00.00-Z-0005-01A |
| 14 | Carry out engine test run | i Check leakage when engine is running. | |
| 15 | Read out fault memory and erase if necessary Connect STAR DIAGNOSIS and read out fault memory | | AD00.00-P-2000-04A |

Nm Oil pan

| Number | Designation | | | Engine 642 |
|--------------------|---|-----|----|---------------|
| BA01.45-P-1003-01Q | Oil pan bottom section to oil pan top section | M6 | Nm | 14 |
| BA01.45-P-1006-01Q | Oil drain screw to oil pan | M12 | Nm | 30 |
| | | M24 | Nm | 45 |

$\overline{^{\rm Nm}}$ Engine mount, engine support (engine side)

| Number | Designation | Model 164 |
|--------------------|---|--------------|
| BA22.10-P-1001-03G | Bolt, front engine mount to front axle carrier Nm | 53 |

$\overline{^{\rm Nm}}$ Engine mount, engine support (engine side)

| Number | Designation | Model 251 |
|--------------------|---|-----------|
| BA22.10-P-1001-03F | Bolt, front engine mount to front axle carrier Nm | 53 |


| Number | Designation | Model 251 |
|--------------------|--|--------------|
| BA62.30-P-1008-01E | Bolt for partition wall reinforcement between Nm wheel well liners to fender | 10 |

Engine lubrication system

| Number | Designation | on | | Engine 642.940/950 with particulate filter | Engine 642.820/822/870 /872 with particulate filter |
|--------------------|-------------|--|--------|--|--|
| BF18.00-P-1001-01S | Engine oil | Filling capacity (oil and filter change) | Liters | 8.5 | 8.5 |
| | | Specifications for Operating Fluids | Sheet | BB00.40-P-0228-51A | BB00.40-P-0228-51A |
| | | | Sheet | BB00.40-P-0229-31A | BB00.40-P-0229-31A |
| | | | Sheet | BB00.40-P-0229-51A | BB00.40-P-0229-51A |

Engine lubrication system

| Number | Designation | on | | Engine 642.940/950 without particulate filter | Engine 642.820/822/870 /872 without particulate filter |
|--------------------|-------------|--|--------|--|---|
| BF18.00-P-1001-01A | Engine oil | Filling capacity (oil and filter change) | Liters | 8.5 | 8.5 |
| | | Specifications for Operating Fluids | Sheet | BB00.40-P-0228-03A | BB00.40-P-0228-03A |
| | | | Sheet | BB00.40-P-0228-05A | BB00.40-P-0228-05A |
| | | | Sheet | BB00.40-P-0228-51A | BB00.40-P-0228-51A |
| | | | Sheet | BB00.40-P-0229-03A | BB00.40-P-0229-03A |
| | | | Sheet | BB00.40-P-0229-31A | BB00.40-P-0229-31A |
| | | | Sheet | BB00.40-P-0229-05A | BB00.40-P-0229-05A |
| | | | Sheet | BB00.40-P-0229-51A | BB00.40-P-0229-51A |



Engine lifting fixture

Repair materials

| Number Designation | Order number |
|--------------------|--------------|
|--------------------|--------------|

| BR00.45-Z-1013-01A | Loctite 5970 sealant | A 003 989 98 20 |
|--------------------|--------------------------------------|--|
| BR00.45-Z-1038-04A | Loctite 7200 | Henkel Loctite Deutschland GmbH Arabellastrasse 17 81925 München Germany Tel. +49 899268-0 Fax + 49 899101978 www.Loctite.de |
| BR00.45-Z-1046-04A | Loctite 7063 cleaning spray (150 ml) | A 001 986 71 71 10 |