Vehicle:07 ML320 CDI 4MATIC Customer:MONISH Operator: Date (D/M/Y):03-06-2020 _____ BENZ EN TEST 00002>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan> ECM - Engine Control Module(CDI4)>Read Fault Code: Total Number: 1 2267-1 1/1 State: Current LIN message from component 'N14/3(Glow time output stage) ' faulty Faulty message or timeout ______ BENZ EN TEST 00002>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan>IC -Instrument Cluster>Read Fault Code: Total Number: 1 9116 1/1 State: Current Control module UCP is not sending any data ______ BENZ EN TEST 00002>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan>IC -Instrument Cluster>Read Fault Code: Total Number: 1 9116 1/1 State: Current Control module UCP is not sending any data ______ BENZ EN TEST 00002>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan> AIRMATIC>Read Fault Code: Total Number: 1 5350 1/1 State: Current Check component A9/1y1(AIRmatic pressure release valve) ______ BENZ EN TEST 00002>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan> AIRMATIC>Read Fault Code: Total Number: 1 _ _ _ _ _ _ _ _ _ 5350 1/1 State: Current Check component A9/1y1(AIRmatic pressure release valve) ______ BENZ EN TEST 00002>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan>

DCM RF - Door Control Module Right Front>Read Fault Code:

Total Number : 1
9014 1/1 State: Current S85/6(Right interior CL [ZV] switch): The component remains in the switched state(contact sticking) or has Short circuit to ground
BENZ_EN_TEST_00002>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan> RevETR_LF - Left Front Reversible Emergency Tensioning Retractor>Read Fault Code: Total Number : 2
5261 1/2 State: Historic The supply voltage of the control module is too low(undervoltage)
5061 2/2 State: Historic Control module A76(Left front reversible emergency tensioning retractor) is defective
BENZ_EN_TEST_00002>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan> RevETR_RF - Right Front Reversible Emergency Tensioning Retractor>Read Fault Code: Total Number : 2
5261 1/2 State: Historic The supply voltage of the control module is too low(undervoltage)
5061 2/2 State: Historic Control module A76/1(Right front reversible emergency tensioning retractor) is defective
BENZ_EN_TEST_00002>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan> SAM_F - Signal Acquisition and Actuation Module Front>Read Fault Code: Total Number : 5
9006 1/5 State: Current Component E1e2(Left low beam) is faulty or the lead has open circuit, OR Component E1e10(Left bi-xenon lamp with integral ignition module) is faulty or the lead has open circuit
9008 2/5 State: Current Component E2e2(Right low beam) is faulty or the lead has open circuit, OR Component E2e10(Right bi-xenon lamp with integral ignition module) is faulty or the lead has open circuit
904A 3/5 State: Historic The coolant level is too low

9057 4/5 State: Current Control module N72/1(Upper control panel control module) is not sending any data
9061 5/5 State: Current Component G1/7(Auxiliary battery) is faulty or the lead has open circuit
BENZ_EN_TEST_00002>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan> SAM_R - Signal Acquisition and Actuation Module Rear>Read Fault Code: Total Number : 2
9136 1/2 State: Current Component E4e2(Right taillamp and rear fog lamp) or line to component has short circuit to ground
C331 2/2 State: Current Event: Control module N72/1(Upper control panel control module) is not sending any data
BENZ_EN_TEST_00002>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan> ESP - Electronic Stability Program>Read Fault Code: Total Number : 1
7286 1/1 State: Historic CAN signal 'N72/1s24(Downhill Speed Regulation switch) ' from control module N72/1(Upper control panel control module) is unreasonable
BENZ_EN_TEST_00002>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Manual>ISM - Intelligent Servo Module>Read Fault Code: Total Number : 2
1904 1/2 State: Current The internal mechanism in component A80(Intelligent servo module for DIRECT SELECT) for engaging selector lever position P is not in the correct position
1974 2/2 State: Current Selector lever position 'P' was engaged due to a fault occurring in component A80(Intelligent servo module for DIRECT SELECT) or in the vehicle communications