

W/X 166 – Sealing bodyshell openings Page 1-19

Date of issue: 2016.10.21 GSP/TPB I




Contents

1. BR166 - Sealing bodyshell openings




2. Replacement parts







Note: Perform task on left- and right-hand sides




Note: Perform task on left- and right-hand sides




Note: Perform task on left- and right-hand sides.



Note: Perform task on left- and right-hand sides. Adapt adhesive tape.




Note: Perform task on left-hand side. Check right-hand side (depending on equipment variant). Remove seal (black) of the plastic clip (orange) and install onto the cable strap to seal. Disconnect the cable fastening fixture from the cable harness (e.g. using side cutting pliers) and fasten with the prepared cable strap




Note: Perform task on left-hand side. Check right-hand side (depending on equipment variant). Remove seal (black) of the plastic clip (orange) and install on the cable strap to seal. Disconnect the cable fastening fixture from the cable harness (e.g. using side cutting pliers) and fasten with the prepared cable strap

Fault location A-pillar, center, inside Bodyshell holes open Bodyshell holes sealed Item number A 006 989 30 85


Note: Perform task on left- and right-hand sides. Adapt adhesive tape.



Note: Perform task on left- and right-hand sides (undo damping if necessary)



Note: Perform task on left- and right-hand sides




Bodyshell hole open




Bodyshell hole sealed




Note: Perform measure on the right-hand side for left-hand-drive vehicles.




Note: Perform task on left- and right-hand sides. Bodyshell openings may or may not be present depending on the production year.




Note: Perform task on left- and right-hand sides. (Behind cable duct)




Note: Perform task on left- and right-hand sides. Bodyshell openings may or may not be present depending on the production year. Variant X166 has one additional bodyshell opening which must also be sealed.











Note: Perform task on left- and right-hand sides. <u>Caution:</u> It must be ensured that there is no adhesive tape between the bodyshell and the seat belt holder (black). Adapt adhesive tape.








Note: Perform task on left-hand side. Two bodyshell holes are sealed with screws on vehicles with a trailer hitch. Variant X166 has one additional bodyshell opening which must also be sealed.



Note: Bodyshell opening only present on right-hand side. On variant X166, the bodyshell opening is located further forward in the direction of travel.



Note: Perform task on right-hand side. Two bodyshell holes are sealed with screws on vehicles with a trailer hitch. Variant X166 has one additional bodyshell opening which must also be sealed.