### **VEHICLE DIAGNOSTIC REPORT**



Shop Name: Watkins Auto Tel: 3375523520

Email: Watkinsauto88@gmail.com Shop Number: 1

Address: 111 Walter St, Loreauville, 70552, LA

**Technician Date&Time:** 2021-05-07 15:59:00

**Customer** information

Title 2007 Mercedes-Benz 221.171 S500(S550US) Gasoline

Year 2007 VIN: WDDNG71X87A016642

Make Mercedes-Benz Lic Plate

Model221.171 S500(S550US) GasolineOdometer Mileage161771Miles

Sub model Color

**Engine** 

#### Status

Status

### Technician notes

#### Scan report

| System   | Status          |
|--|-----------------|
| ME 9.7-Motor electronics 9.7                               | Fault   2       |
| ETC-Electronic transmission control                        | Fault   2       |
| AB-Airbag  | Pass   No Fault |
| IC-Instrument cluster                                      | Fault   1       |
| Electronic parking brake-Electric parking brake            | Fault   1       |
| CGW-Central gateway  | Pass   No Fault |
| ISM-Shift module   | Pass   No Fault |
| ABR-Adaptive Brake   | Fault   1       |
| AIRmatic   | Pass   No Fault |
| WSS-Weight sensing system                                  | Pass   No Fault |
| OCP-Overhead control panel                                 | Pass   No Fault |
| UCP-Upper control panel                                    | Pass   No Fault |
| Dr-side SAM-Driver signal acquisition and actuation module | Pass   No Fault |
| REAR SAM-Rear signal acquisition and actuation module      | Pass   No Fault |
| DCM-FL-Door control module front left                      | Pass   No Fault |
| DCM-FR-Door control module front right                     | Pass   No Fault |
| DCM-RL-Door control module rear left                       | Pass   No Fault |
| DCM-RR-Door control module rear right                      | Pass   No Fault |

www.autel.com Page 1

# VEHICLE DIAGNOSTIC REPORT AUTEL®



| ESA-FL-Electric seat adjustment front left  | Pass   No Fault |
|---|-----------------|
| ESA-FR-Electric seat adjustment front right   | Pass   No Fault |
| SCM [MRM]-Steering column module  | Fault   1       |
| RevETR-LF-Left front reversible emergency tensioning retractor                            | Pass   No Fault |
| RevETR-RF-Right front reversible emergency tensioning retractor                           | Pass   No Fault |
| ASSYST-Active Service System  | Pass   No Fault |
| ASSYST PLUS   | Pass   No Fault |
| AAC-Automatic air conditioning  | Pass   No Fault |
| System diagnosis(CAN)   | Pass   No Fault |
| COMAND  | Pass   No Fault |
| D2B-COMAND, MCS or AUDIO  | -!-             |
| Tuner-Tuner sound   | Pass   No Fault |
| VCS-Voice control   | Pass   No Fault |
| CTEL-Mobile phone adapter with universal interface  | Pass   No Fault |
| ZAN-Central display   | Pass   No Fault |
| COU [ZBE]-Central operating unit  | Pass   No Fault |
| TELE AID-Control unit   | Pass   No Fault |
| TELE AID-Telematic services Emergency call  | Pass   No Fault |
| TELE AID-Telematic services ToolInfo,Roadside assistance(USA, Canada),Tele diagnosis(ECE) | Pass   No Fault |
| TELE AID-Telematic services Stolen vehicle tracking                                       | Pass   No Fault |
| TELE AID-Telematic services Remote door unlocking,Remote door locking                     | Pass   No Fault |
|   |                 |

## DTC

| System  | Codes | Description  | Status         |
|---|-------|--|----------------|
| System  | Codes | Description  | Status         |
| ME 9.7-Motor electronics 9.7                          | 1789  | Fault exists in the control module 'Transmission' (P0730)  | Stored (Event) |
| ME 9.7-Motor electronics 9.7                          | 1433  | No CAN message is received from the control module 'N15/5 (Electronic Selector Module (ESM/EWM))' or 'A80 (Intelligent Servo Module (ISM) for Direct Select)'. | Stored (Event) |
| ETC-Electronic transmission control                   | C103  | No CAN message is received from the control module 'A80 (Intelligent Servo Module (ISM) for Direct Select)'.   | Stored (Event) |
| ETC-Electronic transmission control                   | 1709  | The actuator motor in the component 'A80 (Intelligent Servo Module (ISM) for Direct Select)' cannot reach its specified target position.                       | Stored (Event) |
| IC-Instrument cluster                                 | C020  | No CAN message is received from the control module 'Intelligent Servo Module'.   | Stored (Event) |
| Electronic parking<br>brake-Electric parking<br>brake | 5841  | No CAN message is received from the control module 'A80 (Intelligent Servo Module (ISM) for Direct Select)'.   | Stored (Event) |

Page 2 www.autel.com

# VEHICLE DIAGNOSTIC REPORT AUTEL®



| 6107 | No CAN message is received from the control module 'Engine Control Module' or 'A80 (Intelligent Servo Module (ISM) for Direct Select)'.       | Stored (Event)  |
|------|---|---|
| 9020 | Component 'Interior lamp' or wire to the component has an open or a short circuit.  | Not checked   |
| 9021 | Component 'Rear lighting' or wire to the component has an open or a short circuit.  | Not checked   |
| 9024 | Component 'Left rear reading lamp' or wire to the component has an open or a short circuit.   | Not checked   |
| 9025 | Component 'Right rear reading lamp' or wire to the component has an open or a short circuit.  | Not checked   |
| 90F0 | The obstruction sensor unit reports a fault.  | Not checked   |
| 9040 | Component 'M5/2 (Headlamp Cleaning System (HCS/SRA) pump)' has an overload or the component or the wire to the component has a short circuit. | Not checked   |
| 9045 | Component 'M5/2 (Headlamp Cleaning System (HCS/SRA) pump)' is faulty or the wire to the component has an open circuit.                        | Not checked   |
| 9131 | Hall effect sensor of component 'M24 (Rear window blind motor)' is faulty.  | Not checked   |
| 9132 | Component 'M24 (Rear window blind motor)' is blocked or has reversed polarity or has Short circuit or open circuit.                           | Not checked   |
| 900A | The mirror heater has Open circuit.   | Not checked   |
| 9367 | No CAN message is received from the control module 'Motor Electronics'.   | Stored (Event)  |
|      | 9020<br>9021<br>9024<br>9025<br>90F0<br>9040<br>9045<br>9131<br>9132<br>900A  | module 'Engine Control Module' or 'A80 (Intelligent Servo Module (ISM) for Direct Select)'.  9020 Component 'Interior lamp' or wire to the component has an open or a short circuit.  9021 Component 'Rear lighting' or wire to the component has an open or a short circuit.  9024 Component 'Left rear reading lamp' or wire to the component has an open or a short circuit.  9025 Component 'Right rear reading lamp' or wire to the component has an open or a short circuit.  90F0 The obstruction sensor unit reports a fault.  90F0 Component 'M5/2 (Headlamp Cleaning System (HCS/SRA) pump)' has an overload or the component or the wire to the component has a short circuit.  90F0 Component 'M5/2 (Headlamp Cleaning System (HCS/SRA) pump)' is faulty or the wire to the component has a short circuit.  90F0 Component 'M5/2 (Headlamp Cleaning System (HCS/SRA) pump)' is faulty or the wire to the component has an open circuit.  90F0 Component 'M24 (Rear window blind motor)' is blocked or has reversed polarity or has Short circuit or open circuit.  91F0 Component 'M24 (Rear window blind motor)' is blocked or has reversed polarity or has Short circuit or open circuit. |

Page 3 www.autel.com