



Mercedes-Benz

Campaign No. 2015120004, December 2015

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 217 (S-Coupe), 222 (S-Class), Model Years 2015, 2016**
SCN Code the Instrument Cluster Control Module

Daimler AG (DAG), the manufacturer of Mercedes-Benz vehicles, has determined that certain S- and CL-Class vehicles (222/217 platform) might not fully comply with Federal Motor Vehicle Safety Standard 101 S5.2.1, (Controls and Displays). The referenced standard requires the speed to be shown either in miles-per-hour (mph) or miles-per-hour (mph) and kilometers-per-hour (km/h). On the subject vehicles, the speedometer indicator can be set by the driver to display only the vehicle speed in either miles-per-hour or kilometers-per-hour (km/h). An authorized Mercedes-Benz dealer will SCN code the instrument cluster.

This recall affects dealer inventory only. Affected vehicles must be repaired prior to sale or lease.

Prior to performing this Recall Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Recall Campaign bulletin and follow the repair procedure exactly as described.

Please note that Recall Campaigns **do not expire** and may also be performed on a vehicle with a vehicle status indicator.






Approximately 4,755 vehicles are involved.

Order No. P-RC-2015120004

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Procedure

Note:

- Use Xentry BD 09-10-11/2015 with all associated patches or higher.
 - Follow the steps exactly as described in DAS/Xentry.
 - Connect battery charger (battery voltage  >12.5V).
 - Ensure all electrical consumers are switched-off.
 - In the event of software/SCN update issues, contact Star Diagnosis User Help Desk. Please refer to the “pre-call” check list before contacting UHD
 - Refer to Star Diagnosis System (SDS) Best Practices Guide.
1. SCN Code the Instrument Cluster Control Module: Control units view  Information and communication  IC-Instrument cluster  Control unit adaptations  SCN coding
 2. Follow on-screen instructions.

Note:

The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Operation: Connect/disconnect battery charger (02-5058)
 Star Diagnosis System (SDS), Connect/disconnect (02-4762)
 Perform SCN coding in instrument cluster control module (02-9446)

Damage Code	Operation Number	Labor Time (hrs.)
54 986 45 8	02-5058	0.1
	02-4762	0.1
	02-9446	0.1

Note

Operation Number labor times are subject to change