Conditions causing fueling station nozzle to disengaging prematurely



MBUSA Product Technical Support Support document for LI47.00-P-058235 01/24/2014




Filling station nozzle properly inserted into filler neck

To prevent the filling station nozzle from disengaging prematurely, the following preconditions must be met:

- 1. Filler neck flap sits against the flap end stop
- 2. Fuel tank venting valve is fully actuated
- 3. Tip of filling station nozzle is positioned past filler neck flap

Note: Using a nozzle with a smaller and/or softer vapor recovery boot will aid in meeting the above preconditions




Filling station nozzle improperly inserted into filler neck

Following conditions will result in the filling station nozzle disengaging prematurely:

- 1. Filler neck flap does <u>**not**</u> sit against the flap end stop
- 2. Fuel tank venting valve is **<u>not</u>** fully actuated
- 3. Tip of the filling station nozzle is **<u>not</u>** positioned past the filler neck flap

Note: More robust vapor recovery boot is more difficult to compress, increasing the chance of premature disengagement



Identifying filling station nozzles which will <u>not</u> cause premature disengagement

Different nozzle manufacturers use different length nozzles (A) as shown in pictures below

- Nozzles in photos 1 and 2 will meet all preconditions needed to prevent premature disengagement
- Nozzle in photo 3 will **<u>not</u>** meet the preconditions resulting in premature disengagement

