

CARLY DIAGNOSTICS REPORT MERCEDES E CLASS (2004)




OVERVIEW

Sep 13, 2023







CGW-Central gateway

EZS-Electronic ignition switch/KG-Keyless Go(Special equipment)

Dr-side SAM-Driver signal acquisition and actuation module


B1066 9066 Components S41 (Coolant level indicator switch) and S42 (Windshield washer fluid level indicator switch) are defective or the feed lines have Open circuit. - STORED



Pass-side SAM-Passenger-side signal acquisition and actuation module


REAR SAM-Rear signal acquisition and actuation module

OCP-Overhead control panel



BCM-Battery control module

B1050	B1050 : 9050 The component or the signal line to the component S68/12 (Right rear seatbelt buckle switch) has Short circuit to positive. / Event 9050 Fault in CAN communication with control unit EIS electronic ignition switch. / Event 9050 Control module (Instrument cluster) is not sending an data.	A1
B1051	B1051 : 9051 The component or the signal line to the component S68/12 (Right rear seatbelt buckle switch) ha Short circuit. / Event 9051 Control module N70 (Overhead control panel control unit) is not sending any data. Event 9051 No or incorrect CAN message from control unit EIS electronic ignition switch	
	S	rstem Diagnosis
B130E	930E Synchronization of the DTC memory cannot be ensured Curren and stored	t
	IC-Ins	trument cluster



CDC-CD drive

HFS-hands-free system and microphone

CTEL-car phone

DCM-FL-Door control module front left

DCM-FR-Door control module front right

B1211 9211 There is a discontinuity in the line to component M21/2r1 (Mirror heater) or the component is defective. -Current and stored

Moderate

DCM-RL-Door control module rear left

DCM-RR-Door control module rear right

TLC-Trunk lid control

ESA driver-Electric seat adjustment driver(with memory)

ESA passenger-Electric seat adjustment front passenger(with memory)

HS-Seat heater

DS-LF-Left front dynamic seat

B1180 9180 Switch S109s2 (Left front side bolsters adjustment switch) or S109s5 (Left front seat cushion fore/aft adjustment switch) does not open. -STORED

B1256	9256 Leak air at cushion of left seat - Lumbar bottom - STORED
B1260	9260 No or insufficient pressure Moderate supply Current and stored
	DSP-Pneumatic pump for dynamic seat
B1250	9250 Pressure build-up not possible due Severe to a leak Current and stored
B1254	9254 Pressure relief valve for draining opens without active overpressure run - STORED
B1310	Event 9310 The supply voltage was cut Moderate off by the vehicle power supply control module STORED

C-AAC-Convenience automatic air conditioning/AAC-Automatic air conditioning