WARRANTY REPAIRS

1st OWNER

Date	Facility	Mileage	Work Performed
8/25/2011	MB of Tacoma	8,564	Driver's side keyless inop; Replace handle and door lock tumbler
8/31/2011	MB of Tacoma	8,604	Rear spolier lifting; sub out for repair
10/20/2012	MB of Tacoma	9,000	Left rear tire losing air; nail in tire, patch
10/21/2013	MB of Col. Springs	29,885	Fuel leak/ fuel smell in interior; Fuel filter/transfer pump replaced
"	"	"	Low tire pressure light coming on; Set tire pressure, reset system
12/3/2013	MB of Col Springs	31,120	Since fuel tank repair, guage is .25 tank off; fuel level sender wire loose and repaired
1/14/2014	MB of Col Springs	32,360	Fuel leaking into cabin; Fuel pump clamp defective/ replaced
8/19/2014	MB of Col Springs	39,309	Driver's side chrome trim ring loose (work order does not specificy what trim); repaired
8/24/2014	MB of Col Springs	39,817	Left fog light trim loose; Broken shroud/replaced bezel, shroud and lens
9/10/2017	MB of Col Springs	40,189	Since trans svc, fluid leaking; Warped gasket/replaced with new bolts and added fluid
7/14/2015	MB of Col Springs	48,545	Lower control arm bushings torn; replaced bearings on both arms, spring links/installed new bushings
"	"	"	Driver's rear door handle not unlocking; **NEW OWNER PURCHASED BEFORE REPAIR MADE**

WARRANTY REPAIRS

NEW 2nd OWNER

Date	Facility	Mileage	Work Performed
8/27/2015	Park Place MB Dallas	49,821	Driver's rear door handle not working; Replace door handle at later date due to paint match
"	"	"	Car sitting too low overnight in shop (per MB service mgr); Replace airmatic valve block
10/15/2017	Park Place MB Dallas	49,854 *(dealer stated; actual mileage higher)*	Repalced door handle after paint match from above
12/18/2017	MB dealership	51,442	Updated headbolt replacement;new engine harness; 4 new camshaft position sensors; new oil level sensor; new revised lifters/tappets; oil changed 2x per MB recommendation
"	"	"	New left and right fuel sending units/gaskets
"	"	"	New airmatic distribution block and springs
"	"	"	Replace all engine and transmission mounts with new oem mounts
"	"	"	Repair and replace rear subframe; new rear air bellow/seals;
3/14/2016	MB dealership	52,121	New rear CV axle shaft; new diff fluid; new trans fluid
"	"	"	New power steering pump
"	"	"	Replaced all idler and tensioner pulleys with Weistec units (see mods); all new belts
"	"	"	New HVAC blower motor and a/c control panel operating unit; performed software update for higher air flow
"	"	"	Ambient temp readings off; replaced temp sensor in front bumber
"	"	"	Replaced rear bumper chrome strip
"	"	"	3rd oil change after headbolt replacement for good measure

WARRANTY REPAIRS

NEW 2nd OWNER

Date	Facility	Mileage	Work Performed
8/1/2016	MB dealership	54,811	Air balance from center vent stack
"	"	"	Replaced previously replaced power steering unit (other unit faulty)
"	"	"	Replace both rear struts with new
"	"	"	Repair soft opening mechanism on glove box
"	"	"	Both outside rear view mirrors replaced with new due to scratching even though invoice says decined (pd out of pocket)
"	"	"	New transmission valve body/conductor plate; transmission service included
"	"	"	Exhaust between headers and pipes readjusted and tightened
"	"	"	Driver's side door handle not working; new handle ordered and to replaced later after paint match
9/20/2016	"	54,853	Replaced driver's side door handle after paint match form visit above
"	"	"	Replaced a/c control unit from previous replacement that failed
2/22/2017	MB dealership	56,415	Re-teach new a/c control unit and stepper motor for increase volume via STAR