

Telefon:

CARSOFT Diagnosis-report

19.03.2009

Vehicle type:

License plate:

Customer:

Single diagnosis Traction - Status: ERROR !
C1174

C1160

C1161

C1024 CAN communication with EGS control module disrupted

C1162

SAM FL

Single Diagnosis SAM - Status: ERROR !

B1035

B1016

B1040

B1010 Power supply : under voltage

B1014

B1018 Control unit power supply

B1009-000 ATA: Alarm ended because off tension (<7V)

B1013

B1017 Wiper motor is not within the park position :

Telefon:
