# Fault Report - Carly for Mercedes - Version: 11.63 FVA

ID1: 6a1e3925-7e65-4b61-89fd-5a1c64867121-86d ID2: 0a8c5904-f0e1-45ef-8bde-cc89de116fa2-d2e-622a0d3042cb5758 INFO: 0E0ACFBEADA98C826C624D3D2D1D Base: C Notchback/Van - 203/ C Stufenheck/Kombi - 203 Build-Year: 2006 Faults: 10 ECUs: 7 Filter: just found Model: C Notchback/Van - 203 all/alle (MotorID=null, Parameter=0) Battery: 11.8V ADDITIONAL OBD: OFFEnhanced communication Alternative connection Optimized: 100 C 2 Date: 2018-04-14 08:21:58 OBDII Version: 23 Device: >Sony< >D6603< >D6603<

## **Motor Control:**

Motor Electronics (MB: 0024467340) Fault: Position sensor 1 for the crankshaft has an electrical fault. Code: 000703 ABS / DSC / Brake:

WSS - Weight sensing system (-)

ECU not present/no response from ECU

#### Airbag:

AB - Airbag (MB: 2038207385)

#### ECU OK, no Fault or Event Code

#### Transmission Control:

ESM - Electronic selector module (MB: 2095453332)

ECU OK, no Fault or Event Code

ETC - Electronic transmission control (MB: 0034460310)

Fault: No CAN message was received from control unit "Engine control system". No CAN message was received from control unit 'Engine control system'.

Code: 00C100

Fault: No CAN message was received from control unit "Engine control system". No CAN message was received from control unit 'Engine control system'.

Code: 00D10B

#### Instrument cluster:

ICM - Instrument cluster with maintenance interval display (MB:

NO\_HWID\_FOUND)

Event: CAN communication with the engine system is faulty. / Event: Not Relevant! Control module ME motor electronics is not sending any data. / Fault: Not Relevant! / Event: Fault in CAN communication with control unit ME motor electronics. Code: 009102

Event: Fault in CAN communication with control unit N10/8 (Rear SAM control module). / Fault: @TODO: Error reading Thesaurus-Index: 082502 / Event: Fault in CAN communication with control unit REAR SAM.

Code: 009112

Event: Fault in CAN communication with control unit SAM-F. / Event: @TODO: Error reading Thesaurus-Index: 082502 / Event: Fault in CAN communication with control module Dr-side SAM or Pass-side SAM.

Code: 009113

## Light/Rain Control:

XALWA-L - Xenon headlamp, left (-)

ECU not present/no response from ECU

XALWA-R - Xenon headlamp, right (-)

ECU not present/no response from ECU

# Heating / AC:

STH - Stationary heater with remote control (-)

ECU not present/no response from ECU

# Park distance control:

PTS - Parktronic system (-) ECU not present/no response from ECU

# Audio/Navi/Communication:

DAB - Digital radio (-)

ECU not present/no response from ECU

# COMAND or AUDIO (-)

ECU not present/no response from ECU

## SDAR - Satellite radio (-)

ECU not present/no response from ECU

## SOUND - Sound system (-)

ECU not present/no response from ECU

## UCI - Media Interface (-)

ECU not present/no response from ECU

AGW - Audio gateway (MOST network management, diagnosis gateway, radio tuner) (MB: 2038705089)

Fault: Not Relevant! No or incorrect CAN message from control unit N73 (EIS [EZS] control unit)

Code: 00D147

Fault: Not Relevant! No or incorrect CAN message from control unit N73 (EIS [EZS] control unit) No or incorrect CAN message from control unit N93 (Central gateway control unit)

Code: 00D146

## DTA - TELE AID (-)

ECU not present/no response from ECU

TELE AID - Telematic service Emergency call (-)

ECU not present/no response from ECU

TELE AID - Telematic services Remote door unlocking, Remote door locking (-)

ECU not present/no response from ECU

TELE AID - Telematic services MB Info , Roadside assistance ( USA, Canada

), Tele diagnosis ( ECE ) (-)

ECU not present/no response from ECU

TELE AID - Telematic service Stolen vehicle tracking (-)

ECU not present/no response from ECU

## Systems:

AHE - Trailer recognition (-)

ECU not present/no response from ECU

SCM [MRM] - Steering column module (MB: 2035408145)

Fault: Communication over engine CAN bus is faulty. / Fault: No CAN message was received from control unit Engine control module.

Code: 009348

Fault: Fault in CAN communication with control unit SAM. / Fault: No CAN message was received from control unit REAR SAM.

Code: 009354

System diagnosis (-)

ECU not present/no response from ECU

## NAVI - Navigation (-)

ECU not present/no response from ECU

## CGW - Central gateway (-)

ECU not present/no response from ECU

# Body:

ESA passenger - Electric seat adjustment front passenger (with memory) (-)

ECU not present/no response from ECU

ESA driver - Electric seat adjustment driver (with memory) (-)

ECU not present/no response from ECU

# Other: