

75/001	11	MERCEDES C300W				54500	54561	1646
PROD. DATE	WARR. EXP.	PROMISED	PO. NO.		PAYMENT	INV. DATE		
08OCT10	25JAN2015	15:00	11FEB15		CASH	12FEB15		
	READY	OPTIONS: SOLD-STK:L4494P DLR:17302 ENG:27294731830372 TRN:72298902848739						
	10:58	12FEB15						

					LIST	NET	TOTAL
--	--	--	--	--	------	-----	-------

A. 01 MODEL 204 MODEL YEARS 2008-2011, CHECK TAIL LAMP CARRIER, REPLACE AS NECESSARY

CAUSE: CHECK RIGHT AND LEFT BULB CARRIER FOR DAMAGE

1205 W67 (N/C)

1-09-0144 MB 5W40 SYN (N/C)

11 5w40 Form M REPLACE BULB CARRIER

1205 W67 (N/C)

04-820-15-00-05 LAMP CARRIER (N/C)

04-820-16-00-05 LAMP CARRIER (N/C)

PART 0.00 LABOR 0.00 OTHER 0.00 TOTAL LINE A: 0.00

CHECKED AND REPLACED TAIL LIGHT BULB CARRIERS

\*\*\*\*\*

B. NOTES HARD UPSHIFT FROM 4/5 ON HIGHWAY AND HARSH DOWN SHIFT AROUND TOWN OCCURS. REQUESTED TO RIDE WITH SHOP FOREMAN AT

OF DROP OFF

CAUSE: ON-BOARD POWER SUPPLY VOLTAGE MAINTAIN (WHEN CHECKING/ TESTING AND TROUBLESHOOTING)

1205 W40 (N/C)

QUICK TEST PERFORM (N/C)

1205 W40 CONTROL UNIT CODE (N/C)

AFTER QUICK TEST) (N/C)

1205 W40 CONTROL UNIT CODE (N/C)

AFTER QUICK TEST) (N/C)

1205 W40 ADAPTATION PERFORM (AFTER REPAIRS) TEST

MECHANIC: START: KM-READING AT (N/C)

1205 W40 (N/C)

DISCLAIMER

LIMITED WARRANTY

applying to the part(s) installed in accordance with this repair order offered by the manufacturer. The Seller hereby expressly disclaims any implied warranty of merchantability or fitness for a particular purpose of the seller is authorized to alter or modify in any way any disclaimer.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

MERCEDES C300W				54500	54581	1646
DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT		INVT. DATE
01CT10	25JAN2015	15:00 11FEB15		CASH		12FEB15
READY		OPTIONS: SOLD-STK:L4484P DLR:17302 ENG:27294731830372 TRN:72299802848739				
10:58 12FEB15						

W	CH	TYPE	HOURS	LIST	NET	TOTAL
		CONTROL UNIT				
		(PER QUICK TEST)				
005		W40				(N/C)
000		LABOR:	0.00	OTHER:	0.00	TOTAL LINE B: 0.00

TO TEST DRIVE THE VEHICLE WITH CLIENT, CONFIRMED AND CLIENT'S CONCERN, HARD BANGING (HARD DOWN SHIFTING) OF THE BATTERY CHARGER AND RAN SHORT TEST WITH NO FAULTS. CONTROL UNIT LOG (VGS) AND INSPECTED THE ADAPTATION AND ADAPTATIONS RIGHT AT THE MAX LIMITATIONS. SCN CODING CHECK ON VGS (NO NEW SOFTWARE AVAILABLE) TIME SON CODING. SOFTWARE UPDATE PERFORMED REQUIRED TEST DRIVE OVER NIGHT AND TRANSMISSION WITH SUCCESS. TRANSMISSION SHIFTS AND WORK NOW.

\*\*\*\*\*

CAR WASH WITH VACUUM AND TIRE SHINE (\$19.95 VALUE)						
ELEMENTARY CAR WASH WITH VACUUM AND TIRE (\$19.95 VALUE)						
021		DET				(N/C)
000		LABOR:	0.00	OTHER:	0.00	TOTAL LINE C: 0.00

\*\*\*\*\*

CLASS VEHICLE INSPECTION						
WORLD CLASS VEHICLE INSPECTION						
005		C			0.00	0.00
000		LABOR:	0.00	OTHER:	0.00	TOTAL LINE D: 0.00

\*\*\*\*\*

VEHICLE PROVIDED

Customer provided with a RBM Mercedes vehicle while in for service.

005		C			0.00	0.00
000		LABOR:	0.00	OTHER:	0.00	TOTAL LINE E: 0.00

DISCLAIMER		DESCRIPTION	TOTALS
<p>LIMITED WARRANTY</p> <p>Applying to the part(s) installed in accordance with this repair order offered by the manufacturer. The Seller hereby expressly disclaims any implied warranty of merchantability or fitness for a particular use of the seller is authorized to alter or modify in any way any repair.</p>		LABOR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		LESS	
		SALES TAX	
		PLEASE PAY THIS AMOUNT	

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	LESS	SALES TAX	PLEASE PAY THIS AMOUNT
TOTALS	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

DISCLAIMER

LIMITED WARRANTY

Applying to the part(s) installed in accordance with this repair order offered by the manufacturer. The Seller hereby expressly disclaims any implied warranty of merchantability or fitness for a particular purpose of the seller is authorized to alter or modify in any way any disclaimer.

Thank you for your business.  
 If for any reason you feel your experience was not truly exceptional, please contact our management team.

Customer Signature

ISSUES

NEONE MADE WITH

\*\*\*\*\*

RIGHT SIDE TAIL LIGHT BULB CARRIER

RIGHT ON IN INSTRUMENT CLUSTER DUE TO A MALFUNCTION OF TAIL LIGHT CAMPAIGN FOUND RIGHT TAIL LIGHT STILL THROWING

OF REPLACEMENT

LABOR: 0.00 OTHER: 0.00 TOTAL TIME: 0.00

20-16-00-05 LAMP CARRIER

(N/C)

REPLACE BULB CARRIER

message appears.

02/11/15 1:37PM After campaign 2014050001 right tail

CH TYPE HOURS LIST NET TOTAL

10:58 12FEB15

READY

OPTIONS: SOLD-STK:4494P DLR:17302 ENG:27284731630372 TRN:72289902848739

12FEB15

CASH

15:00 11FEB15

25JAN2015

DATE WARR. EXP. PROMISED P.O. NO. PAYMENT INV. DATE