Fault Report - Carly for Mercedes - Version: 11.61 FVA

ID1: deb74740-ee96-4f80-98f6-03da9da37c34-877 ID2: 76741b86-9d3f-46f6-92c2-feddb4b0c6be-d76-2746ccf15c9c632 INFO: 0200D1C5A79A947C645C4A312C11 Base: C Notchback/Van - 204/ C Stufenheck/Kombi - 204 Build-Year: 2008 Faults: 7 ECUs: 20 Filter: just found Model: C Notchback/Van - 204 all/alle (MotorID=ME97, Parameter=81) Battery: 11.9V ADDITIONAL OBD: OFFEnhanced communication Normal connection Optimized: 100 None Date: 2018-02-11 18:42:02 **Carly Adapter** Version: 24 Device: >samsung< >gts28vewifixx< >SM-T713<

Motor Control:

PTCU - Common powertrain controller (N127) (MB: NO_HWID_FOUND)
ECU not present/no response from ECU
Motor Electronics (MB: 0034467740)
Fault: Combustion misfiring has been detected.
Code: 000632
Fault: Combustion misfiring of cylinder 5 has been detected. / Fault: Combustion misfiring of cylinder 3 has been detected.
Code: 000656
Fault: Adjustment of the exhaust camshaft (cylinder bank 1) is performed late.

Code: 000060

Fault: Adjustment of the exhaust camshaft (cylinder bank 2) is performed late. Code: 000064

AMG DRVU - AMG DRIVE UNIT (N145) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

FSCU - Fuel pump (MB: 2215401701)

ECU OK, no Fault or Event Code

FSCU - Right fuel pump (N118/4) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

FSCU_EC - Control unit "Fuel pump" (N118) (MB: NO_HWID_FOUND) ECU not present/no response from ECU

SCR - Selective Catalytic Reduction (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

ABS / DSC / Brake:

DTR - Distronic (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

IRS-HRA - Outer right rear intelligent radar sensor system (B29/5) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

IRS-HLA - Outer left rear intelligent radar sensor system (B29/4) (MB: NO HWID FOUND)

ECU not present/no response from ECU

NBR-VL - Nahbereichsradar vorn links (B29/2) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

NBR-VR - Nahbereichsradar vorn rechts (B29/3) (MB: NO_HWID_FOUND) ECU not present/no response from ECU

NBR-HR - Nahbereichsradar hinten rechts (B29/7) (MB: NO_HWID_FOUND) ECU not present/no response from ECU

NBR-HL - Nahbereichsradar hinten links (B29/6) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

WSS - Weight sensing system (N110) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

SGR - Radar sensors control unit (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

Airbag:

SRS - Supplemental restraint system (N2/10) (MB: 2048208285)Fault: Belt buckle 'Front passenger' has a short circuit to positive or open circuit.Code: B1B55

Transmission Control:

ESM [EWM] - Electronic selector module (N15/5) (MB: 2045450832)

ECU OK, no Fault or Event Code

VGS4NAG2 (722.9) - Fully integrated transmission control (Y3/8n4) (MB: NO HWID FOUND)

ECU not present/no response from ECU

Instrument cluster:

IC - Instrument cluster (A1) (MB: 2045400311)

ECU OK, no Fault or Event Code

Multifunction control unit - Multifunction control unit (N26/9 - N26/14) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

OCP - Overhead control panel (N70) (MB: 2048202501)

ECU OK, no Fault or Event Code

AU - Analog clock (A70/1), LCP - Lower control panel (S77), LCP - Lower control panel 2 (S16/12), Hazard warning light system - Switch 'Hazard warning light system' (S6/1), GTO - Garage door opener (A67n2), AISP -Dimming inside rearview mirror (A67), RGLS - Rain/light sensor (B38/2), UCP - Upper control panel (N72/1), LDS - Switch 'Exterior lights' (S1), Driver-side SAM - Front signal acquisition and actuation module (N10/1) (MB: 2045455001)

ECU OK, no Fault or Event Code

Light/Rain Control:

XALWA-R - Right xenon headlamp (E2n1) (MB: NO_HWID_FOUND) ECU not present/no response from ECU

XALWA-R - Right xenon headlamp (E2n1) (MB: NO_HWID_FOUND) ECU not present/no response from ECU

LAM-SL - LED Ansteuermodul Signallicht links (E1n7) (MB:

NO_HWID_FOUND)

ECU not present/no response from ECU

LAM-SR - LED Ansteuermodul Signallicht rechts (E2n7) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

Heating / AC:

AAC - Air conditioning (N22/7) (MB: 2048308885)

ECU OK, no Fault or Event Code

STH - Stationary heater (A6n1) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

Immobilizer System: KG - KEYLESS GO (N69/5) (MB: NO_HWID_FOUND) ECU not present/no response from ECU

Park distance control:

PTS - PARKTRONIC (N62) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

PTS - PARKTRONIC (N62) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

Sunroof / Roof:

PSD - Control module "Panoramic sliding roof" (A98) (MB:

NO_HWID_FOUND)

ECU not present/no response from ECU

Audio/Navi/Communication:

SG-SOGE-AGA - Sound generator for exhaust system (N12) (MB:

NO_HWID_FOUND)

ECU not present/no response from ECU

APM - AMG Performance Media (N125/2) (MB: NO_HWID_FOUND) ECU not present/no response from ECU

ZBE - Audio/COMAND operating unit (A40/9) (MB: 2048701051)

ECU OK, no Fault or Event Code

DAB - Digital radio (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

ZAN - Audio/COMAND display (A40/8) (MB: 2048204397)

ECU OK, no Fault or Event Code

Left rear screen (MB: NO HWID FOUND) ECU not present/no response from ECU Right rear screen (MB: NO HWID FOUND) ECU not present/no response from ECU Drive Kit Plus - Drive kit for iPhone® (N123/7) (MB: NO HWID FOUND) ECU not present/no response from ECU RFK - Backup camera (N66/2) (MB: NO HWID FOUND) ECU not present/no response from ECU FU - DVD player (A40/4) (MB: NO HWID FOUND) ECU not present/no response from ECU Audio 20 / COMAND - Audio or COMAND (A2 - A40/3) (MB: 2048700389) ECU OK, no Fault or Event Code IHI - Mercedes-Benz InCar Internet (N125/3) (MB: NO HWID FOUND) ECU not present/no response from ECU MFK - Multifunction camera (A40/11) (MB: NO HWID FOUND) ECU not present/no response from ECU mbrace - mbrace (N123/4) (MB: NO HWID FOUND) ECU not present/no response from ECU SDAR - Satellite digital audio radio (N87/5) (MB: NO HWID FOUND) ECU not present/no response from ECU SOUND - Sound system (N40/3) (MB: NO HWID FOUND) ECU not present/no response from ECU 360° camera - 360°-Kamera (N148) (MB: NO HWID FOUND) ECU not present/no response from ECU TV - TV tuner (A90/1) (MB: NO HWID FOUND) ECU not present/no response from ECU MIF - Media interface (N125/1) (MB: NO HWID FOUND) ECU not present/no response from ECU DTA - TELE AID (MB: NO HWID FOUND) ECU not present/no response from ECU TELE AID - Telematic service Emergency call (MB: NO HWID FOUND) ECU not present/no response from ECU TELE AID - Telematic services Remote door unlocking, Remote door locking (MB: NO HWID FOUND)

ECU not present/no response from ECU

TELE AID - Telematic services MB Info, Roadside assistance (USA, Canada), Tele diagnosis (ECE) (MB: NO HWID FOUND)

ECU not present/no response from ECU

TELE AID - Telematic service Stolen vehicle tracking (MB:

NO_HWID_FOUND)

ECU not present/no response from ECU

Systems:

Trailer recognition module - Trailer recognition (N28/1) (MB:

NO_HWID_FOUND)

ECU not present/no response from ECU

ESP - Electronic stability program (N30/4) (MB: 2045455332)

ECU OK, no Fault or Event Code

CGW [ZGW] - Central gateway (CGW [ZGW]) (MB: 2045451101)

Fault: The front end CAN network management is unstable. _ / Fault: The chassis CAN 2 network management is unstable.

Code: 18100

ISM - Intelligent servo module (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

EHPS - Electrohydraulic power steering (A91/1) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

EZS - Electronic ignition lock (N73) (MB: 2045450908)

ECU OK, no Fault or Event Code

NAVI - Navigationsmodul (A2/30) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

HKS - Tailgate control (N121/1) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

BSN - Battery sensor (B95), AS - Alarm siren (H3/1), IRS - Interior protection and tow-away protection (N26/6), Rear SAM - Rear signal acquisition and actuation module (N10/2), SIH/SIB - Seat heater/seat ventilation (R13/1,

R13/2, M18/9, M18/10) (MB: 2045456132)

ECU OK, no Fault or Event Code

SCCM - Steering column module (N80) (MB: 2045404401)

ECU OK, no Fault or Event Code

RDK - Tire pressure monitor (N88) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

TPM - Tire pressure monitor (N88) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

Chassis:

ADS - Adaptive damping system (N51/5) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

Body:

DCU-LF - Left front door (N69/1) (MB: 2048200326)

ECU OK, no Fault or Event Code

DCU-RF - Right front door (N69/2) (MB: 2048200426)

Fault: The output for the mirror heater has a malfunction. There is an open circuit. Code: 9DD013

DCU-LR - Left rear door (N69/3) (MB: 2048200526)

ECU OK, no Fault or Event Code

DCU-RR - Right rear door (N69/4) (MB: 2048200626)

ECU OK, no Fault or Event Code

AISP - Dimming inside rearview mirror (A67) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

SBE / AKSE - Seat occupied recognition "Front passenger" (B48) (MB:

NO_HWID_FOUND)

ECU not present/no response from ECU

RevETR-LF - Left front reversible emergency tensioning retractor (A76) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

RevETR-RF - Right front reversible emergency tensioning retractor (A76/1) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

ESA "Driver" - Electric seat adjustment "Driver" (N32/1) (MB:

NO_HWID_FOUND)

ECU not present/no response from ECU

ESA "Front passenger" - Electric seat adjustment "Front passenger" (N32/2) (MB: NO_HWID_FOUND)

ECU not present/no response from ECU

Other: