

Vehicle information

Mercedes-Benz 204.054 C (204) Gasoline

VIN: WDD2040542A127099

Diagnostics time: 2021/12/23 23:48

Mileage: 224408km

Path: Auto scan >

Status report

System name	DTC counts	Status
ME-Motor Electronics (ME) 'ME97' for combustion engine 'M272'	1	Fault
VGS-Transmission control for 7-speed transmission	0	Pass
ESP-Electronic Stability Program	1	Fault
SRS-Supplemental Restraint System	0	Pass
KI-Instrument cluster	0	Pass
PTS-Parking system	0	Pass
SAMF-Front Signal Acquisition and Actuation Module (SAM)	0	Pass
SAMR-Rear Signal Acquisition and Actuation Module (SAM)	0	Pass
HLML-Left Xenon headlamp	0	Pass
HLMR-Right Xenon headlamp	0	Pass
ZGW-Central gateway	0	Pass
FSCM-Control module for fuel pump	0	Pass
TSLM-Electronic Selector Module	0	Pass
EZS-Electronic ignition lock	0	Pass
KG-Keyless Go	4	Fault
MRM-Steering Column Module	0	Pass
KLA-Air Conditioning	0	Pass
TSGVL-Left front door	0	Pass
TSGVR-Right front door	0	Pass

TSGHL-Left rear door	0	Pass
TSGHR-Right rear door	0	Pass
ESF-Electric Seat Adjustment (ESA/ESV) for driver	0	Pass
ESB-Electric Seat Adjustment (ESA/ESV) for front passenger	0	Pass
HU-Radio	0	Pass
CTRLC-Operating unit of control module 'Audio/COMAND'	0	Pass
DSPC-Audio/COMAND display	0	Pass

1. ME-Motor Electronics (ME) 'ME97' for combustion engine 'M272' — (1)

- 1.1. 0521 The charge movement flap (cylinder bank 1) is faulty.
Current and Stored

2. ESP-Electronic Stability Program — (1)

- 2.1. 5001 An internal fault exists in the component 'N30/4 (ESP control module)'.
Stored

3. KG-Keyless Go — (4)

- 3.1. 9A4A14 The Keyless Go (KG) sensor in the left front door handle is faulty. There is a short circuit to ground or an open circuit.
Current and Stored
- 3.2. 9A4C14 The Keyless Go (KG) sensor in the left rear door handle is faulty. There is a short circuit to ground or an open circuit.
Current and Stored
- 3.3. 9A4B14 The Keyless Go (KG) sensor in the right front door handle is faulty. There is a short circuit to ground or an open circuit.
Current and Stored
- 3.4. 9A4D14 The Keyless Go (KG) sensor in the right rear door handle is faulty. There is a short circuit to ground or an open circuit.
Current and Stored