







- Parts list -

Mode	MD mode	Mod. des. overview	PASSENGER CAR,SEDAN, -W- MODEL YEAR '98 UP TO IDENT NO. WDBHA33G.W F 757883.....
FIN/MD	202033	Catalog	44W
VIN		Major assembly:	
Sales designation	C 43 AMG USA	Major assembly MD	
Assortment class	Car	Group	63 - SIDE PANELS
Market	North America	Subgroup	045 - REAR FENDER

Item no.	Part number	Designation/description	Quantity	Version
5	A 202 630 01 21	REAR FENDER LESS HOLE FOR ANTENNA,LEFT	001	
5	A 202 630 03 21	REAR FENDER WITH HOLE FOR ANTENNA,LEFT	001	
5	A 202 630 02 21	REAR FENDER LESS HOLE FOR ANTENNA,RIGHT	001	
11	A 202 630 07 31	. CONSOLE LEFT,REAR BUMPER	001	
14	A 202 637 19 16	. REINFORCEMENT LEFT REAR FENDER	001	
14	A 202 637 20 16	. REINFORCEMENT RIGHT REAR FENDER	001	
17	A 202 630 00 60	. FLOOR RIGHT REAR FENDER	001	
18	A 202 637 11 09	PANELLING LEFT FRONT	001	
18	A 202 637 12 09	PANELLING RIGHT FRONT	001	
20	A 140 830 00 42	FLAP BREATHER TO REAR FENDER IN BUMPER AREA	001	
23	A 202 698 37 30	COVERING AT LEFT REAR WHEELHOUSE  [880] FROM MODEL YEAR 1998	001	
23	A 202 698 38 30	COVERING AT RIGHT REAR WHEELHOUSE  [880] FROM MODEL YEAR 1998	001	
26	A 201 990 00 50	PLASTIC NUT COVERING TO WHEELHOUSE  [880] FROM MODEL YEAR 1998	006	
29	A 001 990 12 36	SCREW COVERING TO WHEELHOUSE	004	
30	A 124 988 00 35	CAP AT LEFT REAR WHEELHOUSE	001	
31	A 124 990 04 92	EXPANSION RIVET	001	
32	A 202 750 01 06	FLAP Replaced by: A 202 750 04 06 +001 A 202 800 21 75 +001 A 202 800 01 79  [006] Up to ident. no.:	-	
32	A 202 750 04 06	FLAP FUEL FILLER NECK  [007] As of ident. no.	001	
35	A 140 758 16 36	SPRING FILLER NECK FLAP	001	
38	A 140 990 00 04	SCREW Replaced by: N 910105 006002	-	
38	N 910105 006002	HEXAGON HEAD BOLT FLAP TO RIGHT REAR FENDER	002	
41	A 123 987 24 40	RUBBER BUFFER FLAP TO RIGHT REAR FENDER	001	

44	A 210 639 01 94	HOSE TANK FILLER NECK DRAIN PIPE  [409] TO BE ADAPTED DURING ASSEMBLY	001
47	A 000 476 04 40	CLAMP FOR WATER DRAIN HOSE AT WHEELHOUSE	001
70	A 000 991 76 32	BLIND RIVET REPAIR SOLUTION FOR SPOT WELDS	NB