



Mercedes-Benz  
The best or nothing.

**star bulletin**



Date: July 8, 2011  
Order No.: S-B-07.61/89, S-B-54.21/244  
Group: 07, 54

**SUBJECT: MY-All, Models All  
Engine Control Module (N3/10) Flashing**

Do not flash the engine control module (N3/10) unless specifically instructed to do so in a technical document, such as a LI, Service Bulletin, Campaign, or Diagnostic Tree. Failure to adhere to this policy will result in rejected warranty claim or a debit. Unnecessary flashing could have an adverse effect on vehicle functionality.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Records.