



Thank you for choosing Buddy's Auto Repair & Alignment. We are happy to perform every alignment to factory specification when possible. Please note that ride disturbances existing after alignments may be caused by various factors, these include road crown/condition, tire pressure/tread life, type of tire, worn steering/suspension components etc. If your vehicle has a pull or vibration it may not be a result of our efforts to align vehicle.

Work Order: R052679  
 Last Name: Mancuso  
 License: BHD8724  
 Color: WHT  
 Year: 14  
 Technician: ES  
 Mileage: 5858  
 Date: 9/18/14 11:33 AM

Mercedes-Benz : 204 (C Class 2008-14) : without 4-MATIC : AMG Europe version/USA : M 271 EVO, OM 651 Sport Coupe (Code P84)



• One or more values are not within specification. Tire wear, handling and safety problems may result.