

MODEL 245.2## 1# up to 1.6.08
 except CODE (809) Model year 2009
 with CODE (533) Front and rear speakers -without radio-

A2 Radio



P82.60-4738-11



P82.60-5409-07

1 Cover (if installed)
 2 Accessory radio (if installed)

3 Radio recess cover
 4 Radio recess

	Removing		
	Notes on radio installation		AH82.60-P-0001-03AK
1	Switch off all electrical consumers, switch off ignition and remove transmitter key from EIS [EZS] control unit		
2	Remove cover of automatic heater control and operating unit (N18), AAC [KLA] control and operating unit (N22) or comfort AAC control and operating unit (N22/7)		AR68.20-P-2314AK
3	Remove center air vent		AR83.10-P-4503AK
4.1	Remove radio accessories (2)	In vehicles with accessory radio (2). The radio accessories (2) must be handed over to the customer.	
4.2	Remove cover (1) over radio recess cover (3)	In vehicles without accessory radio (2). The cover (1) is no longer required.	
5	Remove radio recess cover (3)	The radio recess cover (3) is no longer required. The four screws are needed for securing the new Audio 5 CD radio (A2).	
6	Remove radio recess (4)	The radio recess (4) is no longer required.	
7	Remove cover below right dashboard		AR68.10-P-1520AK
	Install		
8	Retrofit Controller Area Network (data bus/CAN Bus) (CAN) wiring harness		AN82.61-P-0001-01AKC
9	Install Audio 5 CD radio (A2)		AR82.60-P-7502AK
10	Install cover below dashboard on right		AR68.10-P-1520AK
11	Connect STAR DIAGNOSIS		AD00.00-P-2000-04A

12	Enter special equipment on the vehicle data card and the online vehicle data card	i Enter code (520) Audio 5 CD radio and delete code (533) Front and rear speakers - without radio-.	
13	Subsequently perform variant coding with STAR DIAGNOSIS	i Register new system.	
14	Close STAR DIAGNOSIS		AD00.00-P-2000-04A
15	Perform function check of radio (A2)	i See operating instructions of Audio 5 CD radio (A2).	

Parts ordering notes

Part no.	Designation	Quantity
DG 99 (see EPC)	Scope of delivery for Audio 5 CD radio	1