

Brake juddering at the rear axle

Topic number	LI42.10-P-063149
Version	1
Design group	42.10 Service brake
Date	01-21-2016
Validity	Model series 218, model designation 218.391 only, with code 494 USA
Reason for change	

Complaint:

Juddering/shuddering of the brakes at the rear axle can be felt when braking.

Cause:

Thickness fault on brake disk.

Remedy:

Note: Applies only in the event of complaint.

Replacement of brake linings and brake disks.

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 007 420 67 20			Brake lining set	1		X
A 000 423 11 12			Brake disk	2		X

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
40-1590			42201 H4	
42-2706			42201 H4	
42-2731			42201 H4	