

Brake juddering at the front axle

Topic number	LI42.10-P-063154
Version	1
Design group	42.10 Service brake
Date	01-21-2016
Validity	Model series 212 / 218 (Code 494 USA and code 951 Sport) with brake dimension 322x32 mm
Reason for change	Translation error>

Complaint:

Juddering/shuddering of the brakes at the front axle can be felt when braking.

Cause:

Thickness fault on brake disk.

Remedy:

Note: Applies only in the event of complaint.

Replacement of brake linings and brake disks.

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 007 420 75 20			Brake lining set	1		X
A 000 421 30 12			Brake disk	2		X

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
40-1590			42101 H4	
42-2706			42101 H4	
42-2731			42101 H4	