

## 2009 Mercedes-Benz CLS-Class V8, 5.5L

WDDDJ72X79A148001

### 1 HRA - Headlamp range adjustment Code

**B1086** A right headlamp component is defective.  
NOT PRESENT

### 4 OCP - Overhead control panel Codes

**B10F0** No description available  
NOT PRESENT

**B10FF** Not Relevant!

**B1068** No description available  
NOT PRESENT

**B10E1** CAN communication with control unit IC is sporadically disturbed.  
NOT PRESENT

### 1 EZS - Electronic ignition switch / KG - Keyless Go

**B1016** No description available  
NOT PRESENT

### 1 COMAND or AUDIO Code

**U1018** MOST communication has a malfunction (ring break at position 1).  
NOT PRESENT

### 3 AAC - Automatic air conditioning Codes

**B1461** A32n1 (Blower regulator) / Short circuit  
NOT PRESENT

**B1465** No description available  
NOT PRESENT

**B1460** No description available  
NOT PRESENT

### 1 UCP - Upper control panel Code

**B1003** No description available  
NOT PRESENT

### 1 RevETR-RF - Right front reversible emergency

**C1044** CAN message from control module N93 (Central gateway control unit) is faulty.  
NOT PRESENT S68/4 (Passenger-side seat belt buckle restraint systems switch)

### 5 REAR SAM - Rear signal acquisition and actuation

**B1029** No description available  
NOT PRESENT

**B1032** No description available  
NOT PRESENT

**B1057** No description available  
NOT PRESENT

**B1072** No description available  
PRESENT

**B1071** No description available  
PRESENT

### 3 Dr-side SAM - Driver signal acquisition and actuation

**B1005** No description available  
NOT PRESENT

**B1010** Component E6/1 (Left front side marker lamp USA) or lead has Short circuit to  
NOT PRESENT ground or open circuit.

**B1012** Component E6/2 (Right front side marker lamp USA) or lead has Short circuit to ground or open circuit.  
NOT PRESENT

## 1 SDAR - Satellite radio Code

**U1250** No description available  
PRESENT

## 6 AIRmatic Codes

**C1350** A9/1y1 (AIRmatic pressure release valve) : Open circuit  
NOT PRESENT

**C1356** A9/1y1 (AIRmatic pressure release valve) : Loose contact  
NOT PRESENT

**C1500** Critical vehicle level at front axle  
NOT PRESENT

**C1503** Recovery time during filling of central reservoir is too long.  
NOT PRESENT

**C1507** Suspension strut is implausible.  
NOT PRESENT

**C1508** The pressure line system leaks.  
NOT PRESENT

## 2 ESA passenger - Electric seat adjustment front

**B1060** No normalizing of forward/back adjustment.  
PRESENT

**B1200** No description available  
PRESENT

## 1 LCP - Lower control panel Code

**B1030** CAN communication is faulty.  
NOT PRESENT

## 1 UCI Code

**P1614** An internal control unit reset was performed.

NOT PRESENT

**Disclaimer:** This information is provided without warranty and is subject to the Terms of Use posted at [www.bluedriver.com/eula.html](http://www.bluedriver.com/eula.html). Reproduction of this information or any portion thereof constitutes infringement of copyright.