## **DOT Auto Safety Hotline** Vehicle Owner's Questionnaire

FOR AGENCY USE ONLY	100148				
Date Received	Repository				
15-SEP-2022	Poforonco No				

U.S. Department of Transportation			To Report Vehicle Safety Defects 1-888-DASH-2-DOT							
National Highway Traffic Safety Administration		INTER	(1-888-327-4236) RNET:www.nhtsa.dot.gov/hotline				15-SEP-2022	Reference No. 11484627		
	OWN	ER INFORMA	TION (Type or Print)					<del> </del>		
Name						Davtim	ne Telephone Number	1	Address nicholas.p@gmail.com	
Address				+				-		
City State		State	ZIP Code		Evenin	g Telephone Number				
			potential safety-related defects. We Il in accordance with the routine us							
			VEHICLE	E INFORMATION	N					
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side MAKE						Model			Model Year	
WDDDJ76X86A040184				MERCEDES BEN	ΝZ	CLS55			2006	
Data Barahara	.i	De ele de Neses	T. l l N l				Factoria		F I.T	
Date Purchased Dealer's Name		ne and Telephone Number			Engine: No: Cylinders		Fuel Type:			
Original Owne	r	Dealer's City	Winston-Salem	STATE	ZIP C	ode				
Transmission Type	Antilock Cruise (	k Brakes Control	Powertrain	Multiple Failur	e:	Incident Date(s) 15-SEP-2021				
			FAILED COMPONEN	IT(S)/PART(S) IN	IFORM	ΙΔΤΙΩΝ	<u> </u>			
Vehicle Components Code	s: 110000 ELI	ECTRICAL SYSTE		11(3)/1 ART(3) 110	II OKIV	IA II OI		Τ	5.1. 6. 1.	
vehicle components codes. Troops Electrical Statem				Failure Mileage Failure Speed 130000.0			Fallure Speed			
		A	ADDITIONAL ITEMS TO BE COMP	LETED WHEN RI	EPORT	ING A	TIRE FAILURE			
Tire Make			Tire Model (Name or Number)			Tire Size (Example P215/65R15)				
DOT No. (Example: DOTM	AL 9ABC036)		☐ Original Requirement ☐ Prior Repair	Failure Locatio	lure Location:					
Tire Component Code	re Component Code				Tire Failure Type:					
		ADD	ITIONAL ITEMS TO BE COMPLET	ED WHEN REPO	RTING	A CHI	LD SEAT FAILURE			
Make:			Date Manufactured:		Mode	del No./Name:				
Seat Type:			Installation System:							
Child Seat Component Cod	de:	Failed Part:								
			APPLICABLE IN (Please describe in detail the In	ICIDENT INFORI ncident(s), Failure(s			iury(ies).)			
Crash Yes X No	Fire Yes [2	X No	Number of Persons Injured	Number of Dea	iths	Reported to Police N				
	s leading up	to the failure,	(2) failure and its consequences, a	and (3) what was	done	to corr	ect the failure;			
and other unknown warning lights. Howe displayed. The conta was notified of the fa	2006 Merce warning lig ever, the fai act veered t ailure and in e vehicle w	des Benz CL thts were illu ilure persiste o a parking l nformed the as not diagn	S55. The contact stated that minated. The contact stated ed. Additionally, the contact s ot and turned off the vehicle contact that the vehicle contact that the manuf	that he turned stated that wh s. The contact r ld not be repa	d off a ile at r restar ired u	and reatherstone the street the s	started the vehicle severa op light, the message 'Rea e vehicle and was able to Mercedes-Benz Recall Nu	al times duced E contin imber: 2	s in order to clear the Braking Power" was aue driving. The dealer 2005110001 as the VIN	

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579. This information is requested pursuant to authority vested in the National Highway Traffic. Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.