Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin



Campaign No. 2020110017, December 2020

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model CLS-Class, E-Class, and GLE-Class (167, 213, 238, and 257 Platform)

Model Year 2019-2020

Update on-board electrical system battery control unit software

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz, has determined that on certain Model Year ("MY") 2019-2020 CLS-Class, E-Class, and GLE-Class (167, 213, 238, and 257 Platform) vehicles, the software for the on-board electrical system battery control unit does not correspond to the current series production configuration. An authorized Mercedes-Benz dealer will update the control unit software on the affected vehicles.

Prior to performing this Campaign:

- VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 388 vehicle is affected.

Order No. P-SC-2020110017

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

i Note:

- Use Xentry 6/20 with all associated patches or higher.
- Follow the steps exactly as described in Xentry.
- Connect battery charger (battery voltage >12.5V).
- · Ensure all electrical consumers are switched-off.
- In the event of software/SCN update issues, contact Star Diagnosis User Help Desk via. XSF ticket.
- Refer to Star Diagnosis System (SDS) Best Practices Guide.

Procedure

- 1. Connect XENTRY Diagnosis.
- 2. Update on-board electrical system battery control unit software.

To do this, select menu item "Quick test view G 1/3-48V on-board electrical system battery
Adaptations Control unit update Update of control unit software".
Then follow the user guidance in XENTRY Diagnosis.

Warranty Information

Operation: Connect/disconnect battery charger (02-5058)

Star Diagnosis System (SDS), Connect/disconnect (02-4762)

Update on-board electrical system battery control unit software (02-9334)

Damage Code	Operation Number	Labor Time (hrs.)
54 903 29 8	02-5058*	0.1
	02-4762*	0.1
	02-9334	0.1

^{*} Operation item may be invoiced only once for each workshop order

Li Note

Operation Number labor times are subject to change