

## Brake juddering at the front axle

|                   |   |
|-------------------|---|
| Topic number      | LI42.10-P-062555  |
| Version           | 1   |
| Design group      | 42.10 Service brake   |
| Date              | 11-06-2015  |
| Validity          | Model series 207 (code 494 USA) with brake dimensions 360x36 mm |
| Reason for change |   |

**Complaint:**

Juddering/shuddering of the brakes at the front axle can be felt when braking.

**Cause:**

Thickness of brake disk.

**Remedy:**

Note: Applies only in the event of complaint.

Replacement of brake linings and brake disks.

| Parts           |     |     |                  |          |      |     |
|-----------------|-----|-----|------------------|----------|------|-----|
| Part number     | ES1 | ES2 | Designation      | Quantity | Note | EPC |
| A 007 420 87 20 |     |     | Brake lining set | 1        |      | X   |
| A 000 421 14 12 |     |     | Brake disk       | 2        |      | X   |

| Operation numbers/damage codes |                |      |             |      |
|--------------------------------|----------------|------|-------------|------|
| Op. no.                        | Operation text | Time | Damage code | Note |
| 40-1590                        |                |      | 42101 H4    |      |
| 42-2706                        |                |      | 42101 H4    |      |
| 42-2731                        |                |      | 42101 H4    |      |