





















- Parts list -





Mode	BM mode	Market	
VIN/mod. des.	WDD2073591F211394	BM overview	E 350 BLUE EFFICIENCY
VIN	WDDKJ5KB1DF211394	Catalog	D48
Assortment class	PC	Group	82 ELECTRICAL SYSTEM
		Sub-group	310 LOUDSPEAKER



Copyright 2020-07-14 Daimler AG

Image ID: drawing_B82310000106

Item	Part number	Designation/additional information	Qty
10	A 204 820 55 02	SPEAKER LEFT DOOR  Code: 810+(803/804/805/806/807);  Fault location 82F58	1
10	A 204 820 55 02	SPEAKER RIGHT DOOR  Code: 810+(803/804/805/806/807);  Fault location 82U58	1
80	A 212 820 10 02	SPEAKER MIRROR TRIANGLE, LEFT  Code: 810;  Fault location 82G77	1
80	A 212 820 10 02	SPEAKER MIRROR TRIANGLE, RIGHT  Code: 810;  Fault location 82V77	1
100	A 172 820 07 02	SPEAKER IN INSTRUMENT PANEL  Code: 810+((359)+803/(348/350/06U)+(803/804/805/806/807));  Fault location 87037	1
150	A 204 820 55 02	SPEAKER SIDE PANELLING, LEFT  Code: (803/804/805/806/807)+810;  Fault location 82H51	1
150	A 204 820 55 02	SPEAKER SIDE PANELLING, RIGHT  Code: (803/804/805/806/807)+810;  Fault location 82W51	1
200	A 204 820 58 02	SPEAKER IN LEFT PARCEL SHELF 00041  Code: 810+-(800/801/802);  Fault location 82513	1
250	A 204 820 57 02	SPEAKER IN RIGHT PARCEL SHELF  Code: 810;  Plant information  Fault location 82513	1

Item	Part number	Designation/additional information	Qty
300	A 212 820 10 02	SPEAKER LEFT TWEETER  Code: 810;  Fault location 82G78	1
300	A 212 820 10 02	SPEAKER RIGHT TWEETER  Code: 810;  Fault location 82V78	1