

[Select Vehicle](#) | [New TSBs](#) | [Technician's Reference](#)

Component Search:

[Conversion Calculator](#)

1997 Mercedes Benz E 420 (210.072) V8-4.2L (119.985)

[Vehicle Level](#) → [Technical Service Bulletins](#) → [All Technical Service Bulletins](#) ←

## All Technical Service Bulletins

### Information

<u>Number</u>	<u>Date</u>	<u>Title</u>
<a href="#">P-32_25-19B</a>	<a href="#">05/05/2006</a>	<a href="#">Suspension - Shock Absorber/Strut Replacement Guidelines</a>
<a href="#">P-46_30-40</a>	<a href="#">04/26/2006</a>	<a href="#">Steering - Flow Noises/Fluid Foams in Reservoir</a>
<a href="#">S-54_10-162</a>	<a href="#">04/12/2006</a>	<a href="#">Electrical - Voltage Drop Testing at The Fuses</a>
<a href="#">S-98_00-13M</a>	<a href="#">03/01/2006</a>	<a href="#">Body/Paint - MBUSA Approved Refinishing Materials</a>
<a href="#">P-82_70-475</a>	<a href="#">11/14/2005</a>	<a href="#">Cell Phone - Calls Cut Off/Dropped</a>
<a href="#">2005030005</a>	<a href="#">05/01/2005</a>	<a href="#">Campaign - Door Frame Corrosion</a>
<a href="#">P-82_10-419</a>	<a href="#">12/30/2004</a>	<a href="#">Lighting - Condensation in Headlamps</a>
<a href="#">P-30_30-61</a>	<a href="#">12/30/2004</a>	<a href="#">Cruise Control Inoperative</a>
<a href="#">P-00_45-77</a>	<a href="#">02/17/2004</a>	<a href="#">Interior - Squeaking/Creaking Noise Kit</a>
<a href="#">S-01_30-15</a>	<a href="#">02/01/2004</a>	<a href="#">Engine - Cylinder Wall Damage Assesment</a>
<a href="#">S-49_10-08</a>	<a href="#">02/01/2004</a>	<a href="#">Exhaust System - Rattling/Hissing/Humming Noises</a>
<a href="#">P-40_10-43</a>	<a href="#">01/16/2004</a>	<a href="#">Tires - Michelin Pilot Sport A/S(R) Tires Not Approved</a>
<a href="#">S-18_00-16A</a>	<a href="#">12/01/2003</a>	<a href="#">Gasoline Engine - Oil Sludging</a>
<a href="#">P-82_70-222</a>	<a href="#">03/21/2003</a>	<a href="#">Cell Phone - Phone Won't Fasten Into Cradle Holder</a>
<a href="#">P-67_00-09</a>	<a href="#">03/07/2003</a>	<a href="#">Body - Windshield/Rear Glass Body Seam Corrosion</a>
<a href="#">P-80_57-20</a>	<a href="#">02/25/2003</a>	<a href="#">Audio System - RF Interference Explanation</a>
<a href="#">P-82_85-210</a>	<a href="#">11/25/2002</a>	<a href="#">Navigation/GPS System - Various Malfunctions</a>
<a href="#">P-82_85-198</a>	<a href="#">07/25/2002</a>	<a href="#">COMAND(R) System - No Sound/Whistling</a>
<a href="#">P-47_10-23</a>	<a href="#">02/06/2002</a>	<a href="#">Fuel System - MIL ON/DTC P03XX (Misfire)</a>
<a href="#">P-91_60-48</a>	<a href="#">08/09/2001</a>	<a href="#">Air Bag System - Side Impact Sensor Replacement</a>
<a href="#">P-47_31-12</a>	<a href="#">07/01/2001</a>	<a href="#">Emissions, On Board Refueling Vapor Recovery Valve</a>

<a href="#">S-00_00-072</a>	<a href="#">05/01/2001</a>	<a href="#">Emission/VIN Label - Availability</a>
<a href="#">S-05_010A</a>	<a href="#">05/01/2001</a>	<a href="#">Tools - Universal Valve Spring Tool</a>
<a href="#">S-58_091A</a>	<a href="#">05/01/2001</a>	<a href="#">Special Tool - Universal Valve Spring Tool</a>
<a href="#">S-58_20-93B</a>	<a href="#">04/01/2001</a>	<a href="#">Fender/Interior/Fascia Cover - Availability</a>
<a href="#">S-58_00-118</a>	<a href="#">03/01/2001</a>	<a href="#">Engine Oil - Approved Evacuation Equipment</a>
<a href="#">S-40_10-036</a>	<a href="#">02/01/2001</a>	<a href="#">Tires - Maintenance &amp; Inspection</a>
<a href="#">P-88_50-023</a>	<a href="#">02/01/2001</a>	<a href="#">Emergency Trunk Release - Retrofit</a>
<a href="#">1998110001</a>	<a href="#">01/01/2001</a>	<a href="#">Campaign - Brake Assist System Control Module</a>
<a href="#">2000110004</a>	<a href="#">01/01/2001</a>	<a href="#">Recall - Side Air Bag</a>
<a href="#">S-40_10-034</a>	<a href="#">12/01/2000</a>	<a href="#">Tires - High Performance Tire Storage</a>
<a href="#">S-58_094A</a>	<a href="#">12/01/2000</a>	<a href="#">Chassis/Frame - Dedicated Frame Straightener</a>
<a href="#">S-58_30-103A</a>	<a href="#">12/01/2000</a>	<a href="#">Special Tool - Resistance Spot Welder</a>
<a href="#">S-58_30-115</a>	<a href="#">12/01/2000</a>	<a href="#">Special Tool - Resistance Welder</a>
<a href="#">S-60_00-008A</a>	<a href="#">12/01/2000</a>	<a href="#">Special Tool - Spot Welder</a>
<a href="#">S-60_00-012</a>	<a href="#">12/01/2000</a>	<a href="#">Special Tool - M20 Resistance Welder</a>
<a href="#">S-60_004A</a>	<a href="#">12/01/2000</a>	<a href="#">Body/Frame - Dedicated Straightening Equipment</a>
<a href="#">00V388000</a>	<a href="#">11/21/2000</a>	<a href="#">Recall 00V388000: Air Bag Module Defect</a>
<a href="#">P-91_60-44</a>	<a href="#">10/01/2000</a>	<a href="#">Rear Door Airbag - Deactivation/Activation</a>
<a href="#">P-40_10-20P</a>	<a href="#">09/01/2000</a>	<a href="#">Tires/Snow Chains - Factory Approved Specifications</a>
<a href="#">DDAF42_10-U-6002A</a>	<a href="#">07/07/2000</a>	<a href="#">Selector Lever Blocks</a>
<a href="#">DDAF82_60-U-6008B</a>	<a href="#">07/07/2000</a>	<a href="#">Radio Inoperative</a>
<a href="#">DDAF32_20-U-1120AG</a>	<a href="#">07/06/2000</a>	<a href="#">Rumbling at Front Axle on Undulations or Poor Roads</a>
<a href="#">DDAF97_10-U-4043FU</a>	<a href="#">07/05/2000</a>	<a href="#">Ingress of Water in Luggage Compartment</a>
<a href="#">DDAF54_65-U-2000A</a>	<a href="#">07/05/2000</a>	<a href="#">PTS MIL ON For No Apparent Reason</a>
<a href="#">DDAF82_60-U-1105A</a>	<a href="#">07/05/2000</a>	<a href="#">Interference to Radio After Installing Window Screens</a>
<a href="#">DDAF91_00-U-3010Z</a>	<a href="#">06/22/2000</a>	<a href="#">Electrostatic Charge on Seats</a>
<a href="#">DDAF43_10-U-1130AG</a>	<a href="#">06/22/2000</a>	<a href="#">Brakes - Grunting Noise When Brake Pedal is Actuated</a>

<a href="#">DDAF82_10-U-2009B</a>	<a href="#">06/22/2000</a>	<a href="#">Main Beam/Low Beam Not Operating</a>
<a href="#">DDAF07_41-U-6000DA</a>	<a href="#">06/22/2000</a>	<a href="#">Engine Dies When Transmission is Put Into Gear</a>
<a href="#">DDAF54_21-U-6008A</a>	<a href="#">06/22/2000</a>	<a href="#">Operational Problem in Upper Control Panel</a>
<a href="#">S-91_40-31A</a>	<a href="#">06/01/2000</a>	<a href="#">Seat Belt - Extensions</a>
<a href="#">P-91_00-34</a>	<a href="#">05/01/2000</a>	<a href="#">Interior - Installation of Child Restraint Tether Anchor</a>
<a href="#">DDAF82_85-U-1002AG</a>	<a href="#">03/20/2000</a>	<a href="#">Tone Settings in Sound System Not Possible</a>
<a href="#">DDAH54_10-P-0001-01A</a>	<a href="#">03/17/2000</a>	<a href="#">Battery Safety Notes</a>
<a href="#">DDGF42_45-U-1000-07C</a>	<a href="#">03/17/2000</a>	<a href="#">ESP Electrical and Electronics Components Location</a>
<a href="#">DDAR54_18-P-0100-02A</a>	<a href="#">03/17/2000</a>	<a href="#">Repairing Wiring Harness Using Soldered Terminal</a>
<a href="#">DDAF82_60-U-6008A</a>	<a href="#">03/17/2000</a>	<a href="#">Radio Cannot Be Operated</a>
<a href="#">DDAF82_60-U-6700A</a>	<a href="#">03/02/2000</a>	<a href="#">Volume of ``Hands-Free'' System Too Low</a>
<a href="#">DDAF82_60-U-6009B</a>	<a href="#">03/02/2000</a>	<a href="#">Operational Problem Radio/Cassette Player</a>
<a href="#">DDAF40_10-U-2001A</a>	<a href="#">12/01/1999</a>	<a href="#">Increased Tire Wear</a>
<a href="#">DDAF46_10-U-3001AG</a>	<a href="#">12/01/1999</a>	<a href="#">Steering Stiff, Possible Noises</a>
<a href="#">DDAF27_00-U-3400A</a>	<a href="#">12/01/1999</a>	<a href="#">A/T - Delayed Engagement in Reverse and Drive When Cold</a>
<a href="#">1999080001</a>	<a href="#">12/01/1999</a>	<a href="#">Recall - Infant Restraint/Booster Seat Exchange</a>
<a href="#">DDAF91_60-U-6005A</a>	<a href="#">11/30/1999</a>	<a href="#">Airbag Control Module - DTCs B1310, B1311 Set</a>
<a href="#">S-Si-00-01-70</a>	<a href="#">10/01/1999</a>	<a href="#">Vehicle - Roadside Assistance Program</a>
<a href="#">DDAF82_10-U-2009A</a>	<a href="#">09/23/1999</a>	<a href="#">High/Low Beams Do Not Function</a>
<a href="#">DDAF07_07-U-6700AV</a>	<a href="#">09/21/1999</a>	<a href="#">Engine, Shakes, Misses, and Dies at Idle</a>
<a href="#">DDAF42_45-U-8100A</a>	<a href="#">09/03/1999</a>	<a href="#">ESP Fault Code C1401 or C1405</a>
<a href="#">DDAF54_30-U-2400A</a>	<a href="#">08/23/1999</a>	<a href="#">Digits in Display Become Darker/Not Legible</a>
<a href="#">DDAF54_21-U-6001A</a>	<a href="#">08/23/1999</a>	<a href="#">Turn Signal Lamp Occasionally Fails to Operate</a>
<a href="#">DDAF82_10-U-6010AU</a>	<a href="#">08/23/1999</a>	<a href="#">Foglamps Not Operating</a>
<a href="#">DDAF77_20-U-1200FG</a>	<a href="#">08/19/1999</a>	<a href="#">Wind Noise at Front of Tilting/Sliding Roof</a>
<a href="#">DDAF72_29-U-6000A</a>	<a href="#">08/18/1999</a>	<a href="#">Failure of Power Window Drive</a>
<a href="#">DDAF91_60-U-6090A</a>	<a href="#">08/18/1999</a>	<a href="#">Airbag ControlModule - DTCs 004, 007 Set</a>

<a href="#">DDAF88_70-U-6000A</a>	<a href="#">08/18/1999</a>	<a href="#">Operating Problem Exterior mirror</a>
<a href="#">DDAF77_20-U-6002A</a>	<a href="#">08/18/1999</a>	<a href="#">Malfunction of Electric Tilting/Sliding Roof</a>
<a href="#">DDAF83_30-U-6000A</a>	<a href="#">08/18/1999</a>	<a href="#">Occasional Air Conditioner Failure</a>
<a href="#">DDAF83_40-U-2001A</a>	<a href="#">08/18/1999</a>	<a href="#">EC Lamp ON, Cannot Be Shut OFF</a>
<a href="#">DDAF88_50-U-2003A</a>	<a href="#">08/17/1999</a>	<a href="#">Corrosion at Trunk Lid in Area of Lock Cylinder</a>
<a href="#">DDAF98_10-U-2005A</a>	<a href="#">08/17/1999</a>	<a href="#">Paint Damage to Trunk Lid in Area of Grip</a>
<a href="#">DDAF42_31-U-6001A</a>	<a href="#">05/27/1999</a>	<a href="#">Engine Does Not Start, Touch Start Inoperative</a>
<a href="#">DDGF42_45-U-1000-07C</a>	<a href="#">05/27/1999</a>	<a href="#">ESP Electrical Components Locations</a>
<a href="#">DDAF54_00-U-6000Z</a>	<a href="#">05/17/1999</a>	<a href="#">Battery Discharged/Electronic Damage - After Jump Start</a>
<a href="#">DDAF82_10-U-4041AU</a>	<a href="#">05/17/1999</a>	<a href="#">Headlamps/Turn Signals Mist Up or Leaking</a>
<a href="#">DDAF82_10-U-2008A</a>	<a href="#">05/17/1999</a>	<a href="#">Color or Brightness Difference of Headlamps</a>
<a href="#">DDAF67_30-U-6001A</a>	<a href="#">05/03/1999</a>	<a href="#">Side Window Opens After Closing</a>
<a href="#">P-91_18-39</a>	<a href="#">04/01/1999</a>	<a href="#">Interior - New Style Seat Covers Introduced</a>
<a href="#">DDAF83_25-U-6000AG</a>	<a href="#">02/26/1999</a>	<a href="#">Heater Blower is Noisy</a>
<a href="#">DDAF27_19-U-8000A</a>	<a href="#">02/09/1999</a>	<a href="#">A/T - Emergency Mode, DTCs 012, 013, 108, 109 Set</a>
<a href="#">DDAF27_10-U-6000A</a>	<a href="#">02/09/1999</a>	<a href="#">A/T - Emergency Mode DTCs 051, 055, 147, 151 Set</a>
<a href="#">DDAF82_10-U-6002A</a>	<a href="#">02/05/1999</a>	<a href="#">Short Bulb Life in Headlamps/Marker Lamps</a>
<a href="#">DDAF82_10-U-6002B</a>	<a href="#">02/05/1999</a>	<a href="#">Bulb Life Short in Headlamps/Marker Lamps</a>
<a href="#">S-58_00-043D</a>	<a href="#">02/01/1999</a>	<a href="#">Special Tools - Inventory List</a>
<a href="#">DDAF05_00-U-1300AG</a>	<a href="#">01/27/1999</a>	<a href="#">Complaint Regarding Bucket Tappet Noise</a>
<a href="#">DDAF05_10-U-1450GG</a>	<a href="#">01/27/1999</a>	<a href="#">Arrhythmic Noise at Idle, Coolant Temp. Over 40 Degrees C</a>
<a href="#">DDAF82_60-U-2000BA</a>	<a href="#">01/26/1999</a>	<a href="#">Display Flashes (All Radio Functions in Order)</a>
<a href="#">DDAF91_10-U-9000ZG</a>	<a href="#">01/25/1999</a>	<a href="#">Noises From Front Seats</a>
<a href="#">DDAF72_29-U-6001A</a>	<a href="#">01/25/1999</a>	<a href="#">Malfunction of Rear Power Windows</a>
<a href="#">DDAF72_10-U-1001AG</a>	<a href="#">01/25/1999</a>	<a href="#">Noises When Operating Front Power Windows</a>
<a href="#">DDAF68_20-U-6002A</a>	<a href="#">01/25/1999</a>	<a href="#">Mechanism of Ashtray Housing Damaged/Jamming</a>
<a href="#">DDAF33_15-U-3000A</a>	<a href="#">01/25/1999</a>	<a href="#">Vibration/Torsional Vibration at The Steering Wheel</a>

<a href="#">DDAF30_20-U-9900AG</a>	<a href="#">01/25/1999</a>	<a href="#">Engine Surges/Runs Irregularly at Idle</a>
<a href="#">DDAF98_00-U-2000A</a>	<a href="#">01/25/1999</a>	<a href="#">Deformation of Parts During Repair Paintwork</a>
<a href="#">DDAF07_41-U-2000DA</a>	<a href="#">01/22/1999</a>	<a href="#">Protective Screen on Mass Air Flow Sensor Damaged</a>
<a href="#">P-82_60-88A</a>	<a href="#">01/01/1999</a>	<a href="#">Radio - Alpine Post Warranty Repair Program</a>
<a href="#">S-82_10-115</a>	<a href="#">12/01/1998</a>	<a href="#">Lights - Daytime Running Lamps, Canadian Regulations</a>
<a href="#">P-72_10-018</a>	<a href="#">11/01/1998</a>	<a href="#">Locks - Front Door Lock Trim, Clicking Noise</a>
<a href="#">S-58_30-106</a>	<a href="#">10/01/1998</a>	<a href="#">Engine - Borescope &amp; Fiberscope Functionality</a>
<a href="#">P-72_29-017</a>	<a href="#">10/01/1998</a>	<a href="#">Windows - Power Window Lifter Assembly Components</a>
<a href="#">S-58_40-104</a>	<a href="#">10/01/1998</a>	<a href="#">Computer Control Systems - Diagnostic Analyzers</a>
<a href="#">S-SI-58_30-105</a>	<a href="#">09/01/1998</a>	<a href="#">Tools - Recall Fluke Multimeter</a>
<a href="#">P-62_20-001</a>	<a href="#">09/01/1998</a>	<a href="#">Frame - Longitudinal Member Sectioning Revision</a>
<a href="#">S-SI-40_26A</a>	<a href="#">08/01/1998</a>	<a href="#">Wheel - Balancer Adapters &amp; Flange Plate</a>
<a href="#">S-SI-58_82A</a>	<a href="#">08/01/1998</a>	<a href="#">Wheel - Balancer Adapters and Flange Plate</a>
<a href="#">P-SI-82_109</a>	<a href="#">08/01/1998</a>	<a href="#">Lights - Headlamps/Park Lamps, Short Bulb Life</a>
<a href="#">S-SI-58_99</a>	<a href="#">08/01/1998</a>	<a href="#">Fuel - Fuel Drain Hoses &amp; Portable Fuel Tanker</a>
<a href="#">P-SI-40_30A</a>	<a href="#">08/01/1998</a>	<a href="#">Suspension - New Alignment Tools and Procedures</a>
<a href="#">S-SI-58_97A</a>	<a href="#">08/01/1998</a>	<a href="#">Alignment - New Tools And Procedures</a>
<a href="#">DDAF27_00-P-0000A</a>	<a href="#">07/16/1998</a>	<a href="#">A/T 722.6 - DTC Information</a>
<a href="#">DDAF42_45-U-8101A</a>	<a href="#">07/15/1998</a>	<a href="#">ESP Fault Code C1142</a>
<a href="#">DDAF42_45-U-8102A</a>	<a href="#">07/15/1998</a>	<a href="#">ESP Fault Code C1332</a>
<a href="#">DDAF42_31-U-8000A</a>	<a href="#">07/15/1998</a>	<a href="#">Brake Assist (BAS): Fault Code C1025</a>
<a href="#">DDAF80_57-U-6401A</a>	<a href="#">07/13/1998</a>	<a href="#">Repairs for Faults of Electronic Ignition Switch</a>
<a href="#">DDAF82_60-U-6007-01A</a>	<a href="#">07/13/1998</a>	<a href="#">Test of Electronic Ignition Switch</a>
<a href="#">DDAF46_10-U-1101AG</a>	<a href="#">07/13/1998</a>	<a href="#">Clacking Noises From Impact Absorber in Steering Wheel</a>
<a href="#">DDAF82_60-U-6007-02A</a>	<a href="#">07/13/1998</a>	<a href="#">Making and Installing Auxiliary Wiring Harness</a>
<a href="#">DDAF82_60-U-6007A</a>	<a href="#">07/13/1998</a>	<a href="#">Central Locking System - Inoperative With Remote</a>
<a href="#">P-58_083B</a>	<a href="#">07/01/1998</a>	<a href="#">Body/Frame - Dedicated Fixture Set</a>

<a href="#">P-SI-07_06_02</a>	<a href="#">07/01/1998</a>	<a href="#">Powertrain - Diagnostic Trouble Code P0446</a>
<a href="#">S-SI-91_31</a>	<a href="#">06/01/1998</a>	<a href="#">Seat Belts - Extended Length Belt Order Request</a>
<a href="#">S-SI-27_33</a>	<a href="#">06/01/1998</a>	<a href="#">Policy - Warranty Form for Automatic Transmission</a>
<a href="#">P-SI-54_78</a>	<a href="#">06/01/1998</a>	<a href="#">Parktronic System - (PTS) Function</a>
<a href="#">S-SI-14_12A</a>	<a href="#">05/01/1998</a>	<a href="#">I/M Emission Testing on Dynamometer</a>
<a href="#">S-27_032</a>	<a href="#">05/01/1998</a>	<a href="#">A/T - Repair/Replacement Guidelines</a>
<a href="#">DDAF80_20-U-6100A</a>	<a href="#">04/07/1998</a>	<a href="#">Central Locking Unlocked When Driving, Dome Lamp ON</a>
<a href="#">DDAF80_20-U-4000A</a>	<a href="#">04/07/1998</a>	<a href="#">PSE System Does Not Function But Pump Runs</a>
<a href="#">S-82_108</a>	<a href="#">04/01/1998</a>	<a href="#">Cellular Phone - Diagnosis &amp; Return Form</a>
<a href="#">S-72_055</a>	<a href="#">04/01/1998</a>	<a href="#">Interior - Door Trim Panel Component Replacement</a>
<a href="#">DDAF27_00-U-3900A</a>	<a href="#">03/20/1998</a>	<a href="#">A/T - Delayed Shifts, Unexpected Shifts</a>
<a href="#">DDAF27_19-U-6700A</a>	<a href="#">03/20/1998</a>	<a href="#">A/T - Valve Body Conductor Plate Improper Installation</a>
<a href="#">DDAF27_35-U-4740A</a>	<a href="#">03/18/1998</a>	<a href="#">A/T - Oil Leak at HCU Harness Connector</a>
<a href="#">DDAF54_18-U-6402A</a>	<a href="#">03/17/1998</a>	<a href="#">MIL ON Briefly When Ignition Turned ON</a>
<a href="#">DDAF82_10-U-6001A</a>	<a href="#">03/17/1998</a>	<a href="#">Stop Lamp Mounting is Melting at Taillamp Assembly</a>
<a href="#">DDAF01_30-U-4044AU</a>	<a href="#">03/03/1998</a>	<a href="#">Engine Emits Large Quantities of Blue Smoke</a>
<a href="#">DDAF05_20-U-1400EG</a>	<a href="#">03/03/1998</a>	<a href="#">Loud Rattling Noise During Cold Start</a>
<a href="#">S-82_098</a>	<a href="#">03/01/1998</a>	<a href="#">Cellular - (Motorola) Telephone Direct Repair Program</a>
<a href="#">S-91_048A</a>	<a href="#">03/01/1998</a>	<a href="#">Airbag - Replacement Label</a>
<a href="#">DDAF40_20-U-2100A</a>	<a href="#">02/11/1998</a>	<a href="#">Vehicle Veers to Right on Level Road</a>
<a href="#">DDAF42_45-U-8000A</a>	<a href="#">02/11/1998</a>	<a href="#">Steering Angle Sensor, DTCs C1140, C1504, 015, 016, 017</a>
<a href="#">DDAF01_30-U-4043DU</a>	<a href="#">02/10/1998</a>	<a href="#">Engine Oil Leaks at Right, Formation of Droplets</a>
<a href="#">DDAF01_40-U-4041EU</a>	<a href="#">02/10/1998</a>	<a href="#">Oil Exits at Rear End Cap</a>
<a href="#">S-SI-07_5-018</a>	<a href="#">12/01/1997</a>	<a href="#">Ignition - Checking with Engine Analyzers</a>
<a href="#">S-SI-98_012B</a>	<a href="#">11/01/1997</a>	<a href="#">Paint - Warranty and Suppliers</a>
<a href="#">DDAF01_30-U-4050AU</a>	<a href="#">09/04/1997</a>	<a href="#">Blue Smoke, Oil Consumption</a>
<a href="#">S-SI-82-102</a>	<a href="#">09/01/1997</a>	<a href="#">GPS - Navigation System Installation</a>

<a href="#">00_65</a>	<a href="#">07/01/1997</a>	<a href="#">Tools - Oil Evacuation Equipment</a>
<a href="#">58_95</a>	<a href="#">07/01/1997</a>	<a href="#">Engine - Oil Evacuation Equipment</a>
<a href="#">58_093A</a>	<a href="#">06/01/1997</a>	<a href="#">Body and Frame - Console/Fender Protective Covers</a>
<a href="#">S-SI-98_013C</a>	<a href="#">06/01/1997</a>	<a href="#">Paint - Warranty and Updated Supplier Information</a>
<a href="#">DDAF15_10-U-6600A</a>	<a href="#">05/14/1997</a>	<a href="#">Engine - Hard Start, Long Cranking Time, Cuts Out</a>
<a href="#">DDAF80_20-U-4010A</a>	<a href="#">05/14/1997</a>	<a href="#">Central Locking System Inoperative Below Freezing</a>
<a href="#">DDAF01_10-U-2400AU</a>	<a href="#">05/05/1997</a>	<a href="#">Engine Smokes Excessively After Starting</a>
<a href="#">DDAF80_20-U-6094A</a>	<a href="#">05/05/1997</a>	<a href="#">Drivers Lock Inoperative From Passenger Door/Trunk</a>
<a href="#">58_046C</a>	<a href="#">05/01/1997</a>	<a href="#">Policy - Repair Summary</a>
<a href="#">58_46C</a>	<a href="#">05/01/1997</a>	<a href="#">Policy - Special Tools Repairs</a>
<a href="#">82_90A</a>	<a href="#">05/01/1997</a>	<a href="#">Cellular Phone - Installation</a>
<a href="#">82367</a>	<a href="#">05/01/1997</a>	<a href="#">Cellular Telephone (CTEL) - Installation</a>
<a href="#">82_97</a>	<a href="#">05/01/1997</a>	<a href="#">CD Changers - Parts Listing and Compatibility</a>
<a href="#">DDAF07_30-U-1000A</a>	<a href="#">04/30/1997</a>	<a href="#">Noisy Fuel Pump</a>
<a href="#">DDAF15_40-U-1000AG</a>	<a href="#">04/30/1997</a>	<a href="#">Whining Noise From Alternator</a>
<a href="#">DDAF07_30-U-6402A</a>	<a href="#">04/30/1997</a>	<a href="#">Engine is Difficult to Start When Warm</a>
<a href="#">DDAF83_30-U-1600AG</a>	<a href="#">04/29/1997</a>	<a href="#">Knocking/Humming Noise at Idle With A/C On</a>
<a href="#">DDAF83_30-U-4041A</a>	<a href="#">04/29/1997</a>	<a href="#">No A/C Cooling or Insufficient A/C Performance</a>
<a href="#">DDAF82_64-U-6006A</a>	<a href="#">04/29/1997</a>	<a href="#">Battery Discharge in CD Changer Equipped Vehicles</a>
<a href="#">DDAF91_40-U-2004A</a>	<a href="#">04/29/1997</a>	<a href="#">Seat Belt Curls Up in Upper Seat Belt Guide</a>
<a href="#">DDAF82_50-U-6001A</a>	<a href="#">04/29/1997</a>	<a href="#">Anti Theft System Cannot be Armed From Trunk/Tailgate</a>
<a href="#">DDAF72_00-U-1002AG</a>	<a href="#">04/29/1997</a>	<a href="#">Wind Noise at Doors</a>
<a href="#">DDAF91_18-U-2002A</a>	<a href="#">04/29/1997</a>	<a href="#">Dye transfer From Seat Leather to Clothing</a>
<a href="#">DDAF42_30-U-2101A</a>	<a href="#">04/28/1997</a>	<a href="#">ABS Control Lamp Comes ON Intermittently</a>
<a href="#">DDAF54_10-U-2700A</a>	<a href="#">04/28/1997</a>	<a href="#">ABS MIL ON &amp; OFF Intermittently</a>
<a href="#">DDAF54_30-U-2107A</a>	<a href="#">04/28/1997</a>	<a href="#">ABS, MIL ON No ABS System Malfunctions</a>
<a href="#">DDAF54_00-U-6002A</a>	<a href="#">04/28/1997</a>	<a href="#">Battery Discharges After Extended Inoperation</a>

<a href="#">DDAF54_21-U-6000A</a>	<a href="#">04/28/1997</a>	<a href="#">Ext. Lamp - MIL ON When Turn Signals are Used</a>
<a href="#">DDAF54_30-U-2090A</a>	<a href="#">04/28/1997</a>	<a href="#">Lamp Failure - MIL ON, NO Lamps Defective</a>
<a href="#">DDAF80_20-U-6090A</a>	<a href="#">04/28/1997</a>	<a href="#">Central Locking System Engages Without Actuation</a>
<a href="#">DDAF80_20-U-6091A</a>	<a href="#">04/28/1997</a>	<a href="#">Central Locking System Operates Without Actuation</a>
<a href="#">DDAF80_20-U-6093A</a>	<a href="#">04/28/1997</a>	<a href="#">After Repairs Central Locking System is Inoperative</a>
<a href="#">DDAF27_55-U-2440A</a>	<a href="#">04/24/1997</a>	<a href="#">Automatic Transmission Fluid in Cooling System</a>
<a href="#">DDAF27_00-U-3700A</a>	<a href="#">04/24/1997</a>	<a href="#">Delayed 2-3 Upshift After Cold Start</a>
<a href="#">DDAF18_40-U-2400A</a>	<a href="#">04/24/1997</a>	<a href="#">Low Oil Level Lamp Comes ON, Oil Level OK</a>
<a href="#">DDAF27_19-U-2000A</a>	<a href="#">04/24/1997</a>	<a href="#">Illumination of Shift Gate Is Too Dim</a>
<a href="#">DDAF83_20-U-4040AU</a>	<a href="#">2147483649/2147483648/2147485548</a>	<a href="#">Odors From ACC System in Heating Mode</a>
<a href="#">01_009B</a>	<a href="#">02/01/1997</a>	<a href="#">Engine - Adding Aluminum Sleeves to Alloy Block Revised</a>
<a href="#">20_012a</a>	<a href="#">02/01/1997</a>	<a href="#">Engine Block Heater - Procedures for Installation</a>
<a href="#">DDAF68_10-U-2001B</a>	<a href="#">01/01/1997</a>	<a href="#">Ashtray Wood Trim Color Mismatch</a>
<a href="#">05_010</a>	<a href="#">01/01/1997</a>	<a href="#">Valve Springs - Tool Kit for Removing/Installing</a>
<a href="#">58_091</a>	<a href="#">01/01/1997</a>	<a href="#">Engine - Universal Valve Spring Remover/Installer</a>
<a href="#">82_092</a>	<a href="#">12/01/1996</a>	<a href="#">Audio Systems - Diagnosis &amp; Return Form</a>
<a href="#">67_004</a>	<a href="#">12/01/1996</a>	<a href="#">Glass - Warnings/Replacement Considerations</a>
<a href="#">94_002</a>	<a href="#">12/01/1996</a>	<a href="#">Cowl Panel - Air Inlet Vibration/Noise</a>
<a href="#">58_092</a>	<a href="#">11/01/1996</a>	<a href="#">Engine - Timing Chain Tools</a>
<a href="#">80_007</a>	<a href="#">11/01/1996</a>	<a href="#">Alarm - Drive Authorization System (DAS) Changes</a>
<a href="#">DDAF27_00-U-1193AG</a>	<a href="#">11/01/1996</a>	<a href="#">Knocking Noise that Changes with Engine Load</a>
<a href="#">27_094</a>	<a href="#">10/01/1996</a>	<a href="#">TCM - Ordering Procedure</a>
<a href="#">33_033</a>	<a href="#">09/01/1996</a>	<a href="#">Front Axle Carrier - Mounting</a>
<a href="#">NHTSA99E024000</a>	<a href="#">08/02/1996</a>	<a href="#">Recall 99E024000: Child Restraint &amp; Booster Seat Defect</a>
<a href="#">82_037C</a>	<a href="#">08/01/1996</a>	<a href="#">Radio - Post Warranty Repair Procedure</a>
<a href="#">42_017</a>	<a href="#">06/01/1996</a>	<a href="#">Brakes - New Front Caliper Carrier Resolves Squeal</a>
<a href="#">83_085</a>	<a href="#">06/01/1996</a>	<a href="#">A/C - Capacities and Procedures</a>



<a href="#">00_139</a>	<a href="#">06/01/1996</a>	<a href="#">Hood Latches &amp; Hinges - Lubrication</a>
<a href="#">54_076</a>	<a href="#">05/01/1996</a>	<a href="#">ECT/VAF Sensor - Harness Repair</a>
<a href="#">46_003</a>	<a href="#">05/01/1996</a>	<a href="#">Steering - Leaks from Power Steering Pump/Reservoir</a>
<a href="#">58_087A</a>	<a href="#">04/01/1996</a>	<a href="#">Policy - Fluke Meter Approved</a>
<a href="#">58_100</a>	<a href="#">04/01/1996</a>	<a href="#">Body and Frame - Lateral Portal Frame Kit</a>
<a href="#">91_028</a>	<a href="#">04/01/1996</a>	<a href="#">SRS System - Child Safety Labels</a>
<a href="#">58_088</a>	<a href="#">04/01/1996</a>	<a href="#">Windows - Tool to Preheat Window Bonding Adhesive</a>
<a href="#">46_079</a>	<a href="#">03/01/1996</a>	<a href="#">Steering - Inspection &amp; Torque Specifications</a>
<a href="#">82_089</a>	<a href="#">03/01/1996</a>	<a href="#">Accessories - Garage Door Opener Operation</a>
<a href="#">00_064</a>	<a href="#">02/01/1996</a>	<a href="#">Mercedes Care Maintenance Plan - Introduction</a>
<a href="#">00_057A</a>	<a href="#">11/01/1995</a>	<a href="#">Engine - Oil Level Checking Procedure Revised</a>
<a href="#">27_097</a>	<a href="#">11/01/1995</a>	<a href="#">ATF &amp; Parking Lock - Cautions</a>
<a href="#">00_053</a>	<a href="#">10/01/1993</a>	<a href="#">Maintenance - Factory Approved Service Products</a>
<a href="#">DD01-82042</a>	<a href="#">04/01/1982</a>	<a href="#">External Oil Leaks</a>