

[Select Vehicle](#) | [New TSBs](#) | [Technician's Reference](#)

Component Search:

[Conversion Calculator](#)

1999 Mercedes Benz E 320 Sedan (210.065) V6-3.2L (112.941)

[Vehicle Level](#) → [Technical Service Bulletins](#) → [All Technical Service Bulletins](#) ←

## All Technical Service Bulletins

### Information

<u>Number</u>	<u>▼ Date</u>	<u>Title</u>
<a href="#">2005020003</a>	<a href="#">05/01/2005</a>	<a href="#">Campaign - Harmonic Balancer Pulley Replacement</a>
<a href="#">2005030005</a>	<a href="#">05/01/2005</a>	<a href="#">Campaign - Door Frame Corrosion</a>
<a href="#">P-32_25-19</a>	<a href="#">12/30/2004</a>	<a href="#">Suspension - Shock/Strut Replacement Guidelines</a>
<a href="#">P-82_10-419</a>	<a href="#">12/30/2004</a>	<a href="#">Lighting - Condensation in Headlamps</a>
<a href="#">P-30_30-61</a>	<a href="#">12/30/2004</a>	<a href="#">Cruise Control Inoperative</a>
<a href="#">P-00_45-77</a>	<a href="#">02/17/2004</a>	<a href="#">Interior - Squeaking/Creaking Noise Kit</a>
<a href="#">S-49_10-08</a>	<a href="#">02/01/2004</a>	<a href="#">Exhaust System - Rattling/Hissing/Humming Noises</a>
<a href="#">S-01_30-15</a>	<a href="#">02/01/2004</a>	<a href="#">Engine - Cylinder Wall Damage Assessment</a>
<a href="#">P-40_10-43</a>	<a href="#">01/16/2004</a>	<a href="#">Tires - Michelin Pilot Sport A/S(R) Tires Not Approved</a>
<a href="#">P-18_00-20</a>	<a href="#">12/05/2003</a>	<a href="#">Engine - Oil Sludging Damage/Class Action Settlement</a>
<a href="#">T-18_00-21</a>	<a href="#">12/05/2003</a>	<a href="#">Engine - Oil Sludging/Consumption Diagnosis &amp; Repair</a>
<a href="#">S-18_00-16A</a>	<a href="#">12/01/2003</a>	<a href="#">Gasoline Engine - Oil Sludging</a>
<a href="#">P-20_10-23</a>	<a href="#">05/07/2003</a>	<a href="#">Cooling System - Water Pump Leakage</a>
<a href="#">P-82_70-222</a>	<a href="#">03/21/2003</a>	<a href="#">Cell Phone - Phone Won't Fasten Into Cradle Holder</a>
<a href="#">P-67_00-09</a>	<a href="#">03/07/2003</a>	<a href="#">Body - Windshield/Rear Glass Body Seam Corrosion</a>
<a href="#">P-80_57-20</a>	<a href="#">02/25/2003</a>	<a href="#">Audio System - RF Interference Explanation</a>
<a href="#">P-82_85-210</a>	<a href="#">11/25/2002</a>	<a href="#">Navigation/GPS System - Various Malfunctions</a>
<a href="#">P-47_10-16A</a>	<a href="#">02/07/2002</a>	<a href="#">Instruments - Fuel Gauge Inaccuracy</a>
<a href="#">P-47_10-23</a>	<a href="#">02/06/2002</a>	<a href="#">Fuel System - MIL ON/DTC P03XX (Misfire)</a>
<a href="#">P-82_85-171</a>	<a href="#">09/13/2001</a>	<a href="#">COMAND(R) System - Instrument Display Not Centered</a>
<a href="#">P-82_85-170</a>	<a href="#">09/13/2001</a>	<a href="#">COMAND(R) System - Incorrect ETA Calculation Displayed</a>

<a href="#">P-80_57-11</a>	<a href="#">08/29/2001</a>	<a href="#">Ignition System - Electronic Ignition Switch Replacement</a>
<a href="#">P-18_40-14</a>	<a href="#">08/17/2001</a>	<a href="#">Engine Controls - Implausible Oil Level Messages</a>
<a href="#">P-01_00-10</a>	<a href="#">08/14/2001</a>	<a href="#">Alternator - Mounting Bolt Identification/Application</a>
<a href="#">P-91_60-48</a>	<a href="#">08/09/2001</a>	<a href="#">Air Bag System - Side Impact Sensor Replacement</a>
<a href="#">P-47_31-12</a>	<a href="#">07/01/2001</a>	<a href="#">Emissions, On Board Refueling Vapor Recovery Valve</a>
<a href="#">P-47_31-11</a>	<a href="#">07/01/2001</a>	<a href="#">Emissions - On Board Refueling Vapor Recovery Valve</a>
<a href="#">S-00_00-072</a>	<a href="#">05/01/2001</a>	<a href="#">Emission/VIN Label - Availability</a>
<a href="#">S-05_010A</a>	<a href="#">05/01/2001</a>	<a href="#">Tools - Universal Valve Spring Tool</a>
<a href="#">S-58_091A</a>	<a href="#">05/01/2001</a>	<a href="#">Special Tool - Universal Valve Spring Tool</a>
<a href="#">S-58_20-93B</a>	<a href="#">04/01/2001</a>	<a href="#">Fender/Interior/Fascia Cover - Availability</a>
<a href="#">200104001</a>	<a href="#">04/01/2001</a>	<a href="#">Recall - Replacement of Side Airbags</a>
<a href="#">200104002</a>	<a href="#">04/01/2001</a>	<a href="#">Recall - Side Airbag Replacement</a>
<a href="#">S-58_00-118</a>	<a href="#">03/01/2001</a>	<a href="#">Engine Oil - Approved Evacuation Equipment</a>
<a href="#">S-40_10-036</a>	<a href="#">02/01/2001</a>	<a href="#">Tires - Maintenance &amp; Inspection</a>
<a href="#">S-00_40-071</a>	<a href="#">02/01/2001</a>	<a href="#">Synthetic Oil Recommendations - For FFS Vehicles</a>
<a href="#">P-88_50-023</a>	<a href="#">02/01/2001</a>	<a href="#">Emergency Trunk Release - Retrofit</a>
<a href="#">1998110001</a>	<a href="#">01/01/2001</a>	<a href="#">Campaign1 - Brake Assist System Control Module</a>
<a href="#">S-40_10-034</a>	<a href="#">12/01/2000</a>	<a href="#">Tires - High Performance Tire Storage</a>
<a href="#">S-58_094A</a>	<a href="#">12/01/2000</a>	<a href="#">Chassis/Frame - Dedicated Frame Straightener</a>
<a href="#">S-58_30-103A</a>	<a href="#">12/01/2000</a>	<a href="#">Special Tool - Resistance Spot Welder</a>
<a href="#">S-58_30-115</a>	<a href="#">12/01/2000</a>	<a href="#">Special Tool - Resistance Welder</a>
<a href="#">S-60_00-008A</a>	<a href="#">12/01/2000</a>	<a href="#">Special Tool - Spot Welder</a>
<a href="#">S-60_00-012</a>	<a href="#">12/01/2000</a>	<a href="#">Special Tool - M20 Resistance Welder</a>
<a href="#">S-60_004A</a>	<a href="#">12/01/2000</a>	<a href="#">Body/Frame - Dedicated Straightening Equipment</a>
<a href="#">P-91_60-44</a>	<a href="#">10/01/2000</a>	<a href="#">Rear Door Airbag - Deactivation/Activation</a>
<a href="#">P-40_10-20P</a>	<a href="#">09/01/2000</a>	<a href="#">Tires/Snow Chains - Factory Approved Specifications</a>
<a href="#">DDAF42_10-U-6002A</a>	<a href="#">07/07/2000</a>	<a href="#">Selector Lever Blocks</a>

<a href="#">DDAF82_60-U-6008B</a>	<a href="#">07/07/2000</a>	<a href="#">Radio Inoperative</a>
<a href="#">DDAF82_85-U-6000E</a>	<a href="#">07/07/2000</a>	<a href="#">Fault in COMAND Operating and Display System</a>
<a href="#">DDAF32_20-U-1120AG</a>	<a href="#">07/06/2000</a>	<a href="#">Rumbling at Front Axle on Undulations or Poor Roads</a>
<a href="#">DDAF97_10-U-4043FU</a>	<a href="#">07/05/2000</a>	<a href="#">Ingress of Water in Luggage Compartment</a>
<a href="#">DDAF82_60-U-1105A</a>	<a href="#">07/05/2000</a>	<a href="#">Interference to Radio After Installing Window Screens</a>
<a href="#">DDAF54_65-U-2000A</a>	<a href="#">07/05/2000</a>	<a href="#">PTS MIL ON For No Apparent Reason</a>
<a href="#">DDAF91_00-U-3010Z</a>	<a href="#">06/22/2000</a>	<a href="#">Electrostatic Charge on Seats</a>
<a href="#">DDAF15_30-U-6405A</a>	<a href="#">06/22/2000</a>	<a href="#">Starter Occasionally Does Not Operate</a>
<a href="#">DDAF42_45-U-8101B</a>	<a href="#">06/22/2000</a>	<a href="#">Electronic Stability Program Fault Code C1142</a>
<a href="#">DDAF42_45-U-8103A</a>	<a href="#">06/22/2000</a>	<a href="#">ESP Fault Code C1120</a>
<a href="#">DDAF82_10-U-2009B</a>	<a href="#">06/22/2000</a>	<a href="#">Main Beam/Low Beam Not Operating</a>
<a href="#">DDAF54_21-U-6008A</a>	<a href="#">06/22/2000</a>	<a href="#">Operational Problem in Upper Control Panel</a>
<a href="#">S-91_40-31A</a>	<a href="#">06/01/2000</a>	<a href="#">Seat Belt - Extensions</a>
<a href="#">P-91_00-34</a>	<a href="#">05/01/2000</a>	<a href="#">Interior - Installation of Child Restraint Tether Anchor</a>
<a href="#">DDAF82_85-U-1002AG</a>	<a href="#">03/20/2000</a>	<a href="#">Tone Settings in Sound System Not Possible</a>
<a href="#">DDAH54_10-P-0001-01A</a>	<a href="#">03/17/2000</a>	<a href="#">Battery Safety Notes</a>
<a href="#">DDAF42_45-U-8001D</a>	<a href="#">03/17/2000</a>	<a href="#">Steering Angle Sensor - DTCs C1140 and C1504 Set</a>
<a href="#">DDAR54_18-P-0100-02A</a>	<a href="#">03/17/2000</a>	<a href="#">Repairing Wiring Harness Using Soldered Terminal</a>
<a href="#">DDAF82_60-U-6008A</a>	<a href="#">03/17/2000</a>	<a href="#">Radio Cannot Be Operated</a>
<a href="#">DDAF82_60-U-6009B</a>	<a href="#">03/02/2000</a>	<a href="#">Operational Problem Radio/Cassette Player</a>
<a href="#">DDAF82_60-U-6700A</a>	<a href="#">03/02/2000</a>	<a href="#">Volume of ``Hands-Free'' System Too Low</a>
<a href="#">DDAF40_10-U-2001A</a>	<a href="#">12/01/1999</a>	<a href="#">Increased Tire Wear</a>
<a href="#">DDAF46_10-U-3001AG</a>	<a href="#">12/01/1999</a>	<a href="#">Steering Stiff, Possible Noises</a>
<a href="#">1999080001</a>	<a href="#">12/01/1999</a>	<a href="#">Recall - Infant Restraint/Booster Seat Exchange</a>
<a href="#">DDAF91_60-U-6005A</a>	<a href="#">11/30/1999</a>	<a href="#">Airbag Control Module - DTCs B1310, B1311 Set</a>
<a href="#">DDAF54_20-U-6700A</a>	<a href="#">11/04/1999</a>	<a href="#">Electric Suction Fan Runs All The Time, Ignition OFF</a>
<a href="#">S-Si-00-01-70</a>	<a href="#">10/01/1999</a>	<a href="#">Vehicle - Roadside Assistance Program</a>

<a href="#">DDAF82_10-U-2009A</a>	<a href="#">09/23/1999</a>	<a href="#">High/Low Beams Do Not Function</a>
<a href="#">DDAF07_07-U-6700AV</a>	<a href="#">09/21/1999</a>	<a href="#">Engine, Shakes, Misses, and Dies at Idle</a>
<a href="#">DDAF42_45-U-6200A</a>	<a href="#">09/03/1999</a>	<a href="#">ESP Reacts Too Sensitive at Low Speed Tight Curves</a>
<a href="#">DDAF42_45-U-8100A</a>	<a href="#">09/03/1999</a>	<a href="#">ESP Fault Code C1401 or C1405</a>
<a href="#">DDAF54_30-U-2400A</a>	<a href="#">08/23/1999</a>	<a href="#">Digits in Display Become Darker/Not Legible</a>
<a href="#">DDAF54_21-U-6001A</a>	<a href="#">08/23/1999</a>	<a href="#">Turn Signal Lamp Occasionally Fails to Operate</a>
<a href="#">DDAF82_10-U-6010AU</a>	<a href="#">08/23/1999</a>	<a href="#">Foglamps Not Operating</a>
<a href="#">DDAF77_20-U-1200FG</a>	<a href="#">08/19/1999</a>	<a href="#">Wind Noise at Front of Tilting/Sliding Roof</a>
<a href="#">DDAF72_29-U-6000A</a>	<a href="#">08/18/1999</a>	<a href="#">Failure of Power Window Drive</a>
<a href="#">DDAF91_60-U-6090A</a>	<a href="#">08/18/1999</a>	<a href="#">Airbag ControlModule - DTCs 004, 007 Set</a>
<a href="#">DDAF88_70-U-6000A</a>	<a href="#">08/18/1999</a>	<a href="#">Operating Problem Exterior mirror</a>
<a href="#">DDAF77_20-U-6002A</a>	<a href="#">08/18/1999</a>	<a href="#">Malfunction of Electric Tilting/Sliding Roof</a>
<a href="#">DDAF83_30-U-6000A</a>	<a href="#">08/18/1999</a>	<a href="#">Occasional Air Conditioner Failure</a>
<a href="#">DDAF83_40-U-2001A</a>	<a href="#">08/18/1999</a>	<a href="#">EC Lamp ON, Cannot Be Shut OFF</a>
<a href="#">DDAF88_50-U-2003A</a>	<a href="#">08/17/1999</a>	<a href="#">Corrosion at Trunk Lid in Area of Lock Cylinder</a>
<a href="#">DDAF98_10-U-2005A</a>	<a href="#">08/17/1999</a>	<a href="#">Paint Damage to Trunk Lid in Area of Grip</a>
<a href="#">DDAF07_61-U-6000A</a>	<a href="#">08/12/1999</a>	<a href="#">Engine Cannot Be Started</a>
<a href="#">S-58_40-107</a>	<a href="#">08/01/1999</a>	<a href="#">Engine - Binder Heating Oven (Necessary Tool)</a>
<a href="#">S-99_00-223</a>	<a href="#">06/01/1999</a>	<a href="#">Electrical - Component Locator, Star Finder</a>
<a href="#">DDAF42_31-U-6001A</a>	<a href="#">05/27/1999</a>	<a href="#">Engine Does Not Start, Touch Start Inoperative</a>
<a href="#">DDAF42_45-U-3100A</a>	<a href="#">05/27/1999</a>	<a href="#">ESP is Activated Even On Slight Curves at Moderate Speed</a>
<a href="#">DDGF42_45-U-1000-07C</a>	<a href="#">05/27/1999</a>	<a href="#">ESP Electrical Components Locations</a>
<a href="#">DDAF54_00-U-6000Z</a>	<a href="#">05/17/1999</a>	<a href="#">Battery Discharged/Electronic Damage - After Jump Start</a>
<a href="#">DDAF82_10-U-4041AU</a>	<a href="#">05/17/1999</a>	<a href="#">Headlamps/Turn Signals Mist Up or Leaking</a>
<a href="#">DDAF82_10-U-2008A</a>	<a href="#">05/17/1999</a>	<a href="#">Color or Brightness Difference of Headlamps</a>
<a href="#">DDAF82_70-U-1005A</a>	<a href="#">05/03/1999</a>	<a href="#">Telephone Call is Interrupted When Engine Started</a>
<a href="#">DDAF67_30-U-6001A</a>	<a href="#">05/03/1999</a>	<a href="#">Side Window Opens After Closing</a>

<a href="#">DDAF18_40-U-8042A</a>	<a href="#">04/11/1999</a>	<a href="#">Engine Oil Above Max Level</a>
<a href="#">P-91_18-39</a>	<a href="#">04/01/1999</a>	<a href="#">Interior - New Style Seat Covers Introduced</a>
<a href="#">DDAF83_25-U-6000AG</a>	<a href="#">02/26/1999</a>	<a href="#">Heater Blower is Noisy</a>
<a href="#">DDAF27_19-U-8000A</a>	<a href="#">02/09/1999</a>	<a href="#">A/T - Emergency Mode, DTCs 012, 013, 108, 109 Set</a>
<a href="#">DDAF27_10-U-6000A</a>	<a href="#">02/09/1999</a>	<a href="#">A/T - Emergency Mode DTCs 051, 055, 147, 151 Set</a>
<a href="#">DDAF54_30-U-8400A</a>	<a href="#">02/05/1999</a>	<a href="#">Instrument Cluster Indicates Lubrication System Faults</a>
<a href="#">DDAF82_10-U-6002B</a>	<a href="#">02/05/1999</a>	<a href="#">Bulb Life Short in Headlamps/Marker Lamps</a>
<a href="#">S-58_00-043D</a>	<a href="#">02/01/1999</a>	<a href="#">Special Tools - Inventory List</a>
<a href="#">DDAF18_40-U-8041A</a>	<a href="#">01/28/1999</a>	<a href="#">Instrument Cluster Indicates Oil Sensor Faulty</a>
<a href="#">DDAF01_40-U-4000AU</a>	<a href="#">01/27/1999</a>	<a href="#">Oil Leak From Drain Opening on Left Side of Engine</a>
<a href="#">DDAF13_25-U-1400AG</a>	<a href="#">01/27/1999</a>	<a href="#">Irregular Knocking Noises at Belt Drive/Water Pump</a>
<a href="#">DDAF05_10-U-1450GG</a>	<a href="#">01/27/1999</a>	<a href="#">Arrhythmic Noise at Idle, Coolant Temp. Over 40 Degrees C</a>
<a href="#">DDAF13_22-U-1401AG</a>	<a href="#">01/27/1999</a>	<a href="#">Irregular Knocking and Rattling From Belt Tensioner</a>
<a href="#">DDAF82_60-U-2000BA</a>	<a href="#">01/26/1999</a>	<a href="#">Display Flashes (All Radio Functions in Order)</a>
<a href="#">DDAF82_61-U-6003AG</a>	<a href="#">01/26/1999</a>	<a href="#">Station Storage/Cassette Slot - Warning Too Loud</a>
<a href="#">DDAF91_10-U-9000ZG</a>	<a href="#">01/25/1999</a>	<a href="#">Noises From Front Seats</a>
<a href="#">DDAF72_29-U-6001A</a>	<a href="#">01/25/1999</a>	<a href="#">Malfunction of Rear Power Windows</a>
<a href="#">DDAF72_10-U-1001AG</a>	<a href="#">01/25/1999</a>	<a href="#">Noises When Operating Front Power Windows</a>
<a href="#">DDAF68_20-U-6002A</a>	<a href="#">01/25/1999</a>	<a href="#">Mechanism of Ashtray Housing Damaged/Jamming</a>
<a href="#">DDAF33_15-U-3000A</a>	<a href="#">01/25/1999</a>	<a href="#">Vibration/Torsional Vibration at The Steering Wheel</a>
<a href="#">DDAF30_20-U-9900AG</a>	<a href="#">01/25/1999</a>	<a href="#">Engine Surges/Runs Irregularly at Idle</a>
<a href="#">DDAF98_00-U-2000A</a>	<a href="#">01/25/1999</a>	<a href="#">Deformation of Parts During Repair Paintwork</a>
<a href="#">P-82_60-88A</a>	<a href="#">01/01/1999</a>	<a href="#">Radio - Alpine Post Warranty Repair Program</a>
<a href="#">S-82_10-115</a>	<a href="#">12/01/1998</a>	<a href="#">Lights - Daytime Running Lamps, Canadian Regulations</a>
<a href="#">P-72_10-018</a>	<a href="#">11/01/1998</a>	<a href="#">Locks - Front Door Lock Trim, Clicking Noise</a>
<a href="#">1998090002</a>	<a href="#">11/01/1998</a>	<a href="#">Recall - Side Window Airbag Defect</a>
<a href="#">98V256000</a>	<a href="#">10/07/1998</a>	<a href="#">Recall 98V256000: Window Air Bag Inspection/Replacement</a>

<a href="#">P-72_29-017</a>	<a href="#">10/01/1998</a>	<a href="#">Windows - Power Window Lifter Assembly Components</a>
<a href="#">S-00_00-068</a>	<a href="#">10/01/1998</a>	<a href="#">Computer Software - Y2K Impacts</a>
<a href="#">S-82_35-113A</a>	<a href="#">10/01/1998</a>	<a href="#">Windshield - Washer Concentrate</a>
<a href="#">S-58_30-106</a>	<a href="#">10/01/1998</a>	<a href="#">Engine - Borescope &amp; Fiberscope Functionality</a>
<a href="#">P-68_20-011</a>	<a href="#">10/01/1998</a>	<a href="#">Interior - Reuse Matching Wood Trim From Ashtray Housing</a>
<a href="#">P-82-112</a>	<a href="#">09/01/1998</a>	<a href="#">Radio - Installation of CD Changer and Cell Phone (CTEL)</a>
<a href="#">P-62_20-001</a>	<a href="#">09/01/1998</a>	<a href="#">Frame - Longitudinal Member Sectioning Revision</a>
<a href="#">P-SI-40_30A</a>	<a href="#">08/01/1998</a>	<a href="#">Suspension - New Alignment Tools and Procedures</a>
<a href="#">DDAF27_00-P-0000A</a>	<a href="#">07/16/1998</a>	<a href="#">A/T 722.6 - DTC Information</a>
<a href="#">DDAF42_31-U-8000A</a>	<a href="#">07/15/1998</a>	<a href="#">Brake Assist (BAS): Fault Code C1025</a>
<a href="#">DDAF42_45-U-8101A</a>	<a href="#">07/15/1998</a>	<a href="#">ESP Fault Code C1142</a>
<a href="#">DDAF80_57-U-6401A</a>	<a href="#">07/13/1998</a>	<a href="#">Repairs for Faults of Electronic Ignition Switch</a>
<a href="#">DDAF82_60-U-6007-01A</a>	<a href="#">07/13/1998</a>	<a href="#">Test of Electronic Ignition Switch</a>
<a href="#">DDAF82_60-U-6007-02A</a>	<a href="#">07/13/1998</a>	<a href="#">Making and Installing Auxiliary Wiring Harness</a>
<a href="#">P-58_083B</a>	<a href="#">07/01/1998</a>	<a href="#">Body/Frame - Dedicated Fixture Set</a>
<a href="#">S-SI-91_31</a>	<a href="#">06/01/1998</a>	<a href="#">Seat Belts - Extended Length Belt Order Request</a>
<a href="#">S-SI-14_12A</a>	<a href="#">05/01/1998</a>	<a href="#">I/M Emission Testing on Dynamometer</a>
<a href="#">S-27_032</a>	<a href="#">05/01/1998</a>	<a href="#">A/T - Repair/Replacement Guidelines</a>
<a href="#">DDAF80_20-U-6100A</a>	<a href="#">04/07/1998</a>	<a href="#">Central Locking Unlocked When Driving, Dome Lamp ON</a>
<a href="#">DDAF80_20-U-4000A</a>	<a href="#">04/07/1998</a>	<a href="#">PSE System Does Not Function But Pump Runs</a>
<a href="#">S-82_108</a>	<a href="#">04/01/1998</a>	<a href="#">Cellular Phone - Diagnosis &amp; Return Form</a>
<a href="#">S-72_055</a>	<a href="#">04/01/1998</a>	<a href="#">Interior - Door Trim Panel Component Replacement</a>
<a href="#">S-82_098</a>	<a href="#">03/01/1998</a>	<a href="#">Cellular - (Motorola) Telephone Direct Repair Program</a>
<a href="#">S-91_048A</a>	<a href="#">03/01/1998</a>	<a href="#">Airbag - Replacement Label</a>
<a href="#">DDAF42_45-U-8000A</a>	<a href="#">02/11/1998</a>	<a href="#">Steering Angle Sensor, DTCs C1140, C1504, 015, 016, 017</a>
<a href="#">DDAF54_30-U-2107A</a>	<a href="#">04/28/1997</a>	<a href="#">ABS, MIL ON No ABS System Malfunctions</a>
<a href="#">DDAF27_19-U-2000A</a>	<a href="#">04/24/1997</a>	<a href="#">Illumination of Shift Gate Is Too Dim</a>

<a href="#">NHTSA99E024000</a>	<a href="#">08/02/1996</a>	<a href="#">Recall 99E024000: Child Restraint &amp; Booster Seat Defect</a>
<a href="#">00_053</a>	<a href="#">10/01/1993</a>	<a href="#">Maintenance - Factory Approved Service Products</a>
<a href="#">DD01-82042</a>	<a href="#">04/01/1982</a>	<a href="#">External Oil Leaks</a>

---

© 2006 ALldata LLC. All rights reserved.

[Terms of Use](#)