



AF72.29-U-6000A	Failure of power window drive	18.8.99
-----------------	-------------------------------	---------

Revisions

30.4.99	Supersedes STIP 72.19-006 dated 26.4.99	Valid for front power windows only	
---------	---	------------------------------------	--

Damage code	Cause	Remedy	
	 After failure of the front power window replace only the drive (motor + door control module) and not the complete power window (mechanism + drive).	 Complete power windows sent in for warranty or goodwill claims will no longer be accepted in the event of complaints concerning the electric drives.	
None	Cause 1: Motor defective	Remedy 1: 1 Replace motor	AR72.29-P-1860F
None	Cause 2: Door control module defective	Remedy 2: 1 Replace door control module	AR72.29-P-1000E