

## 2007 MERCEDES-BENZ E-Class 3.5L V6

WDBUF56X17B078947

Odometer: 153,435 miles

### 2 Confirmed Codes

**P0012** "A" Camshaft Position - Timing Over-Retarded Bank 1

**P0128** Coolant Thermostat (Coolant Temperature Below Thermostat Regulating Temperature)

### 1 Pending Code

**P0128** Coolant Thermostat (Coolant Temperature Below Thermostat Regulating Temperature)

### 0 Permanent Codes

### 1 System Diagnose Code

**B130C** Knowledge base configuration incomplete.  
PRESENT Not Relevant!

### 3 Door Control Module - Rear Left Codes

**B1010** N69/3 (Left rear door control unit) : The supply voltage of the control unit is too  
NOT PRESENT low (undervoltage).

**B1404** M14/8 (CL left rear door motor) : Short circuit  
NOT PRESENT

**B1505** No description available  
NOT PRESENT

### 6 Upper Control Panel Codes

**B1023** Fault in CAN communication with control unit N70 (Overhead control panel control unit).  
NOT PRESENT

**B1028** Not Relevant!  
NOT PRESENT

**B1031** The connection between control module N72/1 (Upper control panel control unit) and component M8 (UCP carrier open and close motor) is interrupted.  
NOT PRESENT

**B1032** The supply voltage of control unit N72/1 (Upper control panel (UCP [OBF])) is too low (undervoltage).  
NOT PRESENT

**B1027** CAN communication is faulty.  
NOT PRESENT

**B1033** The folding switch panel received no authorization to open or close from the AGW, CD changer, COMAND or audio systems.  
NOT PRESENT

### 1 Door Control Module - Rear Right Code

**B1010** N69/4 (Right rear door control unit) : The supply voltage of the control unit is too low (undervoltage).  
NOT PRESENT

### 1 Door Control Module - Front Right Code

**B1211** There is a discontinuity in the line to component M21/2r1 (Mirror heater) or the component is defective.  
NOT PRESENT

### 4 Motor Electronics Codes

**P1207** The position of the intake camshaft (cylinder bank 1) is implausible relative to the position of the crankshaft.  
NOT PRESENT

**P0272** Adjustment of the intake camshaft (cylinder bank 1) is performed late.  
NOT PRESENT

**P0064** Adjustment of the exhaust camshaft (cylinder bank 2) is performed late.  
NOT PRESENT

**P0856** The coolant temperature is below the coolant thermostat specified temperature.  
MIL/PRESENT

**Disclaimer:** This information is provided without warranty and is subject to the Terms of Use posted at [www.bluedriver.com/eula.html](http://www.bluedriver.com/eula.html). Reproduction of this information or any portion thereof constitutes infringement of copyright.