MODEL 212.2## (except 212.274/275/276/277/292/298) 1#

without CODE 460 (Canada version)

without CODE 494 (US version)

without CODE 498 (Japanese version)

without CODE 770 (AMG 7 double-spoke design)


without CODE 871 (Sensor system for trunk lid opening/closing)

without CODE R17 (48.3 cm (19-inch) 5-twin-spoke light-alloy wheels)


- 1 Cross member of trailer hitch
- 2 Longitudinal member reinforcement, left
- 3 Longitudinal member reinforcement, right
- 4 Seal
- 5 Bolt with washer (M10 B25)
- 13 Bolt (M12 B1.5B35)

Crossmember

15 Nuts (M10)



P31.10-3252-06



P31.11-2305-01

X	Remove		
⚠ Danger !	<b>Risk of death</b> caused by vehicle slipping or toppling off of the lifting platform.	Align vehicle between vehicle lift columns and position the four support plates at the vehicle lift support points specified by vehicle manufacturer.	AS00.00-Z-0010-01A
i	Notes on installing a trailer hitch		AH31.10-P-1000-02CW
i	Notes on EU type approval requirements		AH31.10-P-1000-03T
1	Print out the document "Trailer hitch, certificate"	Valid only for EU member countries.	
<b>⊯</b> OF	Trailer hitch certificate		OF31.10-P-1000-01DS

		i Print out the document "Trailer hitch,	
		certificate" and submit for the installation acceptance. For do-it-yourself installation, print	
		out the detailed installation instructions and give to the customer.	
2 ⊯AR	Remove trim in cargo area		AR68.30-P-1180ES
		i Check in the EPC whether the interior trim	7.1100.001
		installed in accordance with the vehicle equipment has to be replaced.	
3	Remove rear SAM control module with fuse and relay module		
<b>⊯</b> AR	and relay module		AR54.21-P-1258EW
		The check in the EPC if the rear SAM control unit with fuse and relay module installed in accordance with the vehicle equipment can be used for the retrofitting of the trailer hitch (AHV).	
		If necessary, remove the rear SAM control unit with fuse and relay module and replace it with one that is compatible with the trailer hitch. If the rear SAM control unit with fuse and relay module does not need to be replaced, just detach it and put aside.	
4 ⊯AR	Remove rear bumper		AR88.20-P-2200EW
5	Remove heat shield	i Left on a single-pipe exhaust system. Left and right on a twin-pipe exhaust system.	AROU.201 2200EVV
6	Remove exhaust rubber bushings on rear muffler	Left on a single-pipe exhaust system. Left and right on a twin-pipe exhaust system.	
7	Remove crossmember (6)	The crossmember (6) is no longer required.	
8	Check electric fan for compatibility, replace if necessary	i Check in the EPC if the electric fan installed in accordance with the vehicle equipment can be used for the retrofitting of the trailer hitch (AHV).  If necessary, remove the electric fan and replace it with one that is compatible with the trailer hitch.	
X	Install		
9	Retrofit mechanical detachable parts	Nm Bolt, trailer hitch to longitudinal member reinforcement	AN31.11-P-8080-05ES *BA31.11-P-1001-01J
		Nut, trailer hitch to rear center panel	*BA31.11-P-1002-01J
		Bolt, longitudinal member reinforcement to frame side member	*BA31.11-P-1003-01J
10	Retrofit trailer hitch control unit		AN31.19-P-8080-05ES
11	Retrofit trailer hitch wiring harness	Ensure that the wiring harnesses are not damaged by pinching or crushing. Otherwise the corresponding wiring harness must be replaced.	AN31.19-P-8100-05ES
		Wiring harness repair kit, basic  New passenger car wiring harness repair	*000589139900 *220589049900
12	Retrofit release lever	kit	AN31.11-P-8080-06ES
⚠ Danger !	Risk of explosion caused by paint vapors	No smoking! No open fire! Use respiratory	AS98.00-Z-0002-01A
13	igniting. <b>Risk of poisoning</b> caused by inhaling paint vapors.  Paint bumper on rear lower section	protection, protective clothing, gloves, safety glasses and skin cream. Ensure that the area is well ventilated.  With CODE 950 (AMG sport package)	
		Use only paint and paint system approved by Daimler AG. The Daimler AG painting specifications must be observed.	
		Check with the customer whether the rear lower section of the bumper is to be painted or not. Where applicable, do not perform this step.	
14	Modify rear bumper	With CODE 950 (AMG sport package)	AN88.30-P-0007-01EX

15	Install remaining parts		
16	Enter special equipment in online vehicle data card via vehicle documentation system (VeDoc)	i Add:  ● CODE 550 (Trailer hitch)	
17	Document retrofitted equipment in VeDoc	Attach note "Trailer hitch retrofitted as per AN31.10-P-0001ES" under field organization texts for design group 31.	
18	Connect Star Diagnosis and select vehicle via the vehicle identification number (VIN)		
<b>⊯</b> AD			AD00.00-P-2000-04A
19	Perform variant coding with XENTRY using the software calibration number (SCN)	Variant coding must be carried out with XENTRY using the SCN for the following control unit:     "Front SAM with fuse and relay module"	
20	Disconnect diagnostic system		
21	Perform function test of light signals at trailer hitch socket		AN31.19-P-8100-06CW

## Nm Trailer hitch mechanism

Number Designation		MODEL 212	
BA31.11-P-1003-01J	Bolt, longitudinal member reinforcement to frame side member	Nm	85

## Nm Trailer hitch mechanism


Number	Designation	MODEL 212
BA31.11-P-1001-01J	Bolt, trailer hitch to longitudinal member reinforcement Nm	110

## Nm Trailer hitch mechanism

Number	Designation		MODEL 212
BA31.11-P-1002-01J	Nut, trailer hitch to rear center panel	Nm	85



New passenger car wiring harness repair kit



Wiring harness repair kit, basic

## Parts ordering note

Part no.	Designation	Quantity
KG 99 (siehe EPC)	Vehicles without code (489) AIRMATIC (air suspension with continuous adjustment damping)	1
	Trailer hitch package contents	
KG 99 (siehe EPC)	Vehicles with code (489) AIRMATIC (air suspension with continuous adjustment damping)	1
	Trailer hitch package contents	