Fading of wood trim in model series 212

Topic number LI68.30-P-053962

Version 3

Design group 68.30 Coverings, trim

Date 03-14-2013

Validity Affected vehicles up to:

MODEL 212 with CODE (731) Burred walnut veneer

wood finish trim

MODEL 212 with CODE (W 60) Burred walnut veneer

designo wood trim, brown Cleanpoint August 2011

Reason for change Removed non-US specific parts due to confusion with

parts ordering.

Complaint:

Fading of the burred walnut veneer wood finish trim parts.

Cause:

UV radiation can cause fading in some cases.

Remedy:

Affected vehicles:

MODEL 212 with CODE (731) Burred walnut veneer wood finish trim

MODEL 212 with CODE (W 60) Burred walnut veneer designo wood trim, brown

Cleanpoint August 2011

Parts kits of burred walnut veneer wood finish trim are available from the GLC in the event of complaints.

In order to rule out the possibility of installing the wrong parts, check the date of manufacture on the rear of each component.

Parts kits with parts earlier than cleanpoint August 2011 should be returned to GLC.

Encode the affected component with damage type "**"

Symptoms

Body / Interior equipment / Door paneling / Discolored

Body / Interior equipment / Instrument panel / Surface discolored

Body / Interior equipment / Interior trim / Discolored

| Parts | | | | | | | |
|-------------|-----|-----|-------------|----------|------|-----|-------|
| Part number | ES1 | ES2 | Designation | Quantity | Note | EPC | Other |
| | | | | | | | ma- |

XENTRY

| _ | | | | ke part |
|-------------|--|--|--|------------|
| A2126801293 | | Parts kit: Burred walnut veneer wood finish trim parts | LHD with steering wheel gearshift (code 279) | Х |

| Work units | | | | | | | |
|------------|----------------|------|-------------|---|--|--|--|
| Op. no. | Operation text | Time | Damage code | Note | | | |
| | | | | Encode the affected component with damage type "**" | | | |