

Lump under seat cushion cover

| | |
|-------------------|---|
| Topic number | LI91.30-P-054637 |
| Version | 3 |
| Design group | 91.30 Seat heater, seat ventilation |
| Date | 08-12-2013 |
| Validity | Model series 212 with seat heater (SA code 873/401) up to VIN A703331 |
| Reason for change | SA code 401 added |

Complaint:

Cable channel of seat heater visibly protruding and able to be felt

| Attachments | |
|-------------|--------------|
| File | Designation |
| PIC212.jpg | Lump visible |

Cause:

The position of the channel may be such that it protrudes and is visible at the surface of the cushion cover

Remedy:

Installation of a heat mat with modified heating element routing

| Symptoms |
|--|
| Body / Seat / Seat cover / Pilling/knots |
| Body / Seat / Seat cover / Folds |
| Body / Seat / Seat cover / Staining |
| Body / Seat / Seat cover / Detaches |

| Parts | | | | | | | |
|-----------------|-----|-----|-------------|----------|------|-----|-----------------|
| Part number | ES1 | ES2 | Designation | Quantity | Note | EPC | Other make part |
| A 212 906 40 02 | | | Seat heater | 1 | | X | |

| Work units | | | | |
|------------|----------------|------|-------------|----------------------------|
| Op. no. | Operation text | Time | Damage code | Note |
| | | | 91A24 73 | Left front seat heater pad |

| | | | | |
|--|--|--|----------|-----------------------------|
| | | | 91N24 73 | Right front seat heater pad |
|--|--|--|----------|-----------------------------|