

Lump under seat cushion cover

Topic number	LI91.30-P-054637
Version	3
Design group	91.30 Seat heater, seat ventilation
Date	08-12-2013
Validity	Model series 212 with seat heater (SA code 873/401) up to VIN A703331
Reason for change	SA code 401 added

Complaint:

Cable channel of seat heater visibly protruding and able to be felt

Attachments	
File	Designation
PIC212.jpg	Lump visible

Cause:

The position of the channel may be such that it protrudes and is visible at the surface of the cushion cover

Remedy:

Installation of a heat mat with modified heating element routing

Symptoms
Body / Seat / Seat cover / Pilling/knots
Body / Seat / Seat cover / Folds
Body / Seat / Seat cover / Staining
Body / Seat / Seat cover / Detaches

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other make part
A 212 906 40 02			Seat heater	1		X	

Work units				
Op. no.	Operation text	Time	Damage code	Note
			91A24 73	Left front seat heater pad

			91N24 73	Right front seat heater pad
--	--	--	----------	-----------------------------