

Inspection Report

This report is created by

LAUNCH

Vehicle Information

VIN: WDDHH8JB4GB*****

Vehicle manufacturer/model: Mercedes/E-Class

Year of manufacture: 2016

Mileage: 77369

Vehicle Software Version: V49.95

Inspection Organization

Name:

Address:

Contact Number: [☎ 8312524115](tel:8312524115)

SN: 960744005203

Time and date of inspection: 01/21/2023 19:59:40

Inspection Location: 

Inspection Result

There are 1 issues for Safety and Security system:

1.The squib for pyrofuse "On-board electrical network line" has a malfunction.There is an open circuit.

Inspections are normal for Power system

- 1.FSCU - Control Unit'Fuel pump'(N118)
- 2.TCM - Transmission Control Module
- 3.ISM - Shift module(A80)
- 4.ECM - Engine Control Module(ME)

Inspections are normal for Chassis system

- 1.AIRMATIC - AIRMATIC(N51/3)
- 2.TPMS - Tire Pressure Monitoring System

Inspections are normal for Safety and Security system

- 1.RevETR_LF - Left Front Reversible Emergency Tensioning retractor(A76)
- 2.MFK - Multifunction camera(A40/11)
- 3.SG-AWF - COLLISION PREVENTION ASSIST
- 4.RevETR_RF - Right Front Reversible Emergency Tensioning retractor(A76/1)
- 5.ES - Electronic Power Steering
- 6.RFK - Backup Camera
- 7.IRS-HRA - Outer Right Rear Intelligent Radar Sensor system(B29/5)
- 8.ESP(R) - Electronic Stability program(N30/4)
- 9.SCCM - Steering Column module(N80)

10.IRS-HLA - Outer Left Rear Intelligent Radar Sensor system(B29/4)

Inspections are normal for Vehicle body system

- 1.CGW[ZGW] - Central gateway(CGW[ZGW])
- 2.IC - Instrument cluster(A1)
- 3.COU[ZBE] - Audio/COMAND Operating Unit
- 4.XALWA_R - Right Xenon headlamp(E2n1)
- 5.PTG - Power Tail Gate(N121/1)
- 6.KG - KEYLESS GO(N69/5)
- 7.AC - Air Conditioning(N22/7)
- 8.DCU_RR - Right Rear door(N69/4)
- 9.DCU_LF - Left Front door(N69/1)
- 10.ESA 'Driver' - Electric Seat Adjustment 'Drive'(N32/1)
- 11.DCU_RF - Right Front door(N69/2)
- 12.EZS - Electronic Ignition lock(N73)
- 13.Rear SAM - Rear Signal Acquisition And Actuation module(N10/2)
- 14.SD - Control Module Sliding Roof
- 15.XALWA_L - Left Xenon headlamp(E1n1)
- 16.Driver-side SAM - Front Signal Acquisition And Actuation module(N10/1)
- 17.ESA'Front Passenger' - Electric Seat Adjustment 'Front passenger'(N32/2)
- 18.DCU_LR - Left Rear door(N69/3)

Inspections are normal for Infotainment system

- 1.KOMO/mbrace - Communication Module'Telematics Services'/Emergency call system
- 2.SOUND - Sound system(N40/3)
- 3.ZAN - Audio/COMAND display(A40/8)
- 4.Audio/COMAND - Audio Or COMAND(A2-A2/56-A40/3)
- 5.TV - TV tuner(A90/1)

Professional Report

RevETR_LF - Left Front Reversible Emergency Tensioning retractor(A76)	Normal	∨
KOMO/mbrace - Communication Module'Telematics Services'/Emergency call system	Normal	∨
MFK - Multifunction camera(A40/11)	Normal	∨
SOUND - Sound system(N40/3)	Normal	∨
CGW[ZGW] - Central gateway(CGW[ZGW])	Normal	∨
AIRMATIC - AIRMATIC(N51/3)	Normal	∨
SRS - Supplemental Restraint system(N2/10)	Abnormal	1 ^

DTC Qty (1)

B273513

The squib for pyrofuse "On-board electrical network line" has a malfunction.There is an open circuit.

CURRENT and STORED

SG-AWF - COLLISION PREVENTION ASSIST	Normal	∨
FSCU - Control Unit'Fuel pump'(N118)	Normal	∨
TCM - Transmission Control Module	Normal	∨
RevETR_RF - Right Front Reversible Emergency Tensioning retractor(A76/1)	Normal	∨
IC - Instrument cluster(A1)	Normal	∨
COU[ZBE] - Audio/COMAND Operating Unit	Normal	∨
XALWA_R - Right Xenon headlamp(E2n1)	Normal	∨
ES - Electronic Power Steering	Normal	∨
ISM - Shift module(A80)	Normal	∨
TPMS - Tire Pressure Monitoring System	Normal	∨
RFK - Backup Camera	Normal	∨
IRS-HRA - Outer Right Rear Intelligent Radar Sensor system(B29/5)	Normal	∨
PTG - Power Tail Gate(N121/1)	Normal	∨
KG - KEYLESS GO(N69/5)	Normal	∨
ESP(R) - Electronic Stability program(N30/4)	Normal	∨
ZAN - Audio/COMAND display(A40/8)	Normal	∨
ECM - Engine Control Module(ME)	Normal	∨
AC - Air Conditioning(N22/7)	Normal	∨
DCU_RR - Right Rear door(N69/4)	Normal	∨
DCU_LF - Left Front door(N69/1)	Normal	∨
ESA 'Driver' - Electric Seat Adjustment 'Drive'(N32/1)	Normal	∨
DCU_RF - Right Front door(N69/2)	Normal	∨
EZS - Electronic Ignition lock(N73)	Normal	∨
Rear SAM - Rear Signal Acquisition And Actuation module(N10/2)	Normal	∨

SD - Control Module Sliding Roof	Normal	∨
XALWA_L - Left Xenon headlamp(E1n1)	Normal	∨
Audio/COMAND - Audio Or COMAND(A2-A2/56-A40/3)	Normal	∨
Driver-side SAM - Front Signal Acquisition And Actuation module(N10/1)	Normal	∨
SCCM - Steering Column module(N80)	Normal	∨
IRS-HLA - Outer Left Rear Intelligent Radar Sensor system(B29/4)	Normal	∨
ESA'Front Passenger' - Electric Seat Adjustment 'Front passenger'(N32/2)	Normal	∨
TV - TV tuner(A90/1)	Normal	∨
DCU_LR - Left Rear door(N69/3)	Normal	∨

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.