

- Parts list -

Vehicle	WDDHF9HB7EA886790 (D01)	E 250 BlueTEC 4MATIC Sedan / E 250 d 4MATIC Sedan
Color	149 - undefined	Equipment 111 -
FIN: WDD2120971A886790		Assortment class PC
Group	61 Substructure	Sub-group 015 Front floor














Image ID: drawing_B61015000176

Item	Part number	Designation/additional information	Qty
10	A 212 610 03 60	FLOOR LEFT	1
30	A 212 610 04 60	FLOOR RIGHT	1
50	A 212 680 12 09	COVER, SUBSTRUCTURE BELOW MAIN FLOOR,LEFT Code: (M651/M642)+M005+(U42/U77)+-100;	1
70	A 212 680 04 09	COVER, SUBSTRUCTURE BELOW MAIN FLOOR,RIGHT	1
80	A 002 994 93 45	* SECURING ATTACHMENT COVER LEFT; 4,8MM	1
80	A 002 994 93 45	* SECURING ATTACHMENT COVER RIGHT; 4,8MM	1
95	A 124 990 04 92	EXPANSION RIVET MOUNTING, COVER; 6.5X18	4
100	N 000000 000815	TAPPING SCREW UNDERBODY SHIELD TO WHEELHOUSE; 4,8X16	2

Parts Information

Item	Part number	Designation/additional information	Qty
103	A 000 990 44 62	PLASTIC NUT ATTACHMENT COVER LEFT  [002229] IMPORTANT: OBSERVE TIPS DOCUMENT GI61.25-P-047672!!	8
103	A 000 990 44 62	PLASTIC NUT ATTACHMENT COVER RIGHT  [002229] IMPORTANT: OBSERVE TIPS DOCUMENT GI61.25-P-047672!!	8
104	A 008 990 75 82	SPACER DISK ATTACHMENT COVER LEFT  [002229] IMPORTANT: OBSERVE TIPS DOCUMENT GI61.25-P-047672!!	7
104	A 008 990 75 82	SPACER DISK ATTACHMENT COVER RIGHT  [002229] IMPORTANT: OBSERVE TIPS DOCUMENT GI61.25-P-047672!!	7
120	A 212 619 03 00 	STIFFENER TUNNEL,REAR Replaced by: A 212 619 10 00	1
120	A 212 619 10 00	STIFFENER TUNNEL,REAR Replaces: A 212 619 03 00	1
130	N 000000 004688	HEXALOBULAR BOLT REINFORCEMENT AT REAR TUNNEL; M10X30	4
140	A 212 610 11 31	MOUNTING CONSOLE REINFORCEMENT AT TUNNEL, LEFT  [402] NO LONGER AVAILABLE	1
140	A 212 610 12 31	MOUNTING CONSOLE REINFORCEMENT AT TUNNEL, RIGHT  [402] NO LONGER AVAILABLE	1
150	A 212 616 02 00	REINFORCEMENT BRACKET TO MAIN FLOOR LEFT	1
200	A 212 610 01 23	LONGITUDINAL MEMBER BELOW MAIN FLOOR,LEFT	1
220	A 212 610 02 23	LONGITUDINAL MEMBER BELOW MAIN FLOOR,RIGHT	1
240	A 212 610 03 10	CONNECTING CARRIER MAIN FLOOR,FRONT LEFT	1
260	A 212 610 04 10	CONNECTING CARRIER MAIN FLOOR,FRONT RIGHT	1
280	A 212 610 05 20	CROSSMEMBER BELOW FRONT SEAT,FRONT LEFT	1
300	A 212 610 06 20 	CROSSMEMBER BELOW FRONT SEAT,FRONT RIGHT  [429] THEFT-RELEVANT PART	1
360	A 212 610 07 20	CROSSMEMBER BELOW FRONT SEAT,REAR LEFT	1
380	A 212 610 08 20	CROSSMEMBER BELOW FRONT SEAT,REAR RIGHT	1
700	A 000 990 12 10	THREADED PIN REPAIR SOLUTION FOR RUPTURED WELDED PINS	NB
705	A 000 991 76 32	BLIND RIVET REPAIR SOLUTION; 6,4 X 12MM / 1-3,5MM  [002970, 402] RIVET ONLY VALID FOR BR 222. FOR REPAIR INFORMATION, SEE WIS.	NB