Model 213.0 (except 213.088/089), 213.2 (except 213.288/289) as of model year 2018 with code 531 (COMAND APS) except code 320 (Single CD drive preinstallation) except code 334 (Two-way radio retainer in glove compartment) except code 498 (Japanese version) except code 830 (China version) 213.088/089/288/289 Model as of model year 2018 with code 531 (COMAND APS) except code 320 (Single CD drive preinstallation) except code 334 (Two-way radio retainer in glove compartment) except code 460 (Canada version) except code 494 (US version) except code 498 (Japanese version) except code 830 (China version)



P82.64-2970-09

CD drive 1

X	Remove		
	Information on preventing damage to electronic components due to electrostatic discharge		AH54.00-P-0001-01A
	Notes on the use of paint scraping nuts on ground connections		AH00.19-P-1000-20A
1	Remove fragrance generator	Type 213.0/2 with code P21 (Air quality package)	
₩AR			AR83.40-P-0200LW
2	Remove glove box		
<b>₩</b> AR			AR68.10-P-1402LWE
3	Remove head unit		
₩ AR			AR82.85-P-1101LWE
4	Detach HERMES control unit from holder and place to one side with attached lines		
₩FAR			AR82.95-P-0019LWE
5	Remove COMAND display		
₩AR			AR82.85-P-7429LWE

© Daimler AG, 8/26/19, X/08/19, az82.64-p-0002lwe, Retrofit CD drive

Page 1 of 2 Model 213.0 (except 213.088/089), 213.2 (except 213.288/289) as of model year 2018 with code 531 (COMAND APS) except code 320 (Single CD drive preinstallation) except code 334 ...

6	Remove bottom paneling for dashboard on		
0	driver side		
₩			AR68.10-P-1501LWE
7	Detach driver-side fuse and relay module (K40/6)		
GF	Assignment of driver-side fuse and relay module		GF54.15-P-1256-49FG
₩AR			AR54.15-P-0003LWE
		<b>i</b> so that electrical fuse 204 (K40/6f204) is accessible.	
8	Remove entrance plate on driver side		
₩FAR			AR68.30-P-4100LW
X	Install		
9	Produce a CD drive bracket drilling template (1)	Model 213.0/2## 1#	AZ82.64-P-0002-04LWE
		Model 213.0/2## 2#	AZ82.64-P-0002-04LWR
10	Fabricate adhesive film cutting template for CD drive (1)		AZ82.64-P-0002-05LWE
11	Use cutting template to cut adhesive film to size		
12	Prepare glove box for installation of CD drive (1)	Model 213.0/2## 1#	AZ82.64-P-0002-08LWE
		Model 213.0/2## 2#	AZ82.64-P-0002-08LWR
13	Prepare holder for CD drive (1) for installation		AZ82.64-P-0002-06LWE
14	Retrofit wiring harness for CD drive (1)		AZ82.64-P-0002-01LWE
		Nm Left footwell ground point	*BA00.19-P-1024-02A
15	Retrofit CD drive (1) in glove box		AZ82.64-P-0002-03LWE
16	Install glove box with CD drive (1)		
₩AR			AR68.10-P-1402LWE
		<b>i</b> Pay attention to installation of lines.	
17	5 Insert A fuse into the f204 slot of the driver- side fuse and relay module (K40/6)		
GF	Assignment of driver-side fuse and relay module		GF54.15-P-1256-49FG
18	Install remaining parts		
	Update Vehicle Documentation (VeDoc)		
19	Enter special equipment in on-line vehicle data card	i Code 320 (Single CD drive pre- installation)	
20	Attach "CD drive retrofitted as per AN82.64- P-0002LWE" note under field organization texts	<b>i</b> On design group 82 and design group 54.	
21	Connect diagnostic system and select vehicle via the vehicle identification number (VIN)		
i≆ AD			AD00.00-P-2000-04B
22	Carry out variant coding using software calibration number (SCN)	<b>i</b> Head unit	
23	Disconnect diagnostic system		
₩FAD			AD00.00-P-2000-04B
4	Check		
24	Perform function test	i See Owner's Manual.	

Nm Ground points

Number	Designation			Model 213
BA00.19-P-1024-02A	Left footwell ground point	W34	Nm	10

## Parts ordering note

Part no.	Designation	Quantity
KG 98 (siehe EPC)	CD drive scope of delivery	1