

# Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2017120005, January 2018

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 213, Model Year 2017**  
**Perform SCN coding in ESP control unit**

Daimler AG ('DAG'), the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY17 E-Class (213 platform) vehicles, the Electronic Stability Program (ESP) control unit software may not meet current series production specifications. An authorized Mercedes-Benz dealer will update the ESP control unit software on the affected vehicles.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 859 vehicles are affected.

Order No. P-SC-2017120005

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

# Service Campaign Bulletin

Service Campaign Bulletin







Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

## Procedure

### Note:

- Use DAS/Xentry 07/17 with all associated patches or higher.
  - Follow the steps exactly as described in DAS/Xentry.
  - Connect battery charger (battery voltage  >12.5V).
  - Ensure all electrical consumers are switched-off.
  - In the event of software/SCN update issues, contact Star Diagnosis User Help Desk. Please refer to the “pre-call” check list before contacting UHD
  - Refer to Star Diagnosis System (SDS) Best Practices Guide.
1. **Perform SCN coding in the ESP control unit:** Control units view  Chassis  ESP Electronic Stability Program  Adaptations  Control unit update  Update of SCN coding.
  2. Follow on-screen instructions.

### Note:

The following allowable labor operation should be used when submitting a warranty claim for this repair:

## Warranty Information

**Operation:** Connect/disconnect battery charger (02-5058)  
 Star Diagnosis System (SDS), Connect/disconnect (02-4762)  
 Perform SCN coding in the ESP control unit (02-9446)

Damage Code	Operation Number	Labor Time (hrs.)
42 940 41 8	02-5058	0.1
	02-4762	0.1
	02-9446	0.1

### Note

Operation Number labor times are subject to change.