

Vehicle Information

Brand: MERCEDES	VIN: WDC1668242A214202	Plate Number:
Model: 166.824	Mileage: 157477 km	Color:
Year:	Capacity:	Status: Unset status
Engine:	Reference:	Date: 07.11.2023 21:45:14

Automatic scanning results

System Name	Status/Count
01-CDI-Motor electronics	Pass No Fault
02-VGS-Transmission control	Fault 4
03-ESP-Electronic stability program	Pass No Fault
04-SRS-Supplemental restraint system	Pass No Fault
05-KI-Instrument cluster	Fault 1
06-EZS-Electronic ignition lock	Fault 1
07-ISM-Shift module	Pass No Fault
08-FSCU-Fuel pump	Pass No Fault
09-SCR-Selective catalytic reduction	Pass No Fault
10-ADS-Suspension system	Pass No Fault
11-ES-Electrical power steering	Pass No Fault
12-EFB-Electric parking brake	Pass No Fault
13-SAMF-Front signal acquisition and actuation module	Fault 1
14-MRM-Steering column module	Pass No Fault

15-PSD-Control module 'Sliding roof'	Pass No Fault
16-RevETR-LF-Left front reversible emergency tensioning retractor	Pass No Fault
17-RevETR-RF-Right front reversible emergency tensioning retractor	Pass No Fault
18-SG-FOND-Rear control unit	Fault 1
19-SG-SW-Headlamps	Fault 2
20-HU-Audio or COMAND	Pass No Fault
21-ZBE-Audio/COMAND operating unit	Pass No Fault
22-ZAN-Audio/COMAND display	Pass No Fault
23-SOUND-Sound system	Pass No Fault
24-UCI-Media interface	Pass No Fault
25-DMFL-Left front door	Fault 1
26-DMFR-Right front door	Fault 1
27-DMRL-Left rear door	Pass No Fault
28-DMRR-Right rear door	Pass No Fault
29-ESED-Electric seat adjustment 'Driver'	Pass No Fault
30-ESEP-Electric seat adjustment 'Front passenger'	Pass No Fault
31-HKS-Tailgate control	Pass No Fault
32-PTS-Control unit 'PARKTRONIC'	Pass No Fault
33-DTR-DISTRONIC	Pass No Fault
34-NBR-LF-Left front short range radar	Pass No Fault
35-NBR-RF-Right front short range radar	Pass No Fault
36-NBR-RR-Right rear short range radar	Pass No Fault

37-NBR-LR-Left rear short range radar	Pass No Fault
38-SGR-Radar sensors control unit	Fault 2
39-SVS-360° camera	Fault 2
40-MFK-Multifunction camera	Pass No Fault
41-KLA-Air conditioning	Pass No Fault
42-HBF-Rear control panel	Pass No Fault
43-LIN Bus : AISP-Dimming inside rearview mirror	Pass No Fault
44-LIN Bus : BSN-Battery sensor	Pass No Fault
45-LIN Bus : AMLAB-L-Actuation module, LED exterior lighting, left front	Pass No Fault
46-LIN Bus : AMLAB-R-Actuation module, LED exterior lighting, right front	Pass No Fault
47-LIN Bus : RGLS-Rain/light sensor	Pass No Fault
48-LIN Bus : WSS-Seat occupied recognition	Pass No Fault
49-LIN Bus : DBE-Control unit 'Overhead control panel'	Pass No Fault
50-LIN Bus : LRE-Steering wheel electronics	Pass No Fault

VGS-Transmission control

ID	Status	Description
0894	Stored	The transmission is slipping.
0732	Stored	Gear 2 is implausible or the transmission is slipping.
0733	Stored	Gear 3 is implausible or the transmission is slipping.
0731	Stored	Gear 1 is implausible or the transmission is slipping.

KI-Instrument cluster

ID	Status	Description
U012187	Stored	Communication with ESP has a malfunction. The message is missing.

EZS-Electronic ignition lock

ID	Status	Description
U012287	Stored(Event)	Communication with control unit 'Traction system' has a malfunction. The message is missing.

SAMF-Front signal acquisition and actuation module

ID	Status	Description
P25567B	Stored&Current	Sensor 'Coolant level' has a malfunction. The fluid level is too low.

SG-FOND-Rear control unit

ID	Status	Description
B1F1A13	Stored&Current	The output for illumination 'Right front door sill' has a malfunction. There is an open circuit.

SG-SW-Headlamps

ID	Status	Description
B283F87	Stored	The right xenon bulb has a malfunction. The message is missing.
B283E87	Stored	The left xenon bulb has a malfunction. The message is missing.

DMFL-Left front door

ID	Status	Description
B1DD015	Stored	The output for the mirror heater has a malfunction. There is a short circuit to positive or an open circuit.

DMFR-Right front door

ID	Status	Description
B1DD015	Stored&Current	The output for the mirror heater has a malfunction. There is a short circuit to positive or an open circuit.

SGR-Radar sensors control unit

ID	Status	Description
530400	Stored(Event)	Radar sensor 3 is disrupted by interference from an external transmitter.
520400	Stored(Event)	Radar sensor 2 is disrupted by interference from an external transmitter.

SVS-360° camera

ID	Status	Description
U014786	Stored	Communication with the control unit 'Head unit' has a malfunction. There is an incorrect signal.
U016886	Stored	Communication with the electronic ignition lock has a malfunction. There is an incorrect signal.

Contact Information

Name:

Address:

Phone:

Email:

Website: