

---

## Night performance of 360° camera dark

---

Topic number	LI54.65-P-059114
Version	5
Design group	54.65 Parking assist
Date	12-09-2014
Validity	166 with code 501 produced up to 10/2014 212 with code 501 produced up to 10/2014 217 with code 501 produced up to 05/2014 222 with code 501 produced up to 05/2014
Reason for change	Model X166 added

---

**Complaint:**

At night, the picture from the 360° camera in the display on the head unit can appear dark.

**Cause:**

Image processing software

**Remedy:**

Software update with optimized parameters.

**Model series 217/222:**

The software update is available for XENTRY with DVD 09/2014.

**Model series 166/212**

The software update is provided for XENTRY via

- Add-on 4018 DVD 07/2014
- Add-on 4039 DVD 09/2014.

Control unit/fault code		
Control unit	Fault code	Fault text
360° camera - 360° camera (N148) (SVS166) (M/GLE (166),GL/GLS (166),E (212))	-	-
360° camera - 360° camera (N148) (SVS222) (S (222),S (217))	-	-