

Model 166.0 up to 11/30/15, 207.3/4 up to 11/30/15, 218.3/9 up to 11/30/15, 292.3 up to 11/30/15
with code 531 (COMAND APS)
except code 14U (Smartphone integration package)

Modification notes

03.03.2016	Work procedure modified	Commissioning removed.	
------------	-------------------------	------------------------	--

	Remove/install		
1	Exchange multimedia connection unit in front stowage compartment		
	Update Vehicle Documentation (VeDoc)		
2	Enter special equipment in on-line vehicle data card	i Code 14U (Smartphone integration package) Code 16U (Smartphone integration Carplay) Code 17U (Smartphone integration Google Automotive Link)	
3	Attach note "Smartphone integration package retrofitted as per AZ82.60-P-0028NKM" under field organization texts to DG 82		
4 	Connect charger and charge battery	Model 207.3/4, 218.3/9 Model 166.0, 292.3	AR54.10-P-1130CW AR54.10-P-1130GZ
5 	Connect diagnostic system and select vehicle using vehicle identification number (FIN)		AD00.00-P-2000-04A
6	Perform software update for head unit	i Variant coding using software calibration number (SCN) is integrated in the software update.	
7	Disconnect diagnostic system		
8	Disconnect battery charger		
	Check		
9	Perform function test	i See operator's manual for smartphone integration package.	

Parts ordering note

Part no.	Designation	Quantity
KG 98 (siehe EPC)	Smartphone integration package parts kit	1