

## BR167 ARTICO Seat Covers On Front Seat Torn


---

|                   |   |
|-------------------|---|
| Topic number      | LI91.18-P-071629  |
| Version           | 9   |
| Function group    | 91.18 - Seat covers   |
| Date              | 9/2/22  |
| Validity          | Model series 167 ARTICO man-made leather upholstery or ARTICO man-made leather upholstery/DINAMICA microfiber |
| Reason for change | Remedy revised  |

---

### Complaint

On vehicles with "ARTICO man-made leather upholstery" or "ARTICO man-made leather upholstery / DINAMICA microfiber - black (601A)" the material of the seat side bolster can tear. Both the seat cushion cover and the backrest cover on the front seat can be affected here.

| Attachments   |             |
|---|-------------|
| File  | Description |
| <a href="#">example1.jpg</a>  | Example 1   |
|  |             |
| <a href="#">example2.jpg</a>  | Example 2   |



[example3.jpg](#)

Example 3



## Cause

The material may tear because the material in the side bolster is not suitable.

## Remedy

Optimized seat covers are available in XPPI (Xentry Portal Parts Information).

The new seat covers have the addition "PREMIUM" in the description. Please take note of this!

In the event of questions or problems concerning the seat covers, please open a PTSS case.

|   |
|---|
| <b>Symptoms</b>                           |
| Body > Seat > Seat cover > Chafed through |
| Body > Seat > Seat cover > Detaches       |
| <b>Operation numbers/damage codes</b>     |

# XENTRY TIPS

---

| Op. no. | Operation text | Time | Damage code | Note |
|---------|----------------|------|-------------|------|
|         |                |      | 91A0407     |      |
|         |                |      | 91N0407     |      |