



DTB

Date: August 23, 2002
 Order No.: T-B-41.10/02
 Supersedes:
 Group: 41

**SUBJECT: All 163 Models w/ Two-Piece Driveshaft
 Noise / Vibration**

As of repair date August 23, 2002, an intermediate bearing (carrier bearing) repair kit is available to address concerns of noise and/or vibration. Please use the specified part no. provided below to resolve. Work instructions can be found in WIS Document No. AR41.10-P-0101GH. Driveshaft replacement for carrier bearing concerns are no longer necessary and will no longer be covered by warranty.

Parts Information

Qty.	Part Name	Part Number
1	Carrier Bearing Kit	163 410 00 10

In Case of Warranty

Operation: Driveshaft – Front transfer case to rear axle, R&R (41-2350)
 Propeller Shaft Intermediate Bearing (propeller shaft with bearing removed) (41-6579)

Damage Code	Operation Number	Time (hrs.)	Model Indicator (s)
41021 38	41 2350	.8 hrs.	K1, K2, K3, K4
	41 6579	1 hr.	K0

This bulletin has been created and maintained in accordance with MBUSA-SLP 5.1, Document and Data Control, and MBUSA-SLP 16.1, Control of Quality Records.