

VIN	WDB2110701A123456	Model series/model designation	163.154
Order number		License plate	

Complete list of fault codes

B1000 Component B38 (Rain sensor) is defective.
B1005 Control module B38 (Rain sensor) does not receive any CAN messages.
B1040-000 CAN bus: fault in communication : ME motor electronics
B1040-001 CAN bus: fault in communication : ETS
B1040-002 CAN bus: fault in communication : ICM
B1040-003 CAN bus: fault in communication : VG
B1040-005 CAN bus: fault in communication : EAM
B1040-006 CAN bus: fault in communication : EAM on internal CAN
B1040-007 CAN bus: fault in communication : Rain sensor
B1217-001 Component B38 (Rain sensor) is defective.
B1217-002 Windscreen adaptation of rain sensor
B1232-000 The sensor for refrigerant pressure supplies implausible values : $\Gamma \neg + , - // -$.
B1232-001 The sensor for refrigerant pressure supplies implausible values : $\Gamma \neg -$.
B1341 Communication fault with component H3/1 (Alarm signal siren with additional battery)
B1368 Wake-up cable to control module EAM: $\Gamma \neg -$
B1419 The electromagnetic clutch of the AC compressor is faulty : $\Gamma \neg - , - // -$.
B1716 The ATA interior motion protection/inclination sensor in component N41 is faulty.
B1783-001 The CL signal contact Driver's door supplies implausible values. - Fault during unlocking
B1783-002 The CL signal contact Driver's door supplies implausible values. - Fault during locking
B1784-001 The CL signal contact Passenger door supplies implausible values. - Fault during unlocking

12/2016 (2016-10-06)\AddOns: ([6988] (7160) (7258) (6755) (6933) (7418) (7176) (6765) (7292) (6726) (6832) (7030) (6815) (6961) (6892) (6927) (6642) (6882) (6977) (6604) (7100) (7128) (6819) (7134) (7069) (6785) (7229) (6669) (6658) (7309) (7188) (6728) (6569) (6843) (6826) (6818) (6997) (6896) (7172) (7092) (6931) (7084) (6951) (6835) (6691) (7014) (6622) (6792) (6828) (6768) (6985) (6721) (6745) (7154) (6677) (7143) (6817) (6919) (6780) (6707) (6686) (6863) (7002) (6991) (6700) (6615) (6803) (6880) (6580) (6646) (6576) (6986) (6814) (6670) (7009) (7018) (6781) (6673) (6877) (6864) (6872) (7033) (7256) (7318) (6730) (7104) (6663) (7147) (6798) (6994) (6858) (6898) (6871) (7386) (6704) (7029) (6822) (6850) (6796) (7065) (6802) (6971) (6874) (7072) (7082) (6746) (7239) (6772) (6857) (6949) (7180) (6831) (7086) (6627) (6916) (7206) (6742) (7042) (6964) (6870) (7166) (7138) (7080) (7398) (6848) (6975) (7001) (6760) (6679) (6845) (6732) (6565) (6941) (6902) (6890) (6847) (6842) (6856) (7359) (6578) (7007) (7185) (7158) (7026) (6894) (6980) (6739) (7119) (6684) (6995) (6816) (6809) (6784) (6972) (6633) (6952) (6648) (6943) (6793) (6981) (7135) (7036) (6608) (6907) (7023) (6861) (7113) (7433) (7209) (7324) (6954) (7097) (6705) (6825) (6968) (6885) (6616) (6573) (6759) (6676) (6682) (6887) (6910) (7226) (6914) (6866) (7360) (6886) (7233) (7108) (6953) (5226) (7267) (7121) (7201) (7063) (6599) (7049) (7216) (6649) (7055) (6774) (6724) (7225) (6990) (6833) (6965) (6906) (6800) (7251) (6962) (6958) (7068) (7071) (6900) (7316) (7289) (6788) (6851) (6709) (6948) (6983) (6769) (6714) (7190) (6924) (6889) (6921) (6911) (7012) (7150) (5225) (7164) (7198) (6588) (6903) (6697) (6596) (6839) (7058) (6790) (7109) (6787) (7052) (6868) (7300) (6653) (7248) (6884) (7032) (6735) (7046) (6876) (6630) (6806) (6904) (6659) (7458) (6867) (7008) (6946) (7184) (6879) (6841) (6912) (6570) (7142) (7077) (6801) (6618) (6976) (73131))

B1784-002 The CL signal contact Passenger door supplies implausible values. - Fault during locking
B1786-001 The CL signal contact Tailgate supplies implausible values. - Fault during unlocking
B1786-002 The CL signal contact Tailgate supplies implausible values. - Fault during locking
B1787-001 The CL signal contact Left rear door supplies implausible values. - Fault during unlocking
B1787-002 The CL signal contact Left rear door supplies implausible values. - Fault during locking
B1788-001 The CL signal contact Right rear door supplies implausible values. - Fault during unlocking
B1788-002 The CL signal contact Right rear door supplies implausible values. - Fault during locking
B1858-002 Two-way radio signal : The programmed code is o.k., but the programmable code is not synchronized.
B1858-003 Two-way radio signal : The programmed code is valid, but not approved.
B1858-005 Two-way radio signal : Synchronization is not possible.

Filename: C:\Program
Files\Mercedes-Benz\DAS\bin\..\trees\Pkw\grundmod\am2k\menues\MNFC0001.S

Cell co-ordinate: 3 , 3