Vehicle: /scan/BENZ/

Test Path: Benz, Manual selection, Automatic selection, Control Units, Chassis, Chassis, EHPS-Electrohydraulic Power Steering, Seats and doors, ESA passenger-Electric seat adjustment passenger, Active test, Height at front, Forward/back adjustment, Backrest, Read codes

## Read codes

9000	Control unit N32/2 (Front seat adjustment control module with memory, front passenger) is defective.	Stored
------	--	--------

9010 The supply voltage of the control unit is too low (undervoltage). Stored

9060 No normalizing of forward/back adjustment. Stored

9200 Hall sensor of component M28/1 (Front passenger seat fore/aft adjustment motor) is faulty. Stored

9853 Fault in CAN communication with control unit REAR SAM. Stored

9854 Fault in CAN communication with control unit ICM. Stored

Vehicle: /scan/BENZ/

Test Path: Benz, Automatic selection, Auto Scan, Control Units, Drive, ME 9.7-Motor electronics 9.7, Read codes

## Read codes

O272 Continuous camshaft adjustment ( RIGHT ): Incorrect position of the intake camshaft (P0012) Stored Continuous camshaft adjustment ( LEFT ): Incorrect position of the exhaust camshaft (P0025) MIL ON&Stored

\_\_\_\_\_

Vehicle: /scan/BENZ/

Test Path: Benz, Automatic selection, Auto Scan, Control Units, Drive, ME 9.7-Motor electronics 9.7, Read codes

## Read codes

O272 Continuous camshaft adjustment ( RIGHT ): Incorrect position of the intake camshaft (P0012) Stored Continuous camshaft adjustment ( LEFT ): Incorrect position of the exhaust camshaft (P0025) MIL

2019-03-17 11:56:46 - 1 -

## **FoxScanner**

ON&Stored

2019-03-17 11:56:46 - 2 -