



P82.60-4772-09

Shown on model 164.1, with USA version, code 494

- | | | | |
|---|---------------------------------|---|--------------------------|
| 1 | Radio | 4 | Electrical connector |
| 2 | Instrument panel center section | 5 | Antenna cable connectors |
| 3 | Bolts | 6 | Latch |

☒ ☒	Remove/install		
⚠	Information on preventing damage to electronic components due to electrostatic discharge		AH54.00-P-0001-01A
1 AD	Read out coding of radio (1) Connect STAR DIAGNOSIS and read out fault memory	i Only when replacing radio and if it can still be read out using STAR DIAGNOSIS. STAR DIAGNOSIS diagnosis system	AD00.00-P-2000-04A
2	Switch off ignition and remove transmitter key from EIS control unit	i On vehicles with code (889) Keyless-Go: Press Keyless-Go start/stop button repeatedly until ignition is switched off. Remove transmitter key from vehicle and store it in a location beyond its transmission range (at least 2 m).	
3	Disengage dashboard center part (2) at bottom edge (arrows A) and pull forward out of dashboard use plastic pry tool	i Protect trim parts of the instrument panel and center console from scratches.	
4	Remove bolts (3) and slide latches (6) on both sides downwards (arrow B)		
5	Pull radio (1) out of installation opening and detach electrical connector (4) along with antenna cable connectors (5)	i Protect dashboard, center console trim parts and the radio from scratches.	
6	Install in the reverse order		
7 AD	Code radio (1) Connect STAR DIAGNOSIS and read out fault memory	i Only after installing a new radio. STAR DIAGNOSIS diagnosis system	AD00.00-P-2000-04A