



P82.60-4772-09

Shown on model 164.1, with USA version, code 494

- | | | | |
|---|---------------------------------|---|--------------------------|
| 1 | Radio | 4 | Electrical connector |
| 2 | Instrument panel center section | 5 | Antenna cable connectors |
| 3 | Bolts | 6 | Latch |

Remove/install		
	Information on preventing damage to electronic components due to electrostatic discharge	AH54.00-P-0001-01A
1	Read out coding of radio (1)	Only when replacing radio and if it can still be read out using STAR DIAGNOSIS.
AD	Connect STAR DIAGNOSIS and read out fault memory	STAR DIAGNOSIS diagnosis system AD00.00-P-2000-04A
2	Switch off ignition and remove transmitter key from EIS control unit	On vehicles with code (889) Keyless-Go: Press Keyless-Go start/stop button repeatedly until ignition is switched off. Remove transmitter key from vehicle and store it in a location beyond its transmission range (at least 2 m).
3	Disengage dashboard center part (2) at bottom edge (arrows A) and pull forward out of dashboard use plastic pry tool	Protect trim parts of the instrument panel and center console from scratches.
4	Remove bolts (3) and slide latches (6) on both sides downwards (arrow B)	
5	Pull radio (1) out of installation opening and detach electrical connector (4) along with antenna cable connectors (5)	Protect dashboard, center console trim parts and the radio from scratches.
6	Install in the reverse order	
7	Code radio (1)	Only after installing a new radio.
AD	Connect STAR DIAGNOSIS and read out fault memory	STAR DIAGNOSIS diagnosis system AD00.00-P-2000-04A